

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form O-103  
Revised 10-1-75

|                        |  |
|------------------------|--|
| NO. OF COPIES RECEIVED |  |
| DISTRIBUTION           |  |
| SANTA FE               |  |
| FILE                   |  |
| U.S.G.S.               |  |
| LAND OFFICE            |  |
| OPERATOR               |  |

|                                |                                         |
|--------------------------------|-----------------------------------------|
| 5a. Indicate Type of Lease     |                                         |
| State <input type="checkbox"/> | Fee <input checked="" type="checkbox"/> |
| 5. State Oil & Gas Lease No.   |                                         |

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM O-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name  
N. HOBBS (G/SA) UNIT

Name of Operator  
SHELL WESTERN E&P INC.

8. Form or Lease Name  
SECTION 18

Address of Operator  
P. O. BOX 576, HOUSTON, TEXAS 77001 (WCK 4435)

9. Well No.  
441

Location of Well  
UNIT LETTER P 330 FEET FROM THE SOUTH LINE AND 990 FEET FROM  
THE EAST LINE, SECTION 18 TOWNSHIP 18-S RANGE 38-E N.M.P.M.

10. Field and Pool, or Window  
HOBBS (G/SA)

11. Elevation (Show whether DF, RT, GR, etc.)  
3662' DF

12. County  
LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data.  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ OTHER PROPERLY TA ☒

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPER. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐ OTHER ☐

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

1. Clean out to 3866'.
2. Set a CIBP @ 3860' and cap w/35' cmt.
3. Pres tst csg to 500#, circ inhibited wtr and temporarily abandon.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Eddie Custer A. J. FORE TITLE SUPERVISOR REG. & PERMITTING DATE FEBRUARY 6, 1986

ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT 1 SUPERVISOR

APPROVED BY \_\_\_\_\_ DATE FEB 10 1986

RECEIVED  
FEB 10 1986  
O.C.D.  
MOBBS OFFICE