

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-07362
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name N. HOBBS (G/SA) UNIT SECTION 19
--

8. Well No. 231

9. Pool name or Wildcat HOBBS (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>

2. Name of Operator SHELL WESTERN E&P INC.

3. Address of Operator P. O. BOX 576, HOUSTON, TX 77001 (WCK 4435)

4. Well Location Unit Letter <u>K</u> : <u>2310</u> Feet From The <u>SOUTH</u> Line and <u>2310</u> Feet From The <u>WEST</u> Line Section <u>19</u> Township <u>18S</u> Range <u>38E</u> NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3663' DF
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>
OTHER: <input type="checkbox"/>
SUBSEQUENT REPORT OF:
REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <u>Cmt sqzd, OAP & Acid</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-21 to 3-29-90:

POH w/prod equip. CO to 4245' (PBTD). Set CIBP @ 4125' & pkr @ 4118'. PT CIBP to 700#, held. Rel pkr & reset @ 4021'. PT csg to 500#, held. POH w/pkr. Set CIBP @ 4021'. Sqzd perfs 4084' - 4120' w/100 sk CIs "C" cmt + .75% CF-14. Do cmt & CIBP 4017' - 4108'. PT csg to 500#, held. Drid CIBP @ 4125' & pushed to 4245' (PBTD). CO to 4245'. Perf'd SA 4062' - 76' (2 JSPF). Acid perfs 4062' - 76' w/1000 gals 15% NEFE HCl. Inst prod equip & ret'd to prod.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 4-30-90

TYPE OR PRINT NAME J. H. SMITHERMAN (713) 870-3797 TELEPHONE NO.

(This space for State Use)
ORIGINAL SIGNED BY JOEY SEXTON
SUPERVISOR

APPROVED BY _____ TITLE _____ DATE MAY 2 1990

CONDITIONS OF APPROVAL, IF ANY: