

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B
7. Unit Agreement Name SMGSAU
8. Farm or Lease Name Tract 4
9. Well No. 11
10. Field and Pool, or Wildcat MALJAMAR (G-SA)
12. County LEA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator CITIES SERVICE OIL & GAS CORPORATION
3. Address of Operator P. O. BOX 1919 - Midland, TX 79702
4. Location of Well UNIT LETTER <u>E</u> , <u>1345</u> FEET FROM THE <u>North</u> LINE AND <u>100</u> FEET FROM THE <u>West</u> LINE, SECTION <u>29</u> TOWNSHIP <u>17S</u> RANGE <u>33E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4077' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

OTD 4072'. This well was plugged and abandoned in the following manner:

- MIRU pulling unit. ND WH. NU BOP. PU tbg. out of pkr. Blanking plug set @ 3812'. CHC.
- Spotted a 30 sack cmt. plug from 3800-3500'.
- Spotted a 30 sack cmt. plug from 2912-2612'.
- Spotted a 50 sack cmt. plug from 1426-926'.
- Spotted a 20 sack cmt. plug from 221'-surface. POOH w/tbg. ND BOP & CO WH.
- Installed a dry hole marker to designate a plugged and abandoned location.

NMOCD notified but did not witness.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David Cotanach TITLE Region Petroleum Engineer DATE 5-23-83

APPROVED BY David Cotanach TITLE OIL & GAS INSPECTOR DATE JUL 15 1983

CONDITIONS OF APPROVAL, IF ANY: