

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31909
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Hooper
2. Name of Operator Rand Oil & Gas, Inc.	8. Well No. 1
3. Address of Operator 4006 Beltline Road, Suite 290, Addison, Texas 75244	9. Pool name or Wildcat Wildcat - Glorietta

4. Well Location
Unit Letter P : 531-54 Feet From The south Line and 498 Feet From The east Line
Section 1 Township 18-S Range 38-E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3650 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. OCD will be notified 24 hours prior to plugging.
 Work to commence about 30 October 1993. 8-5/8" pipe is cemented to surface.
 4½" pipe-top of cement is 4100'. 8-5/8" set at 2095'. Propose to cut off 4½" at approx. 4050' and pull casing.
 Procedure for plugging:
 Set cast iron bridge plug 6050' and run 25 sx and tag. Where we pull 4½" set stub plug/1/2 in and 1/2 out and run 25 sx and tag. At 2095' set stub plug. 1/2 in and 1/2 our and set 100' plug of cement. At 500' set 20 sx and 10 sx in marker at surface.

Well has the following perfs: 6336-6338: 3 holes/6236-6320: 24 holes/
 Cast iron bridge plug set at 6290'.
 6273-6277: 3 holes/ 6263-6266: 4 holes/ 6239-6247: 5 holes/ 6197-6203: 4 holes/
 6134-6138: 4 holes

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jan DeVault TITLE agent DATE 27 Oct 1993
 TYPE OR PRINT NAME Jan DeVault TELEPHONE NO. (915) 694-6059

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE NOV 02 1993

CONDITIONS OF APPROVAL, IF ANY: