

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 South First, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

WELL API NO. 30-025-32005
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1306
7. Lease Name or Unit Agreement Name: New Mexico "R" State NCT -3
8. Well No. 28
9. Pool name or Wildcat Vacuum Drinkard
10. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other Injector

2. Name of Operator
 Texaco Exploration & Production, Inc.

3. Address of Operator
 P. O. Box 3109, Midland, TX 79702


4. Well Location
 Unit Letter P : 1310 feet from the South line and 110 feet from the East line
 Section 1 Township 18S Range 34E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER: <input type="checkbox"/>
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- Set 5 1/2" CIBP @ 7500', spot 25 sx plug 7500'-7300' (Drinkard) WOC Tag.
- Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL.
- Spot 25 sx plug 3800'-3600' (Queen)
- Spot 25 sx plug 2800'-2600' (Yates, B-Salt) WOC Tag.
- Spot 50 sx plug 1600'-1200' (8 5/8" shoe, T-Salt) WOC Tag.
- 10 sx surface, Install dry hole marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James T. Corbitt TITLE FACILITY ENGINEER DATE 11/20/01
 Type or print name JAMES T. CORBITT Telephone No. 688-4438
 (This space for State use)

APPROVED BY Larry W. Wink TITLE NATURAL RESOURCES DATE NOV 2001
 Conditions of approval, if any

2

