

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-32804
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	B-1113-1
7. Lease Name or Unit Agreement Name	CENTRAL VACUUM UNIT
8. Well No.	199
9. Pool Name or Wildcat	VACUUM GRAYBURG SAN ANDRES
10. Elevation (Show whether DF, RKB, RT,GR, etc.)	3972' GR

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL GAS WELL OTHER INJECTION

2. Name of Operator: TEXACO EXPLORATION & PRODUCTION INC.

3. Address of Operator: 205 E. Bender, HOBBS, NM 88240

4. Well Location
Unit Letter E ; 1372 Feet From The NORTH Line and 584 Feet From The WEST Line
Section 6 Township 18-S Range 35-E NMPM LEA COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

12-20-97: MIRU. NDWH. NUBOP. REL PKR.
 12-22-97: TIH W/BIT, & DC'S ON WS. TAG @ 4372'. BREAK CIRC. C/O TO 4610'. CIRC CLN. PULL BIT TO 4228'.
 12-23-97: LOWER TOOLS TO 4610'. BREAK CIRC. C/O 172' FILL TO 4782'. CIRC CLN. TIH W/PKR & SET @ 4151.73'.
 12-24-97: PRESS CSG TO 500#-OK. A/SAN ANDRES PERFS FR 4238-4621' W/10,000 GALS 15% NEFE & 6000# RK SLT IN 4 STGS & 3 BLKS.
 12-29-97: SWAB & RECVD 0 BO, 195 BW, & 0 MCF. FL 300' FR SURF. REL PKR.
 12-30-97: TIH W/PUMP OUT PLUG W/DUO LINE ON/OFF TOOL ON TBG. KB @ 12'. SET PKR @ 4186.28'. REL ON/OFF TOOL & CIRC 100 BBLs PKR FLUID. RE-LATCH ON/OFF TOOL. NDBOP & NU CO2 TREE. PRESS ANNULUS 500# FOR 30 MIN. CIW TEST WELL HEAD TO 3000#-OK. SHEAR PUMP OUT PLUG @ 1000#.
 1-19-98: ON 24 HR OPT. INJ'G 945 BWPD @ 1151 PSI. CHANGE STATUS FR WO TO WIW.
 FINAL REPORT

I hereby certify that the information above is true and complete, to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 2/4/98

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
 APPROVED BY CHRIS WILLIAMS DISTRICT I SUPERVISOR TITLE DISTRICT I SUPERVISOR DATE FEB 12 1998

CONDITIONS OF APPROVAL, IF ANY:

DeSoto/Nichols 12-93 ver 1.0