

Submit 3 Copies To Appropriate District Office
 District I
 1625 N. French Dr., Hobbs, NM 87240
 District II
 811 South First, Artesia, NM 87210
 District III
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV
 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

Form C-103
 Revised March 25, 1999

OIL CONSERVATION DIVISION
 2040 South Pacheco
 Santa Fe, NM 87505

WELL API NO. 30-025-03218-03222
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-5839
7. Lease Name or Unit Agreement Name: East Pearl Queen Unit
8. Well No. 26
9. Pool name or Wildcat Pearl Queen

SUNDRY NOTICES AND REPORTS ON WELLS
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
 Oil Well Gas Well Other Injection

2. Name of Operator
 Xeric Oil & Gas Corporation

3. Address of Operator
 P. O. Box 352
 Midland, TX 79702

4. Well Location
 Unit Letter F : 1980 feet from the North line and 1980 feet from the West line
 Section 27 Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
 3731' DF

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: MIT <input checked="" type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

A MIT was performed on this well 2/20/02. The casing was pressured to 580 PSI over a 30 minute period. The test was deemed successful. The chart is attached. Request TA Status.


This Approval of Temporary Abandonment Expires 7/30/07

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 7/26/02
 Type or print name Angie Crawford Telephone No. 915-683-3171
 (This space for State use)

APPROVED BY _____ TITLE _____ DATE JUL 30 2002
 Conditions of approval, if any: _____
 ORIGINAL SIGNED BY _____ STAFF MANAGER

SJS



GRAPHIC CONTROLS CORPORATION
A DIVISION OF

VERIC EPQJ#26

2-20-02
BR 2221

[Handwritten signature]
2-20-02

[Handwritten note]
2-20-02

XERIC OIL & GAS CORP
EAST PEARL QUEEN UT # 26
F. 27. 19. 35

Start 580*

FIN 580*

Time 30 min

Log ~~o~~

Surf ~~o~~

th ~~o~~

Willis (TA)