

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
B-155

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texaco Producing Inc.	8. Farm or Lease Name N.M. "O" State (Nct-1)
3. Address of Operator P.O. Box 728, Hobbs, New Mexico 88240	9. Well No. 13
4. Location of Well UNIT LETTER <u>N</u> <u>519</u> FEET FROM THE <u>South</u> LINE AND <u>1839</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or WHdcat Vacuum Glorieta
15. Elevation (Show whether DF, RT, GR, etc.) 3997' GR	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPHB. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1503.

- MIRU. Pull rods, pump. Install BOP. Pull production tubing.
- Spot 40 gallons xylene and 40 gallons 20% NEFE HCl across perforations at 5907-6131'.
- Acidize with 6000 gallons 20% NEFE XL HCl and 450 pounds rock salt.
- Run production equipment.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED A. Gernandt 393-4031 TITLE Area Superintendent DATE 10/21/87

APPROVED BY JERRY SEXTON DISTRICT I SUPERVISOR TITLE _____ DATE OCT 26 1987

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED
MAY 21 1967
DOD
MAIL ROOM