




Following completion of flow test No. 1, the operator shall check the pressure in accordance with paragraph 3 above.

Flow Test No. 2 shall be conducted in accordance with the procedure for Flow Test No. 1, except that the operator shall check the pressure in accordance with the previously stated procedure.

The operator shall check the pressure throughout the entire test period and record the pressure on the recording pressure gauge. The pressure gauge shall be checked with a deadweight tester at the beginning and end of each flow test.

The results of the above-described tests shall be reported to the appropriate District Office of the Ventilation Division, Bureau of Mines, Southeast New Mexico, Packer, and the operator shall file the original pressure recording charts and the pressure readings which were taken on the recording pressure gauge for each zone of each test. The operator shall also file the original chart which was reflected by the pressure recording gauge. The pressure readings which were taken on the recording pressure gauge shall also be accompanied by a copy of the test report which coincides with a copy of the test report.



69, 11 0 1 11 807