

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-05662
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-2209-16

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name NORTH MONUMENT G/SA UNIT BLK. 6	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	8. Well No. 1		
2. Name of Operator Amerada Hess Corporation	9. Pool name or Wildcat EUNICE MONUMENT G/SA		
3. Address of Operator P.O. Box 840, Seminole, Texas 79360			
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>20</u> Township <u>19S</u> Range <u>37E</u> NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.)		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK PLUG AND ABANDON
 TEMPORARILY ABANDON CHANGE PLANS
 PULL OR ALTER CASING
 OTHER: CONVERT TO INJECTION WELL.

SUBSEQUENT REPORT OF:

REMEDIAL WORK ALTERING CASING
 COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
 CASING TEST AND CEMENT JOB
 OTHER: _____

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NMGSAU #601
Plan to:

Order No. R-9596

MIRU PU & RU. TOH W/PROD. EQUIPMENT & TBG. SET RBP @ +\-3.675'. CIRC. HOLE W/WATER & TST. CSG. TO 700 PSI. CHG'D. OUT WELLHEAD. REMOVE RBP. CLEAN OUT TO 3.980'. CIRC. HOLE CLEAN. RUN GRN/CCL FR. 3.980' TO 3.190'. TIH W/SONIC HAMMER TO TD. WASH TO 3,740'. ACIDIZE O.H. FR. 3,740'-3.980' W/12,000 GALS. HCL USING SONIC HAMMER. SWAB BACK LOAD. EVALUATE FOR SAN ANDRES COMMUNICATION BY SWAB TST. IF COMMUNICATION EXISTS, PLUG BACK WELL W/CMT. TIH W/INJ. EQUIPMENT. SET PKR. @ +\-3.675'. RDMO. SI. OBTAIN 72 HR. SBHP DIP-IN.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terry L. Harvey TITLE SR. STAFF ASSISTANT DATE 06-04-97
TYPE OR PRINT NAME TERRY L. HARVEY TELEPHONE NO. 505-393-2144

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: