

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION  
**MAY 20 9 14 AM '68**

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease  
 State  Fee   
 5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - 1" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- 2. Name of Operator <b>Sunray DX Oil Company</b> 3. Address of Operator <b>P. O. Box 1416 - Roswell, New Mexico 88201</b> 4. Location of Well UNIT LETTER <b>D</b> , <b>330</b> FEET FROM THE <b>North</b> LINE AND <b>960</b> FEET FROM THE <b>West</b> LINE, SECTION <b>7</b> TOWNSHIP <b>20-S</b> RANGE <b>37-E</b> NMPM.	7. Unit Agreement Name 8. Farm or Lease Name <b>A. Cooper</b> 9. Well No. <b>10</b> 10. Field and Pool, or Wildcat <b>Monument Blinebry</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3566 DF</b>	12. County <b>Lea</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <b>Acidize</b> <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MI and RU workover unit.
2. Pull rods and tubing.
3. Run tubing and packer.
4. Acidize with 9000 gal. 15% acid using 1350# rock salt as diverting agent.
5. Swab well and clean up.
6. Pull tubing and packer.
7. Run tubing and rods and place on production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Hastings TITLE District Engineer DATE May 17, 1968

APPROVED BY [Signature] TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: