

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-06015
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. 014896
7. Lease Name or Unit Agreement Name Bertie Whitmire
8. Well No. 5
9. Pool name or Wildcat Langlie Mattix/Monument Blinebry
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3563' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL GAS
WELL WELL OTHER

2. Name of Operator
Arch Petroleum, Inc.

3. Address of Operator
10 Desta Drive, Suite 420 E, Midland, TX 79705

4. Well Location
Unit Letter **F** : **1650** Feet From The **North** Line and **1650** Feet From The **West** Line
Section **8** Township **20S** Range **37E** NMPM **Lea** County

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JO <input type="checkbox"/>
OTHER: _____ <input type="checkbox"/>	OTHER: _____ <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Description of Work:

- 1) Set CIBP @ 5600'. Spot 25 sx cement on top of CIBP.
- 2) Spot 50 sx cement plug @ 3007'. Top of cement @ 2791'.
- 3) Spot 35 sx cement plug @ 2500'. TOC @ 2339'.
- 4) Spot 35 sx plug @ 1400'.
- 5) Spot 35 sx plug @ 350'.
- 6) Cut off wellhead, 7", 9-5/8", and 13-3/8" csg.
- 7) Cemented to surface. Erected Dry Hole Marker. *9/17/97*

Plugged and Abandoned wellbore

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Robin S. McCarley* TITLE Technical Assistant DATE: 9/18/97

TYPE OR PRINT NAME Robin S. McCarley TELEPHONE NO. 915-685-1961

APPROVED BY *John W. Hill* TITLE Oil & Gas Inspector DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____

JCT

11c
CP