

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Box Drawer DD, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 06050
5. Indicate Type of Lease STATE [] FEE [x]
6. State Oil / Gas Lease No. 859210
7. Lease Name or Unit Agreement Name VAN ETTEN, L.
8. Well No. 10
9. Pool Name or Wildcat EUMONT YATES 7R QUEEN

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.
1. Type of Well: OIL WELL [] GAS WELL [x] OTHER []
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator 205 E. Bender, HOBBS, NM 88240
4. Well Location
Unit Letter O : 990 Feet From The SOUTH Line and 1650 Feet From The EAST Line
Section 9 Township 20S Range 37E NMPM LEA COUNTY
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3553'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING []
OTHER: []
SUBSEQUENT REPORT OF:
REMEDIAL WORK [x] ALTERING CASING []
COMMENCE DRILLING OPERATION [] PLUG AND ABANDONMENT []
CASING TEST AND CEMENT JOB []
OTHER: DRILL OUT PLUG & ACIDIZE [x]

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
11-16-99: MIRU KEY. MIRU REV UNIT. L NDWH. NUBOP. TIH W/BIT, DC'S. STOP BIT @ 1428'.
11-17-99: LOWER TBG & TOOLS & TAG @ 3520'. BREAK CIRC. DRILL 32' CMT TO 3552'. DRILL ON CIBP. LOST CIRC. ATTEMPT TO GET CIRC W/230 BBLS 2% KCL WTR. NO LUCK. PULL BIT TO 3326'. MIRU FOAM UNIT.
11-18-99: BREAK CIRC W/FOAM UNIT. DRILL ON CIBP @ 3352'. PLUG TURNED LOOSE. PUSH TO 3408-TAGGE. DRILL CAST IRON & CMT TO 3444'.
11-19-99: TIH W/BIT, DC'S & TBG. TAG @ 3444'. START DRLG CMT 121'-3565'.
11-22-99: OPEN WELL. 50 PSI. LOWER TBG. TAG @ 3560'. TIH W/UNDER REAMER, DC'S & TBG. START UNDER REAMING 3410-3452.
11-23-99: UNDER REAM 3452-3562'. PULL REAMER TO 3362'.
11-24-99: TIH W/BIT ON TBG. TAG @ 3557'. C/O 8' FORM SAND TO 3565'. RD FOAM UNIT & REV UNIT.
11-29-99: RUN GR/CCL FR 3400-3150'. TIH W/CHARGES. PERF 3258-64, 3270-74, 3278-84, 3290-3305, 3348-54, 3362-70, 3410-65, 3470-3550.
11-30-99: TIH W/SONIC HAMMER, SN, TBG. WASH O.H. 3550-3258 W/WTR. ACIDIZE W/SONIC HAMMER SAME ZONE 3550-3258 W/8500 GALS 15% NEFE HCL. PSA 3200'. TBG @ 3515'. ACIDIZE SAME ZONE W/1500 GALS 15% NEFE HCL. RU SWAB. FL @ 3490'. SWAB DRY.
12-01-99: REL PKR. TIH W/SN, TBG, TAC. NDBOP. NUWH. SN @ 3533' & TAC @ 3185'. RU SWAB. TAG FL @ 3400'.
12-02-99: TIH W/PMP, SNKR BARS, RDS. RIG DOWN.
1-17-00: ON 24 HR OPT. PUMPED 0 BO, 6 BW, & 55 MCF. PERFS 3258-3550 EUMONT 7R QUEEN.
FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 1/27/00
TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)
APPROVED
CONDITIONS OF APPROVAL IF ANY: TITLE DATE
DeSoto/Nichols 12-93 ver 1.0