

OIL CONSERVATION DIVISION

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

DISTRICT II P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-33015
5. Indicate Type of Lease STATE [X] FEE []
6. State Oil / Gas Lease No. 584150

SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name E. H. B. PHILLIPS "B"

1. Type of Well: OIL WELL [X] GAS WELL [] OTHER []

8. Well No. 3

2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.

9. Pool Name or Wildcat MONUMENT TUBB

3. Address of Operator 205 E. Bender, HOBBS, NM 88240

4. Well Location Unit Letter C ; 660 Feet From The NORTH Line and 1980 Feet From The WEST Line Section 10 Township 20-S Range 37-E NMPM LEA COUNTY

10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3554' GR, 3567.8 KB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK [] PLUG AND ABANDON []
TEMPORARILY ABANDON [] CHANGE PLANS []
PULL OR ALTER CASING []
OTHER: []

REMEDIAL WORK [] ALTERING CASING []
COMMENCE DRILLING OPERATION [] PLUG AND ABANDONMENT []
CASING TEST AND CEMENT JOB []
OTHER: TA SKAGGS DRINKARD [X]

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-24-96; MIRU PRIDE. POH W/ RODS & PUMP. INSTALL BOP & POH W/ TBG. SDFN
9-25-96; TIH W/ BIT. TAG 6720'. BREAK CIRC. CLEAN OUT SAND TO 6820'. CIRC.' SDFN
9-26-96; TAG 6820'. BREAK CIRC. DRILL 15' CEMENT TO 6835. DRILL CIBP & PUSH TO 7050'.CIRC. CLEAN POH W/ TBG. LAYDOWN D.C.S AND BIT
9-27-96; TIH W/ CIBP & SET 6856' & DUMP 6' CEMENT ON TOP OF PLUG.PBTD=6850'.TOH TIH W/ 4" CSG GUN W/ 120 DEGREE PHASING & PERF SKAGGS DRINKARD W/ 2 JSPF; 6708-6840. 132'GROSS,46' NET,92-.52" HOLES. TOH . TIH W/PKR.
9-28-96; SET PKR @ 6660'. ACIDIZE DRINKARD PERFS. 6708'-6840' W/ 5000 GAL'S 15 % NE FE HCL & 138 7/8 BALLS. MAX PRESS=4350#,MIN PRESS=3700#, AIR=5BPM,ISDP=3200#,5MSIP=2970#,10MSIP=2880#,15MSIP=2840#. FLOW BACK & DIED. RIG UP SWAB. SWABBED 3 HRS RECOVERED 42 BBLS LOAD. PARTED SAND LINE.UNSET PKR & POH W/ TBG & PKR.
9-29-96; TIH W/FISHING TOOLS. TAG SANDLINE & FELL BACK DOWNHOLE. SCREW INTO FISH & TOH RECOVERED SANDLINE SDFN.
9-30-96; TIH W/ PKR. SET @6660'.RIG UP SWAB. SWABBED 4 HRS RECOVERED 63 BBLS LOAD. SDFN
10-1-96 THRU 10-2-96; SWABBING WELL. UNSET PKR & POH W/ TBG. DRINKARD UNECONOMICAL. SDFN
10-3-96; TIH W/CIBP & SET ON TOP OF DRNKARD PERFS. @ 6660' (TA DRINKARD). DUMP 35 ' CEMENT ON TOP OF CIBP. PBTD 6625'. TIH W/ 4" CSG GUN W/ 120 DEGREE PHAZING & PERF MONUMENT TUBB W/2 JSPF 6546'-6597'.(51' NET,20' GROSS,40-.52" HOLES. TIH W/ PKR & SET @ 6521' . LOAD BACKSIDE OK. TUBB PERFS ON BACKSIDE 6420-60,6476-80.
10-04-96; ACIDIZE MONUMENT TUBB PERFS 6546'-6597' , W/2500 GAL'S 15% NEFE + 60-7/8" BALL SEALERS, MAX TP= 4100#, AVG TP= 3300#, FINAL TP= 2530#, AVG INJ RATE= 5-BPM, ISIP= 3310#, 5-MIN= 2780#, 10-MIN= 2590#, 15-MIN= 2530#. RIG UP & SWAB.
10-05-96 THRU 10-7-96; SWAB WELL.
10-8-96; SWAB WELL. UNSET PKR & POH.W/ TBG. & PKR. TIH W/ TBG OPENENDED SDFN.
10-9-96; RAN TBG & SN. ND BOP & NU WELLHEAD. LAYDOWN RODS. RDMO
10-10-96 THRU 12-8-96; SHUT-IN, EVALUATING WELL.
12-9-96; OPT, O-BO, O-BW, O-MCF. SHUT-IN

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE [Signature] TITLE Engineering Assistant DATE 12/13/96
TYPE OR PRINT NAME Paula S. Ives Telephone No. 397-0432

(This space for State Use) APPROVED BY [Signature] TITLE DATE JAN 29 1997
CONDITIONS OF APPROVAL, IF ANY: