

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-33879

5. Indicate Type of Lease:
STATE FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

M & M

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.

2

2. Name of Operator
Collins & Ware, Inc.

9. Pool name or Wildcat
Warren; Tubb, East (87085)

3. Address of Operator
508 West Wall, Suite 1200, Midland, Texas 79701

4. Well Location
Unit Letter F : 1980 Feet From The North Line and 1980 Feet From The West Line

Section 24 Township 20S Range 38E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3567' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- OTHER:
- PLUG AND ABANDON
- CHANGE PLANS

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- OTHER: Completion
- ALTERING CASING
- PLUG AND ABANDONMENT

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Please see attachment.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Supervisor DATE July 10, 1997

TYPE OR PRINT NAME Dianne Sumrall

TELEPHONE NO. (915) 687-3435

(This space for State Use)

OIL & GAS INSPECTOR

APPROVED BY Charles Ferris TITLE _____ DATE 8-4-97

CONDITIONS OF APPROVAL, IF ANY:

ATTACHMENT TO FORM C-103
COLLINS & WARE, INC.
M & M #2

- 6/19/97 Tag PBSD at 6948'. Run GR/CCL from 6945' - 2500'. RIH with guns and perforate 6932' - 36', 6865' - 85', 6740' - 60' with 1 SPF (total 45 perfs). TIH and set RBP at 6660' and packer at 6650'. Test RBP to 1000 psi.
- 6/20/97 Treated perfs 6932' - 6936' with 375 gals 15% NEFE acid. Had fair ball action. Communicated with annulus. Treated perfs 6865' - 6885' with 1000 gals 15% NEFE acid. Had good ball action - did not ball out. Treated perfs 6740' - 6760' with 1000 gals 15% NEFE acid. Had good ball action - did not ball out.
- 6/21/97 Frac well with 32,000 gals Delta Frac 25 carrying 900 sx 20/40 Ottawa sand. RIH and set RBP at 6600'. Conventionally perforate from 6565' - 6585' with 1 SPF. Acidize perfs 6565 - 6585 with 15 gals acid.
- 6/22/97 Acidize perfs 6565 - 6585 with 3000 gals 15% NEFE acid.
- 6/23/97 Acidize perfs 6565 - 6585 with 1000 gals 15% heated NEFE acid. Frac well with 32,000 gals Delta Frac 25 carrying 900 sx 20/40 Ottawa sand.