

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-04510
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name EUNICE MONUMENT SOUTH UNIT
8. Well No. 199
9. Pool name or Wildcat EUNICE MONUMENT; GRAYBURG-SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER INJECTOR
2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 1150, Midland, TX 79702
4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>5</u> Township <u>21S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3564'

11. **Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>ACZD. SQZD</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH W/INJ EQPT. CLEANED OUT TO 3850'; CIRC HOLE CLEAN. ACZD W/1600 GALS RS II. PPD 2200# SAND DOWN TBG; TAGGED @ 3725'. WASHED PERFS 3615'-3676' W/PERF CLEAN. ACZD 3700'-3708' W/500 GALS 15% HCL. TAGGED SAND @ 3670'; WASHED TO 3720'. SPOTTED 100# SAND. SET CR @ 3494'; SQZD W/200 SX "C" @ 2000#; 150 SX TO FORM. DRILLED CR & CMT 3392'-3718'; TSTD SQZ 500#. CLEANED OUT TO 3850'. CIRC HOLE CLEAN. RIH W/INJ TBG TO 3569'. RETURNED WELL TO INJECTION.

WORK PERFORMED 11/17/97 - 12/2/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECH ASSISTANT DATE 5/19/98

TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Sylvia do you
have chart?

NO

Chart was
sent directly
to OGD after
work was
done

10/10/10
10/10/10
10/10/10
10/10/10