

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240
DISTRICT II
P.O. Drawer Dd, Artesia, NM 88210
DISTRICT III
1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-04937
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name HARRY LEONARD (NCT-C)
8. Well No. 10
9. Pool name or Wildcat BLINEBRY
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3514 GE

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator CHEVRON U.S.A. INC.
3. Address of Operator P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE
4. Well Location Unit Letter <u>NQ</u> Section <u>36</u> Feet From The <u>760</u> SOUTH Line and <u>2080</u> Feet From The <u>WEST</u> Line Township <u>21S</u> Range <u>36E</u> NMPM <u>LEA</u> County
10. Elevation(Show whether DF, RKB, RT, GR, etc.) 3514 GE

11 Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABAN. <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CMT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: _____ <input type="checkbox"/>	

12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 10-9-92 THRU 10-15-92
SPOT 75 SX CMT ON TOP OF CICR AT 5480'. (5480-4760') AS PER OCD REP RAY SMITH
TAG CMT @ 4822', PERF 4 SHOTS @ 3956', LOAD 5-1/2 CSG, SET CICR @ 3300'
PMP 350 SX CMT BELOW & 35' CMT ON TOP OF CICR. CIRC OUT ANNULUS. PMP
25 SX PLUG 2820-2580', SHOT 4 HOLES @ 1300', SET CICR @ 1050', PMP 150 SX CMT BELOW &
LEFT 35' ON TOP. PMP 240 SX CMT, CIRC OUT 9-5/8 X 13-3/8 ANN & CIRC CMT OUT
5-1/2 X 9-5/8 ANN. LEFT 5-1/2" CSG FULL OF CMT. CUT OFF WELLHEAD & ANCHORS
INSTALL P&A MARKER. WELL P&A 10-15-92.

CHANGE STATUS TO P & A.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 10/27/92

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY Charles... TITLE OIL & GAS INSPECTOR DATE JUL 19 1996

CONDITIONS OF APPROVAL, IF ANY: