

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease  
STATE  FEE

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name  
NORTHEAST DRINKARD UNIT

1. Type of Well:  
OIL WELL  GAS WELL  OTHER

8. Well No.  
907

2. Name of Operator  
Shell Western E&P Inc.

9. Pool name or Wildcat  
N. EUNICE BLINEBRY-TUBB-DRNKRD

3. Address of Operator  
P.O. Box 576 Houston, TX 77001-0576

4. Well Location  
Unit Letter J : 1980 Feet From The SOUTH Line and 1980 Feet From The EAST Line

Section 22 Township 21S Range 37E N.M.P.M. LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
3409' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: <u>LOGGED, RECOMP AS B/T/D POW</u> <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-08 TO 5-31-91:

TOH W/DUAL TBG STRINGS. TAG SCALE @ 6258'. CO SCALE TO MDL D PKR @ 6350'. WSHD FILL FROM 6350-57'. MLD ON PKR 6357-63'. FREED PKR, POH. TH W/WOS. TAG FILL @ 6526'. WSHD OUT FILL TO 6547'. MLD ON JUNK FROM 6547' TO 6598'. PLUGGED UP SHOE @ 6598'. POH W/WOS & RETRIEVED 30' FILL. TAG @ 6593'. WSHD OUT TO 6620'. RAN CBL, CET, SDT, GST, NGT, CNL & CCL LOGS. PERF'D BLINEBRY/TUBB/DRINKARD 5514' - 6498' (2 JSPF). ACD DRINKARD OH 6520' - 6620' W/3150 GALS 15% NEFE HCL + 1750# ROCK SALT. ACD BLINEBRY-TUBB-DRINKARD PERFS 5509' - 6498' W/13,272 GALS 15% NEFE HCL + 2250# ROCK SALT USING VAR RBP/PKR SETTINGS. POH W/RBP & PKR. INST PROD EQUIP & RETD TO PROD.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. H. Smitherman TITLE REGULATORY SUPV. DATE 7/02/91

TYPE OR PRINT NAME J. H. SMITHERMAN TELEPHONE NO. 713/870-3797

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

JUL 09 1991