

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer Dd, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, Nm 87410

API NO. (assigned by OCD on New Wells) 30-025-23543	
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>	
6. State Oil & Gas Lease No. N/A	
7. Lease Name or Unit Agreement Name MOORE	
8. Well No. 1	
9. Pool name or Wildcat BLINEBRY	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
CHEVRON U.S.A. INC.

3. Address of Operator
P.O. BOX 1150 MIDLAND, TX 79702 ATTN: NITA RICE

4. Well Location
Unit Letter **I** Section **25** Township **1980** Feet From The **SOUTH** Line and Range **36E** NMPM **410** Feet From The **EAST** Line County **LEA**

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CMT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTER CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABAN. <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WORK PERFORMED 10-15-92 THRU 10-21-92
SET CIBP AT 5470 AND CAP WITH 35' (5 SX) OF CEMENT. SPOT 25 SX PLUG F/5260-5010 .
ABOVE PLUG COVERS GLORIETA AND PADDOCK FORMATION.
SET 85 SX. CMT PLUG F/4040-3210, PLUG COVERS GRAYBURG AND SAN ANDRES.
PERF SQZ. HOLES AT 2970 SET CIGR AT 2600 & SQZ. W/90 SXS. CMT. LEAVE 35' CMT ON TOP.
(2970-2600') ABOVE PLUG COVERS YATES AND 8 5/8" SHOE.
PERF 4 HOLES @ 1350', SET CIGR @ 1165', SQZ WITH 80 SXS. CMT. (1350-1165') LEAVE 35' CMT
ON TOP. SHOOT 4 HOLES @ 355, PMP 216 SX F/355' TO SURFACE. CIRC OUT ANNULUS.
CUT OFF WELLHEAD AND INSTALL P & A MARKER. (OCD REP CHARLES PERRIN ON LOCATION)
P & A MUD WAS CIRCULATED BETWEEN ALL PLUGS.
CHANGE STATUS TO P&A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nita Rice TITLE TECHNICAL ASSISTANT DATE: 10/27/92

TYPE OR PRINT NAME NITA RICE TELEPHONE NO. (915)687-7436

APPROVED BY Charles Perrin TITLE OIL & GAS INSPECTOR DATE OCT 06 1993
CONDITIONS OF APPROVAL, IF ANY: