

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

OIL CONSERVATION DIVISION

P.O. Box 2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

Santa Fe, New Mexico 87504-2088

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-29093

5. Indicate Type of Lease
STATE FEE

6. State Oil & Gas Lease No.
B-1732

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
ARROWHEAD GRAYBURG UNIT

1. Type of Well:
OIL WELL GAS WELL OTHER

8. Well No.
120

2. Name of Operator
Chevron U.S.A. Inc.

3. Address of Operator
P.O. Box 1150, Midland, TX 79702

9. Pool name or Wildcat
ARROWHEAD; GRAYBURG

4. Well Location
Unit Letter D : 660 Feet From The NORTH Line and 990 Feet From The WEST Line
Section 36 Township 21S Range 36E NMPM LEA County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3519'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

| | |
|--|--|
| NOTICE OF INTENTION TO: | SUBSEQUENT REPORT OF: |
| PERFORM REMEDIAL WORK <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> |
| PLUG AND ABANDON <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> |
| CHANGE PLANS <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> |
| OTHER: <input type="checkbox"/> | OTHER: <u>SQZD PERFS, ACZD</u> <input checked="" type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

POH W/PROD EQPT. SPOTTED 4000# SAND; TAGGED @ 3742'. WASHED SAND TO 3770'. SET CICR @ 3578', PPD 150 SX CL "C". DRILLED OUT CICR & CMT TO 3763'. PPD 75 SX CL "C" @ 3361'. DRILLED CMT TO 3765'. DRILLED CMT AND CLEANED OUT SAND TO PBTD @ 4091'. RIH W/TBG, PMP & RODS; TBG @ 3633'. RETURNED WELL TO PRODUCTION.

WORK PERFORMED 3/31/97 - 4/9/97

Handwritten initials/signature

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 10/20/97

TYPE OR PRINT NAME J. K. RIPLEY TELEPHONE NO. (915)687-7148

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DATE NOV 18 1997

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

Handwritten mark