

| | |
|------------------------|--|
| NO. OF COPIES RECEIVED | |
| DISTRIBUTION | |
| SANTA FE | |
| FILE | |
| U.S.G.S. | |
| LAND OFFICE | |
| OPERATOR | |

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
A 2614

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL GAS WELL OTHER
2. Name of Operator
Marathon Oil Company
3. Address of Operator
P. O. Box 2409, Hobbs, New Mexico 88240
4. Location of Well
UNIT LETTER H 1980 FEET FROM THE North LINE AND 990 FEET FROM
THE East LINE, SECTION 35 TOWNSHIP 22S RANGE 36E NMPM.
10. Field and Pool, or Well Unit
South Eunice (Seven Rivers, Queen)
9. Well No.
1406
15. Elevation (Show whether DF, RT, GR, etc.)
GL 3474; KDB 3484'
12. County
Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| | | | |
|---|---|---|---|
| NOTICE OF INTENTION TO: | | SUBSEQUENT REPORT OF: | |
| PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> | PLUG AND ABANDON <input type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/> | ALTERING CASING <input type="checkbox"/> |
| TEMPORARILY ABANDON <input type="checkbox"/> | CHANGE PLANS <input type="checkbox"/> | COMMENCE DRILLING OPNS. <input type="checkbox"/> | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | OTHER <input type="checkbox"/> | CASING TEST AND CEMENT JOB <input type="checkbox"/> | |
| | | OTHER _____ | <input type="checkbox"/> |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Install BOP.
2. Pull downhole equipment.
3. Clean out hole to PBD 3789'.
4. Perforate and stimulate additional interval in Queen section.
5. Rerun 2-3/8" tubing and seating nipple.
6. Rerun rods and production pump.
7. Nipple up wellhead.
8. Test and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. J. Smith TITLE Petroleum Engineer DATE December 16, 1975

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: