

# The Western Co.

## LOG OF PERFORATING SERVICE

District Both Station Holts Date 10-13-52  
 Truck No. 1107 Operator R. B. Roush  
 Customer Kelly P. Co. Order By J. R. Green  
 Helpers W. H. Hensen

### PERFORATING INSTRUCTIONS

Name of Well J. P. Co. #2 Field W. H. Hensen  
 County W. H. Hensen State W. H. Hensen  
 Type Perforation 2. 1/4" Holes from 100 to 100 ft. Holes from 10 to 10 ft.  
 Baker Equipment Holes from 100 to 100 ft. Holes from 10 to 10 ft.  
 Holes from 100 to 100 ft. Holes from 10 to 10 ft.  
 Job Scheduled for 1:00 Holes Per Foot 4

On Job 10-13-52 P. M. 11:52 Off Job \_\_\_\_\_ P. M. \_\_\_\_\_  
 New or Old Well 11 Purpose of Perforating like stage Kind of Fluid water Fluid Level 100'  
 Casing Record 11 Cemented in \_\_\_\_\_ Limer Record 11 Cemented in \_\_\_\_\_  
 Gun Sets Depth 100' Measure Method Tape Zero Point 100'  
 Wireline Depth 100' The Gun and/or Baker Equipment 11  
 M. H. Hensen used 11  
 X. H. Hensen used By 11

**ILLECIBLE**

1) Cut In <u>9:16</u> A. M.	Counter Set At <u>1000'</u>	Wh. Ind. <u>100'</u>
P. M.	Flag <u>1000'</u>	Gun Nos. <u>101 # 61</u>
2) Cut At <u>9:22</u> A. M.		
P. M.		
Depth Perfor. <u>3</u>	Section Perforated This Run <u>100'</u>	To <u>100'</u>
Holes <u>3</u>		
Perfor. <u>3</u>		
3) Cut In _____ A. M.	Counter Set At _____	Wh. Ind. _____
P. M.	Flag _____	Gun Nos. _____
4) Cut At _____ A. M.		
P. M.		
Depth Perfor. _____	Section Perforated This Run _____	To _____
Holes _____		
Perfor. _____		