

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on re-
verse side)

Form approved,
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC-032104

6. INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
TEXACO Inc.

3. ADDRESS OF OPERATOR
P. O. Box 728, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface 2306' FNL, 660' FWL, Sec. 31, T-22-S, R-38-E, Unit Letter 'E', Lea County, New Mexico

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
NCT-3
A.H. Blinebry Fed. NCT

9. WELL NO.
3

10. FIELD AND POOL, OR WILDCAT
Blinebry, Drinkard, Brunson, Ellenburger

11. SEC., T., E., M., OR BEER, AND SURVEY OR AREA
South
Sec. 31

12. COUNTY OR PARISH
Lea

13. STATE
New Mexico

14. PERMIT NO.
Regular

15. ELEVATIONS (Show whether DF, RT, CR, etc.)
3317' (DF)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <u>Downhole Commingle</u> <input checked="" type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

NMOCC Case No. 5628, ORDER No. R-5170

- Rig Up. Pulled rods & pump from Drinkard string. Install BOP. Shut-In Blinebry.
- Fishing job unsuccessful in Blinebry string.
- Perforate 2 7/8" Drinkard Zone w/ 1-JSPF from 6700'-6710'.
- Spot acid over perforations 6700'-6710'. Set packer @ 6210'. Acidize w/500 gal. 15% NE Acid & flushed w/12 bbls. fresh water.
- Install pumping equipment. On 24 hr. Potential Test ending 8-7-76. Well pumped 10 Bbl. oil & 2 BW, GOR 14,700.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Asst. Dist. Supt. DATE 8-11-76

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY: _____

AUG 13 1976
J. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side