

N. M. OIL CONS. COMMISSION
P. O. BOX 1930
HOBBS, NEW MEXICO 88240

Form 9-331
(May 1983)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1124.

5. LEASE DESIGNATION AND SERIAL NO.

LC030187

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

C. E. LaMunyon

9. WELL NO.

22

10. FIELD AND POOL, OR WILDCAT

Langlie Mattix

11. SEC. T. R. M. OR R.L. AND SURVEY OR AREA

Sec 21-T23S-R37E

12. COUNTY OR PARISH 13. STATE

Lea

NM

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Gulf Oil Corporation

3. ADDRESS OF OPERATOR
P. O. Box 670, Hobbs, NM 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)
At surface
660' FSL & 1980' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3308' RKB

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Close Off Lower Perfs, Recond Upper Perfs

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

POH with production equipment. GIH with open-ended tubing, tag CIBP at 3800'. Spot 16 sacks Class "C" neat. WOC. GIH with open-ended tubing, tag cement. If below 3700', spot additional cement. WOC. GIH with open-ended tubing, tag cement. Repeat cementing if necessary. Swab test perfs 3648-52' & 3676-80'. Stimulate as required.

RECEIVED

MAR 1 1983

OIL & GAS
MINERALS INST. SERVICE
ROSWELL, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

R.D. Pitt
APPROVED

TITLE Area Engineer

DATE 2-28-83

(This space for Federal or State office use)

(Orig. Sgd.) *ELMER W. CHESTER*

TITLE

DATE

APPROVED BY
CONDITIONS OF APPROVAL IF

MAR 2 1983
FOR
JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See Instructions on Reverse Side