



Certificate of Analysis

Number: 6030-20110087-001A

Artesia Laboratory

200 E Main St.
Artesia, NM 88210
Phone 575-746-3481Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

Nov. 17, 2020

Field: NMSW
 Station Name: Corral Compressor Station 2 South
 Station Number: N/A
 Sample Point: N/A
 Meter Number:
 County: Eddy
 Type of Sample: Spot-Cylinder
 Heat Trace Used: N/A
 Sampling Method: Fill and Purge
 Sampling Company: OXY

Sampled By: Jesus Escobedo
 Sample Of: Gas Spot
 Sample Date: 11/11/2020 01:09
 Sample Conditions: 1265 psig Ambient: 49 °F
 Effective Date: 11/11/2020 01:09
 Method: GPA 2286
 Cylinder No: 1111-001162
 Instrument: 6030_GC2 (Agilent GC-7890B)
 Last Inst. Cal.: 08/25/2020 8:12 AM
 Analyzed: 11/17/2020 12:40:16 by PGS

Analytical Data

Components	Un-normalized Mol %	Mol. %	Wt. %	GPM at 14.65 psia		
Hydrogen Sulfide	0.000	0.000	0.000		GPM TOTAL C2+	6.390
Nitrogen	1.332	1.320	1.675		GPM TOTAL C3+	3.359
Methane	76.899	76.201	55.381		GPM TOTAL iC5+	0.805
Carbon Dioxide	0.171	0.169	0.337			
Ethane	11.459	11.355	15.468	3.031		
Propane	5.781	5.728	11.443	1.575		
Iso-butane	0.846	0.838	2.207	0.274		
n-Butane	2.259	2.238	5.893	0.705		
Iso-pentane	0.642	0.636	2.079	0.232		
n-Pentane	0.766	0.759	2.481	0.275		
Hexanes Plus	0.763	0.756	3.036	0.298		
	100.918	100.000	100.000	6.390		

Calculated Physical Properties

Relative Density Real Gas	Total	C6+
	0.7649	3.0584
Calculated Molecular Weight	22.07	88.58
Compressibility Factor	0.9960	

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.65 psia & 60°F

Real Gas Dry BTU	1308	4763
Water Sat. Gas Base BTU	1285	4680
Ideal, Gross HV - Dry at 14.65 psia	1302.9	4763.5
Ideal, Gross HV - Wet	1280.1	0.000
Net BTU Dry Gas - real gas	1188	
Net BTU Wet Gas - real gas	1167	

Comments: H2S Field Content 0 ppm

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.



Certificate of Analysis

Number: 6030-20110087-001A

Artesia Laboratory

200 E Main St.

Artesia, NM 88210

Phone 575-746-3481

Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

Nov. 17, 2020

Field: NMSW
Station Name: Corral Compressor Station 2 South
Station Number: N/A
Sample Point: N/A
Meter Number:
County: Eddy
Type of Sample: Spot-Cylinder
Heat Trace Used: N/A
Sampling Method: Fill and Purge

Sampled By: Jesus Escobedo
Sample Of: Gas Spot
Sample Date: 11/11/2020 01:09
Sample Conditions: 1265 psig
Method: GPA 2286
Cylinder No: 1111-001162
Analyzed: 11/17/2020 13:21:28 by PGS
Sampling Company: OXY

Analytical Data

Components	Mol. %	Wt. %	GPM at 14.65 psia	
Hydrogen Sulfide	NIL	NIL		GPM TOTAL C2+
Nitrogen	1.320	1.675		GPM TOTAL C3+
Methane	76.201	55.381		GPM TOTAL iC5+
Carbon Dioxide	0.169	0.337		
Ethane	11.355	15.468	3.031	
Propane	5.728	11.443	1.575	
Iso-Butane	0.838	2.207	0.274	
n-Butane	2.238	5.893	0.705	
Iso-Pentane	0.636	2.079	0.232	
n-Pentane	0.759	2.481	0.275	
Hexanes	0.374	1.443	0.152	
Heptanes Plus	0.382	1.593	0.146	
	100.000	100.000	6.390	

Calculated Physical Properties

Relative Density Real Gas	Total	C7+
	0.7649	3.1738
Calculated Molecular Weight	22.07	91.92
Compressibility Factor	0.9960	

GPA 2172 Calculation:

Calculated Gross BTU per ft³ @ 14.65 psia & 60°F

Real Gas Dry BTU	1308	4850
Water Sat. Gas Base BTU	1285	4766
Ideal, Gross HV - Dry at 14.65 psia	1302.9	4850.4
Ideal, Gross HV - Wet	1280.1	NIL

Comments: H2S Field Content 0 ppm

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.



Certificate of Analysis

Number: 6030-20110087-001A

Artesia Laboratory

200 E Main St.
Artesia, NM 88210
Phone 575-746-3481Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

Nov. 17, 2020

Field: NMSW
Station Name: Corral Compressor Station 2 South
Station Number: N/A
Sample Point: N/A
Meter Number:
County: Eddy
Type of Sample: Spot-Cylinder
Heat Trace Used: N/A
Sampling Method: Fill and PurgeSampled By: Jesus Escobedo
Sample Of: Gas Spot
Sample Date: 11/11/2020 01:09
Sample Conditions: 1265 psig
Method: GPA 2286
Cylinder No: 1111-001162
Analyzed: 11/17/2020 13:21:28 by PGS
Sampling Company: OXY

Analytical Data

Components	Mol. %	Wt. %	GPM at 14.65 psia	
Hydrogen Sulfide	NIL	NIL		GPM TOTAL C2+ 6.390
Nitrogen	1.320	1.675		
Methane	76.201	55.381		
Carbon Dioxide	0.169	0.337		
Ethane	11.355	15.468	3.031	
Propane	5.728	11.443	1.575	
Iso-Butane	0.838	2.207	0.274	
n-Butane	2.238	5.893	0.705	
Iso-Pentane	0.636	2.079	0.232	
n-Pentane	0.759	2.481	0.275	
i-Hexanes	0.229	0.880	0.092	
n-Hexane	0.145	0.563	0.060	
Benzene	0.036	0.125	0.010	
Cyclohexane	0.091	0.348	0.031	
i-Heptanes	0.135	0.566	0.054	
n-Heptane	0.027	0.125	0.013	
Toluene	0.015	0.065	0.005	
i-Octanes	0.065	0.307	0.029	
n-Octane	0.003	0.015	0.001	
Ethylbenzene	0.001	0.002	NIL	
Xylenes	0.003	0.010	0.001	
i-Nonanes	0.005	0.025	0.002	
n-Nonane	0.001	0.003	NIL	
i-Decanes	NIL	NIL	NIL	
n-Decane	NIL	0.001	NIL	
Undecanes	NIL	0.001	NIL	
Dodecanes	NIL	NIL	NIL	
Tridecanes	NIL	NIL	NIL	
Tetradecanes Plus	NIL	NIL	NIL	
	100.000	100.000	6.390	



Certificate of Analysis

Number: 6030-20110087-001A

Artesia Laboratory

200 E Main St.
Artesia, NM 88210
Phone 575-746-3481Chandler Montgomery
Occidental Petroleum
1502 W Commerce Dr.
Carlsbad, NM 88220

Nov. 17, 2020

Field: NMSW
Station Name: Corral Compressor Station 2 South
Station Number: N/A
Sample Point: N/A
Meter Number:
County: Eddy
Type of Sample: Spot-Cylinder
Heat Trace Used: N/A
Sampling Method: Fill and PurgeSampled By: Jesus Escobedo
Sample Of: Gas Spot
Sample Date: 11/11/2020 01:09
Sample Conditions: 1265 psig
Method: GPA 2286
Cylinder No: 1111-001162
Analyzed: 11/17/2020 13:21:28 by PGS
Sampling Company: OXY

Calculated Physical Properties	Total
Calculated Molecular Weight	22.073

GPA 2172 Calculation:**Calculated Gross BTU per ft³ @ 14.65 psia & 60°F**

Real Gas Dry BTU	1308.0
Water Sat. Gas Base BTU	1285.2
Relative Density Real Gas	0.7649
Compressibility Factor	0.9960

Comments: H2S Field Content 0 ppm

Hydrocarbon Laboratory Manager

Quality Assurance: The above analyses are performed in accordance with ASTM, UOP, GPA guidelines for quality assurance, unless otherwise stated.

UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Corral CS 2S**Flare Date:** 02/05/2022**Duration of event:** 1 Hour 35 minutes**MCF Flared:** 356**Start Time:** 01:55 AM**End Time:** 03:30 AM**Cause:** Extreme Freezing Conditions & Temperatures > Facility Equipment Issues**Method of Flared Gas Measurement:** Gas Flare Meter**Comments:** This upset event was not caused by any wells associated with the facility.

1. Reason why this event was beyond Operator's control:

This event was caused by the sudden, unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and maintenance practices. In this case, there were two incidents that were caused by extreme freezing weather conditions and temperatures, which triggered flaring to occur. The first flaring incident was from 01:55 AM to 02:50 AM and in which, the scrubber dump lines froze, which caused the suction control valve to not open, prompting an unexpected and unavoidable shutdown of the facility's compression equipment. The second incident of flaring occurred from 11:00 AM to 11:40 AM, due to extreme freezing weather conditions and temperatures affecting multiple compressor units and causing them to shut down. The facility and the equipment were winterized as part of Oxy's usual operations practices for extreme cold weather, by having it insulated and heat traced. Notwithstanding compressor engine design and operation, compressors are inherently dynamic and even the smallest alarms, false or true, can be sudden, reasonably unforeseeable, and unexpected which can cause compression malfunctions to occur. Prior to the simultaneous malfunctions occurring, the compressor units were working as designed and operated normally prior to the sudden and without warning malfunctions due to extreme freezing weather conditions and temperatures. In both instances, the gas compression equipment shutdown caused by unexpected malfunctions, prompted by extreme weather conditions and temperatures, there was no gas takeaway, and thus field psi increased until set psi levels were reached which triggered flaring. The facility's gas compression equipment was working as designed and operated normally prior to the sudden and without warning malfunction and automatic shutdown of the compression equipment. These incidents were completely out of OXY's control to prevent from happening yet OXY made every effort to control and minimize emissions as much as possible during this event by working safely and diligently during this event.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, as the part of the overall process or steps to take to limit duration and magnitude of flaring. Oxy personnel are in the field 24/7 and can physically see when we are flaring which in turn are communicated to additional Oxy field personnel. Internal OXY procedures ensure that upon notice of flaring, malfunction gas compressor unit and/or multiple unit shutdown alarms, increased sensor line pressure alarms, etc., field production technician personnel are promptly notified, and are instructed to assess the issue as soon as possible to take prompt corrective action and minimize emissions. Oxy production technicians must assess whether the issue or circumstance is due to damage and repair is needed, or whether there are other reasons for its cause.

In this case, in both instances, OXY production techs and USA Compression mechanics worked together to thaw out frozen lines and increased the methanol injection rates to prevent future freezing events.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable, and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice, even during extreme weather conditions and temperatures. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this unit and continue to monitor the methanol injection rates for the equipment at this facility.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 82840

DEFINITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 82840
	Action Type: [C-129] Venting and/or Flaring (C-129)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: <ul style="list-style-type: none">• this application's operator, hereinafter "this operator";• venting and/or flaring, hereinafter "vent or flare";• any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms";• the statements in (and/or attached to) this, hereinafter "the statements in this";• and the past tense will be used in lieu of mixed past/present tense questions and statements.
--

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 82840

QUESTIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 82840
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2126640958] CORRAL #2 SOUTH COMP STATION

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a vent or flare event	Yes, minor venting and/or flaring of natural gas.

An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.

Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Extreme Freezing Conditions & Temperatures > Facility Equipment Issues

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	76
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 82840

QUESTIONS (continued)

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 82840
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	02/05/2022
Time vent or flare was discovered or commenced	01:55 AM
Time vent or flare was terminated	03:30 AM
Cumulative hours during this event	2

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 356 Mcf Recovered: 0 Mcf Lost: 356 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	No
Was notification of downstream activity received by this operator	Not answered.
Downstream OGRID that should have notified this operator	Not answered.
Date notified of downstream activity requiring this vent or flare	Not answered.
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control.	True
Please explain reason for why this event was beyond this operator's control	This event was caused by the sudden, unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and maintenance practices. In this case, there were two incidents that were caused by extreme freezing weather conditions and temperatures, which triggered flaring to occur. The first flaring incident was from 01:55 AM to 02:50 AM and in which, the scrubber dump lines froze, which caused the suction control valve to not open, prompting an unexpected and unavoidable shutdown of the facility's compression equipment. The second incident of flaring occurred from 11:00 AM to 11:40 AM, due to extreme freezing weather conditions and temperatures affecting multiple compressor units and causing them to shut down. The facility and the equipment were winterized as part of Oxy's usual operations practices for extreme cold weather, by having it insulated and heat traced. Notwithstanding compressor engine design and operation, compressors are inherently dynamic and even the smallest alarms, false or true, can be sudden, reasonably unforeseeable, and unexpected which can cause compression malfunctions to occur. Prior to the simultaneous malfunctions occurring, the compressor units were working as designed and operated normally prior to the sudden and without warning malfunctions due to extreme freezing weather conditions and temperatures. In both instances, the gas compression equipment shutdown caused by unexpected malfunctions, prompted by extreme weather conditions and temperatures, there was no gas takeaway, and thus field psi increased until set psi levels were reached which triggered flaring. The facility's gas compression equipment was working as designed and operated normally prior to the sudden and without warning malfunction and automatic shutdown of the compression equipment.
Steps taken to limit the duration and magnitude of vent or flare	It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, as the part of the overall process or steps to take to limit duration and magnitude of flaring. Oxy personnel are in the field 24/7 and can physically see when we are flaring which in turn are communicated to additional Oxy field personnel. Internal OXY procedures ensure that upon notice of flaring, malfunction gas compressor unit and/or multiple unit shutdown alarms, increased sensor line pressure alarms, etc., field production technician personnel are promptly notified, and are instructed to assess the issue as soon as possible to take prompt corrective action and minimize emissions. Oxy production technicians must assess whether the issue or circumstance is due to damage and repair is needed, or whether there are other reasons for its cause. In this case, in both instances, OXY production techs and USA Compression mechanics worked together to thaw out frozen lines and increased the methanol injection rates to prevent future freezing events.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable, and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice, even during extreme weather conditions and temperatures. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this unit and continue to monitor the methanol injection rates for the equipment at this facility.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 82840

ACKNOWLEDGMENTS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 82840
	Action Type: [C-129] Venting and/or Flaring (C-129)

ACKNOWLEDGMENTS

<input checked="" type="checkbox"/>	I acknowledge that I am authorized to submit a <i>Venting and/or Flaring</i> (C-129) report on behalf of this operator and understand that this report can be a complete C-129 submission per 19.15.27.8 and 19.15.28.8 NMAC.
<input checked="" type="checkbox"/>	I acknowledge that upon submitting this application, I will be creating a new incident file (assigned to this operator) to track any C-129 forms, pursuant to 19.15.27.7 and 19.15.28.8 NMAC and understand that this submission meets the notification requirements of Paragraph (1) of Subsection G and F respectively.
<input checked="" type="checkbox"/>	I hereby certify the statements in this report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
<input checked="" type="checkbox"/>	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
<input checked="" type="checkbox"/>	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 82840

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 82840
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	2/20/2022