

**Volumetrics Inc.**

3710 East Rio Grande St, Victoria, TX-77901
Phone: 361-827-4024

Company: OXY USA INC
Field/Location : NMSW
Station Name : CEDAR CANYON TO ENTERPRISE
Station Number : NA
Sample Date: 3/10/22 2:40 PM
Analysis Date: 3/17/22 8:30 PM
Instrument: INFICON
Calibration/Verification Date: 3/17/2022
Heat Trace used: YES

Work Order: 4000535215
Sampled by: OXY/JE
Sample Type : SPOT-CYLINDER
Sample Temperature (F): NA
Sample Pressure (PSIG): 1237
Flow rate (MCF/Day): NA
Ambient Temperature (F): 50
Sampling method: FILL & EMPTY
Cylinder Number: 27772

NATURAL GAS ANALYSIS: GPA 2261

Components	Un-Normalized Mol%	Normalized Mol%	GPM 14.650	GPM 14.730	GPM 15.025
Hydrogen Sulfide	0.0000	0.0000			
Nitrogen	1.4010	1.4329			
Methane	73.2835	74.9537			
Carbon Dioxide	0.1272	0.1301			
Ethane	12.0004	12.2739	3.277	3.295	3.361
Propane	6.1002	6.2392	1.716	1.726	1.760
Isobutane	0.8643	0.8840	0.289	0.290	0.296
N-butane	2.1629	2.2122	0.696	0.700	0.714
Isopentane	0.5139	0.5256	0.192	0.193	0.197
N-Pentane	0.5755	0.5886	0.213	0.214	0.218
Hexanes(C6's)	0.3556	0.3637	0.149	0.150	0.153
Heptanes (C7's)	0.2741	0.2804	0.129	0.130	0.132
Octanes (C8's)	0.1001	0.1024	0.052	0.053	0.054
Nonanes Plus (C9+)	0.0130	0.0133	0.007	0.008	0.008
Total	97.7718	100.0000			

Physical Properties (Calculated)

	14.650 psia	14.730 psia	15.025 psia
Total GPM Ethane+	6.721	6.758	6.893
Total GPM Iso-Pentane+	0.743	0.747	0.762
Compressibility (Z)	0.9959	0.9959	0.9958
Specific Gravity (Air=1) @ 60 °F	0.7713	0.7713	0.7714
Molecular Weight	22.257	22.257	22.257

Gross Heating Value

	14.650 psia	14.730 psia	15.025 psia
Dry, Real (BTU/Ft ³)	1318.1	1325.3	1352.0
Wet, Real (BTU/Ft ³)	1295.0	1302.1	1328.3
Dry, Ideal (BTU/Ft ³)	1312.7	1319.9	1346.3
Wet, Ideal (BTU/Ft ³)	1289.7	1296.8	1322.7

Temperature base 60 °F

Comment: FIELD H2S =0 PPM

Verified by

Mostaq Ahammad
Petroleum Chemist

Approved by

Deann Friend

Deann Friend
Laboratory Manager

UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Cedar Canyon CPD**Flare Date:** 12/23/2022**Duration of event:** 8 Hours 25 minutes**MCF Flared:** 1720**Start Time:** 01:00 AM**End Time:** 09:25 AM**Cause:** Emergency Flare > Downstream Activity > Enterprise > Facility Equipment > Extreme Freezing Conditions & Temperatures**Method of Flared Gas Measurement:** Gas Flare Meter**Comments:** Combined volume of all intermittent flaring occurrences: 1720 MCF.**1. Reason why this event was beyond Operator's control:**

This event was caused by the sudden, unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and maintenance practices. In this case, extreme freezing weather conditions and below 15-degree temperatures, affected third party pipeline operator, Enterprise's, facility equipment, which caused their equipment to malfunction and subsequently shut down, which then prompted emergency shutdowns to occur multiple times through the mid-morning, afternoon and evening hours, which in turn, affected Oxy's ability to send its gas to Enterprise, thereby, triggering flaring instances to occur. Oxy's equipment were winterized as part of Oxy's usual operations practices for extreme cold weather, by having its facility equipment insulated and heat traced, and having methanol readily available to assist with freezing issues, if and when they occurred. The temperature was a minimum of 10-degrees through the night. Third-party pipeline operator, Enterprise, who owns and operates the sales gas service pipeline, did not provide advance notice of the multiple disruptions to their gas pipeline due to their downstream facility experienced compression issues and then subsequently had facility freezing issues. This incident was completely out of OXY's control to prevent from happening yet OXY made every effort to control and minimize emissions as much as possible during this event by working safely and diligently during this event. The Cedar Canyon CDP flare is a gas gathering flare system for multiple tank batteries across Oxy's Cedar Canyon area. The minimal amount of gas flow allowed to be flared was done out of necessity to protect personnel and equipment as a safeguard.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route its stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, as the part of the overall process or steps to take to limit duration and magnitude of flaring. Oxy personnel are in the field 24/7 and can physically see when we are flaring which in turn are communicated to additional Oxy field personnel. Internal OXY procedures ensure that upon notice of flaring, malfunction gas compressor unit and/or multiple unit shutdown alarms, increased sensor line pressure alarms, etc., field production technician personnel are promptly notified, and are instructed to assess the issue as soon as possible to take prompt corrective action and minimize emissions. Oxy production technicians must assess whether the issue or circumstance is due to damage and repair is needed, or whether there are other reasons for its cause. In this case, extreme freezing weather conditions and below 15-degree temperatures, affected third party pipeline

operator, Enterprise's, facility equipment, which caused their equipment to malfunction and subsequently shut down, which then prompted emergency shutdowns to occur multiple times through the mid-morning, afternoon and evening hours, which in turn, affected Oxy's ability to send its gas to Enterprise, thereby, triggering flaring instances to occur. Oxy's equipment were winterized as part of Oxy's usual operations practices for extreme cold weather, by having its facility equipment insulated and heat traced, and having methanol readily available to assist with freezing issues, if and when they occurred. The temperature was a minimum of 10-degrees through the night. In addition, the flare has an automated mitigation optimizer which cut injection rates to wells in the field to reduce injection and sales gas to mitigate emissions. Third-party pipeline operator, Enterprise, who owns and operates the sales gas service pipeline, did not provide advance notice of the multiple disruptions to their gas pipeline due to their downstream facility experienced compression issues and then subsequently had facility freezing issues. This incident was completely out of OXY's control to prevent from happening yet OXY made every effort to control and minimize emissions as much as possible during this event by working safely and diligently during this event. The Cedar Canyon CDP flare is a gas gathering flare system for multiple tank batteries across Oxy's Cedar Canyon area. The minimal amount of gas flow allowed to be flared was done out of necessity to protect personnel and equipment as a safeguard.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in the corrective actions to eliminate the cause and potential reoccurrence of an Enterprise gas flow pipeline restriction or shut-in, as this control issue is downstream of Oxy's custody transfer point and out of Oxy's control to avoid, prevent from happening or reoccurring. Enterprise's downstream facilities and associated facilities may have facility equipment issues which will reoccur from time to time, including due to extreme weather conditions and temperatures, which, can trigger a spike in their gas line pressure, which in turn, directly impacts Oxy's ability to send gas to them. When Enterprise has downstream activity issues or greatly struggles to handle the volume of gas being sent to them by Oxy, Enterprise then restricts Oxy's ability to send gas, which then prompts Oxy to route all of its stranded gas not pushed into the Enterprise gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to keep continually communicate with Enterprise personnel during these types of situations and when possible, engage in emergency alternative compression reaction strategies.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

DEFINITIONS

Action 180435

DEFINITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 180435
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

DEFINITIONS

For the sake of brevity and completeness, please allow for the following in all groups of questions and for the rest of this application: • this application's operator, hereinafter "this operator"; • venting and/or flaring, hereinafter "vent or flare"; • any notification or report(s) of the C-129 form family, hereinafter "any C-129 forms"; • the statements in (and/or attached to) this, hereinafter "the statements in this"; • and the past tense will be used in lieu of mixed past/present tense questions and statements.
--

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Oil Conservation Division

1220 S. St Francis Dr.

Santa Fe, NM 87505

QUESTIONS

Action 180435

QUESTIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 180435
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

QUESTIONS

Prerequisites Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.	
Incident Operator	[16696] OXY USA INC
Incident Type	Flare
Incident Status	Closure Not Approved
Incident Well	Unavailable.
Incident Facility	[fAPP2126642450] CEDAR CANYON ETP CDP
Only valid Vent, Flare or Vent with Flaring incidents (selected above in the Application Details section) that are assigned to your current operator can be amended with this C-129A application.	

Determination of Reporting Requirements Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.	
Was this vent or flare caused by an emergency or malfunction	Yes
Did this vent or flare last eight hours or more cumulatively within any 24-hour period from a single event	Yes
Is this considered a submission for a vent or flare event	Yes, major venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this vent or flare result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the vent or flare within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved	
Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Downstream Activity > Enterprise > Facility Equipment > Extreme Freezing Conditions & Temperatures

Representative Compositional Analysis of Vented or Flared Natural Gas Please provide the mole percent for the percentage questions in this group.	
Methane (CH4) percentage	75
Nitrogen (N2) percentage, if greater than one percent	1
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0
If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.	
Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sufide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS, Page 2

Action 180435

QUESTIONS (continued)

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 180435
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

QUESTIONS

Date(s) and Time(s)	
Date vent or flare was discovered or commenced	12/23/2022
Time vent or flare was discovered or commenced	01:00 AM
Time vent or flare was terminated	09:25 AM
Cumulative hours during this event	9

Measured or Estimated Volume of Vented or Flared Natural Gas	
Natural Gas Vented (Mcf) Details	Not answered.
Natural Gas Flared (Mcf) Details	Cause: Freeze Other (Specify) Natural Gas Flared Released: 1,720 Mcf Recovered: 0 Mcf Lost: 1,720 Mcf.
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was this vent or flare a result of downstream activity	Yes
Was notification of downstream activity received by this operator	No
Downstream OGRID that should have notified this operator	[713731] Enterprise Crude Pipeline LLC
Date notified of downstream activity requiring this vent or flare	
Time notified of downstream activity requiring this vent or flare	Not answered.

Steps and Actions to Prevent Waste	
For this event, this operator could not have reasonably anticipated the current event and it was beyond this operator's control	True
Please explain reason for why this event was beyond this operator's control	This event was caused by the sudden, unavoidable breakdown of equipment or process that was beyond the owner/operator's control and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and maintenance practices. In this case, extreme freezing weather conditions and below 15-degree temperatures, affected third party pipeline operator, Enterprise's, facility equipment, which caused their equipment to malfunction and subsequently shut down, which then prompted emergency shutdowns to occur multiple times through the mid-morning, afternoon and evening hours, which in turn, affected Oxy's ability to send its gas to Enterprise, thereby, triggering flaring instances to occur. Oxy's equipment were winterized as part of Oxy's usual operations practices for extreme cold weather, by having its facility equipment insulated and heat traced, and having methanol readily available to assist with freezing issues, if and when they occurred. The temperature was a minimum of 10-degrees through the night. Third-party pipeline operator, Enterprise, who owns and operates the sales gas service pipeline, did not provide advance notice of the multiple disruptions to their gas pipeline due to their downstream facility experienced compression issues and then subsequently had facility freezing issues. This incident was completely out of OXY's control to prevent from happening yet OXY made every effort to control and minimize emissions as much as possible during this event by working safely and diligently during this event. The Cedar Canyon CDP flare is a gas gathering flare system for multiple tank batteries across Oxy's Cedar Canyon area. The minimal amount of gas flow allowed to be flared was done out of necessity to protect personnel and equipment as a safeguard.
Steps taken to limit the duration and magnitude of vent or flare	In this case, extreme freezing weather conditions and below 15-degree temperatures, affected third party pipeline operator, Enterprise's, facility equipment, which caused their equipment to malfunction and subsequently shut down, which then prompted emergency shutdowns to occur multiple times through the mid-morning, afternoon and evening hours, which in turn, affected Oxy's ability to send its gas to Enterprise, thereby, triggering flaring instances to occur. Oxy's equipment were winterized as part of Oxy's usual operations practices for extreme cold weather, by having its facility equipment insulated and heat traced, and having methanol readily available to assist with freezing issues, if and when they occurred. The temperature was a minimum of 10-degrees through the night. In addition, the flare has an automated mitigation optimizer which cut injection rates to wells in the field to reduce injection and sales gas to mitigate emissions. Third-party pipeline operator, Enterprise, who owns and operates the sales gas service pipeline, did not provide advance notice of the multiple disruptions to their gas pipeline due to their downstream facility experienced compression issues and then subsequently had facility freezing issues. This incident was completely out of OXY's control to prevent from happening yet OXY made every effort to control and minimize emissions as much as possible during this event by working safely and diligently during this event. The Cedar Canyon CDP flare is a gas gathering flare system for multiple tank batteries across Oxy's Cedar Canyon area. The minimal amount of gas flow allowed to be flared was done out of necessity to protect personnel and equipment as a safeguard.
Corrective actions taken to eliminate the cause and reoccurrence of vent or flare	Oxy is limited in the corrective actions to eliminate the cause and potential reoccurrence of an Enterprise gas flow pipeline restriction or shut-in, as this control issue is downstream of Oxy's custody transfer point and out of Oxy's control to avoid, prevent from happening or reoccurring. Enterprise's downstream facilities and associated facilities may have facility equipment issues which will reoccur from time to time, including due to extreme weather conditions and temperatures, which, can trigger a spike in their gas line pressure, which in turn, directly impacts Oxy's ability to send gas to them. When Enterprise has downstream activity issues or greatly struggles to handle the volume of gas being sent to them by Oxy, Enterprise then restricts Oxy's ability to send gas, which then prompts Oxy to route all of its stranded gas not pushed into the Enterprise gas pipeline, to flare. OXY makes every effort to control and minimize emissions as much as possible. The only actions that Oxy can take and handle that is within its control, is to keep continually communicate with Enterprise personnel during these types of situations and when possible, engage in emergency alternative compression reaction strategies.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

ACKNOWLEDGMENTS

Action 180435

ACKNOWLEDGMENTS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 180435
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

ACKNOWLEDGMENTS

☒	I acknowledge that with this application I will be amending an existing incident file (assigned to this operator) for a vent or flare event, pursuant to 19.15.27 and 19.15.28 NMAC.
☒	I acknowledge that amending an incident file does not replace original submitted application(s) or information and understand that any C-129 forms submitted to the OCD will be logged and stored as public record.
☒	I hereby certify the statements in this amending report are true and correct to the best of my knowledge and acknowledge that any false statement may be subject to civil and criminal penalties under the Oil and Gas Act.
☒	I acknowledge that the acceptance of any C-129 forms by the OCD does not relieve this operator of liability should their operations have failed to adequately investigate, report, and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment.
☒	I acknowledge that OCD acceptance of any C-129 forms does not relieve this operator of responsibility for compliance with any other applicable federal, state, or local laws and/or regulations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 180435

CONDITIONS

Operator: OXY USA INC P.O. Box 4294 Houston, TX 772104294	OGRID: 16696
	Action Number: 180435
	Action Type: [C-129] Amend Venting and/or Flaring (C-129A)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires further amendment(s), submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	1/29/2023