

EOG Resources, Inc. Artesia Division Office 104 S. 4<sup>th</sup> Street Artesia, N. M. 88210

August 30, 2022

Bradford Billings EMNRD 1220 South St. Francis Drive Santa Fe, NM 87505

Re: Anadarko Pardue Farms ANQ Com #1 30-015-22212 F-27-21S-24E Eddy County, NM 2RP-468 nMLB1031337060

EOG Resources, Inc. is submitting the enclosed Closure Report for the above referenced site which currently has an open incident on the NMOCD E-Permitting website. The report is being submitted in reference to the C-141 Initial dated October 13, 2010, and the original C-141 Final submitted September 27, 2011. EOG Resources, Inc. has included a C-141 Final on the most current form in this Closure Report, and hereby requests closure of the open incident.

If you have any questions, feel free to call me at (575) 748-1471.

Respectfully,

Chase Settle

Chase Settle Rep Safety & Environmental Sr EOG Resources, Inc.



Anadarko Pardue Farms ANQ Com #1 Closure Report #nMLB1031337060



August 30, 2022

#### Anadarko Pardue Farms ANQ Com #1

**Closure Report** 

30-015-22212

F-27-21S-24E

Eddy County, NM

August 30, 2022

nMLB1031337060

Anadarko P Closure Rep #nMLB103		<b>eog resources</b>	August	t 30, 2022
I.	Location	Table of Contents		1
II.	Background			1
III.	Scope of Work Completed.			1
IV.	Closure Request			1

1

#### Appendices:

Appendix A: Original C-141 Initial

Appendix B: Internal YPC Documents/Photos

Appendix C: NMOCD Correspondence

Appendix D: Original Closure Report

Appendix E: Current C-141 Closure

Anadarko Pardue Farms ANQ Com #1 Closure Report #nMLB1031337060



August 30, 2022

Page 4 of 31

#### I. Location

The site is located in Eddy County, New Mexico approximately 10.6 miles southwest of Seven Rivers.

#### II. Background

On September 7, 2010, Yates Petroleum Corporation (YPC) had a release of 18 barrels of crude oil at the Anadarko Pardue ANQ Com #1 when a circulating pump failure occurred, allowing an approximate area of 21 feet by 10 feet to be impacted within the berm of the battery. A vacuum truck was mobilized to the site to begin retrieval of the standing fluid upon discovery of the release, with a dirt contractor performing excavation of the visually impacted soils the following day. A C-141 Initial (Appendix A) was submitted to NMOCD on October 13, 2010.

#### III. Scope of Work Completed

YPC begin assessing the release through the collection of soil samples and performing analysis through the internal laboratory it maintained during that time period, as indicated on the Status Report page included with other internal documents as Appendix B. These first initial samples exhibited total petroleum hydrocarbon (TPH) results above the Recommended Remediation Action Level (RRAL) for according to the *New Mexico Oil Conservation Division (NMOCD) Guidelines for Remediation of Leaks, Spills and Releases,* dated August 13, 1993. YPC through the course of addressing the release, determined that the best way to fully address the impacts around the equipment would be to downsize the facility and reduce the number of production tanks within the battery. The decision was made to start the downsizing at the southernmost tanks to properly address the release that had occurred in September 2010. An email was sent to NMOCD on December 6, 2010, explaining the decision to pursue this effort. This is included in Appendix C.

Once the production tanks and equipment were removed from the release area, the excavation was increased to a depth of four (4) feet below grade surface (bgs). Confirmation soil sampling then occurred on January 14, 2011, with these samples submitted to Cardinal Laboratory for analysis. Results (Appendix D) of the confirmation sampling event indicated that the excavation had removed all impacted soils above the RRALs, meeting the closure criteria for the era.

Backfill of the excavation was undertaken beginning in May, along with further reconstruction of the battery. On September 27, 2011, the original C-141 Final was submitted to NMOCD requesting closure of 2RP-468. These documents are included as Appendix D.

#### IV. Closure Request

This release, remediation work, and original C-141 Final submission occurred prior to the passage of the current Spill Rule (NMAC 19.15.29), therefore the requirements for a scaled site map and excavation photographs cannot be accommodated as they were not required by NMOCD during the time of this incident occurring.

Based on the confirmation soil analytical results, EOG Resources, Inc. believes enough evidence is provided to substantiate that remedial activities were completed correctly for the time period, and requests Closure of nMLB1031337060 (2RP-468), the current C-141 Closure Form is included with this Closure Report as Appendix E.



August 30, 2022

## Appendix A Original C-141 Initial

<b>N</b>	RECEIVED
1025 N. French Dr., Flodds, NM 88240	ate of New Mexico nerals and Natural Resources OCT 14 2010 Revised October 10, 2003
1301 W. Grand Avenue, Artesia, NM 88210	Submit 2 Conjes to appropriate
1000 Rio Brazos Road, Aztec, NM 87410	Conservation Division South St. Francis Dr. Submit 2 Copies to appropriate NMOCD ARTESHAC Office in accordance with Rule 116 on back
1220 C. C. Emmil- Dr. Conta E. NIX (22000	inta Fe, NM 87505
Release Notif	ification and Corrective Action
Name of Company OGRID Numb	
Yates Petroleum Corporation 25575	Amanda Trujillo
Address 104 S. 4 <sup>TH</sup> Street	Telephone No. 575-748-1471
Facility Name API Number	Facility Type Order Number
Anadarko Pardue ANQ Battery 30-015-22212	
Surface Owner Mineral Ov Federal Federal	Wener Lease No.
	CATION OF RELEASE           North/South Line         Feet from the         East/West Line         County
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	North 1980 West Eddy
Type of Release NA'I	TURE OF RELEASE           Volume of Release         Volume Recovered
Oil	18 bb1 10
Source of Release Valve not fully closed	Date and Hour of Occurrence Date and Hour of Discovery 9/7/2010 9/7/2010 - PM
Was Immediate Notice Given?	If YES, To Whom?
By Whom?	equired Mike Bratcher – NMOCD/Artesia Date and Hour
Amanda Trujillo – Yates Petroleum Corporation	09/10/2010 pm
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse. N/A
If a Watercourse was Impacted, Describe Fully.*	
N/A Describe Cause of Problem and Remedial Action Taken.*	
Circulating pump failed and catch valve ran over because valve was pick up standing fluids. A clean up crew was then dispatched to rem	as not fully closed. Fluid circulated back through valve. A vacuum truck was called to
Describe Area Affected and Cleanup Action Taken.*	
An approximate size of 21' x 10' was impacted. The impacted area of at an NMOCD approved facility. Crew excavated contaminated s	a is located near the last oil tank. Soil from the pooling areas was excavated and disposed soils; soils were placed directly onto plastic. Vertical and horizontal delineation samples
will taken and analysis ran for TPH and BTEX once a contaminate	ed material has been removed. Chlorides sampling available upon request. Depth to f the State Engineer); Wellhead Protection Area: No; Distance to Surface Water
Body: >1000'; SITE RANKING IS 0. Based on site ground wat	iter quality and enclosed analytical results No Amak first submet her
	lete to the best of my knowledge and understand that pursuant to NMOCD rules and clease notifications and perform corrective actions for releases which may endanger
public health or the environment. The acceptance of a C-141 report	rt by the NMOCD marked as "Final Report" does not relieve the operator of liability
	emediate contamination that pose a threat to ground water, surface water, human health report does not relieve the operator of responsibility for compliance with any other
federal, state, or local laws and/or regulations.	OIL CONSERVATION DIVISION
A	1.
Signature: / / lugello	Approved by Distances Bervison
Printed Name: Amanda Trujillo	
Title: Environmental Scientist	Approval DateNOV 0 9 2010 Expiration Date:
E-mail Address: atrujillo@yatespetroleum.com	Conditions of Approval:
	REMEDIATION per OCD Rules and
	- CURMIT REMEDIATION
-	Delineation for BTEX, TAH & Chloride reguired
	1 A RTEV.
	Delineation for DIGN!
	TAH & Chloride reguired

#### Bratcher, Mike, EMNRD

From: Sent: To: Subject: Attachments: Amanda Trujillo [atrujillo@yatespetroleum.com] Thursday, October 14, 2010 5:25 PM Bratcher, Mike, EMNRD RE: Anadarko Pardue ANQ Com Anadarko Pardue ANQ #1(Inital 9-7-2010) .pdf

Attached is the C-141

Thank you 😊

Amanda N. Trujillo Environmental Scientist Yates Petroleum Corporation Office 575-748-4310 Cell 575-703-6537 Email atrujillo@yatespetroleum.com

> -----Original Message-----From: Amanda Trujillo Sent: Friday, September 10, 2010 4:03 PM To: 'Bratcher, Mike, EMNRD' Cc: Jerry Fanning Subject: Anadarko Pardue ANQ Com

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Anadarko Pardue ANQ Com Sec. 27,Township 21 South, Range 24 East Eddy County Date of Release: 09/07/10 Approximately 18 barrels of Oil were released Approximately 10 barrels were recovered Cause of release has been isolated and repairs are in progress Site will be evaluated and a work plan for remediation will be submitted for consideration

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo Environmental Scientist Yates Petroleum Corporation Office 575-748-4310 Cell 575-703-6537 Email <u>atrujillo@yatespetroleum.com</u>



August 30, 2022

Anadarko Pardue Farms ANQ Com #1 Closure Report #nMLB1031337060

# **Appendix B** Internal YPC Documents/Photos

BREAKS, SPI	LLS AND LEAKS REPORT
Barran Barating (), 1( Karra	
Person Reporting <u>GARY</u> HICKOX	
Person Reported to (Field Supervisor) <u>Joe PAIMA</u> Environmental Notification Coordinator	Time Reported: 3;31 am off
	Time Reported: am pm
1. LOCATION:	
	ANQ COM /TANKS & BAttery
Location $\overrightarrow{F}$ Section $27$ Township $\underline{TzIS}$	Range RZ4 E County: Eddy Co NM
Surface Owner: 23/DFNL	API: 30-015-22212
2. TIME OF INCIDENT:	112 00 010 20012
Date: <u>9-7-2010</u> Time:	<u>3'.00</u> am (pm)
3. SOURCE AND CAUSE: CIRCULATING PUMp Faile Valve Not Fully closed Circulated	d AND CAtch Vate RAN over
Valve Not Fully closed Circulated	acek through Vate
4. TYPE OF DISCHARGE	Other
5. QUANITY:	
	f Oil Barrels of Water
Barrels of	
MCF Gas	
Barrels of	1 <u></u>
6. SITE CHARACTERISTICS:	
Weather Conditions: SUNNY Dry 96 Soi	il Type and Condition: per gravel / Dirt
Distance & Direction to fresh water wells or watercourse:	sid NOT ESCAPE CONTAINMENT
Secondary Containment type & condition:	ed over diat -
Miscellaneous:	
	5 <sup>1</sup>
7. IMMEDIATE CORRECTIVE ACTION:	
Action and time taken to control incident:CAILED Vac TRU	1014 ( limb wife Source) to
SUCKUD Duddled Oil, Medrano's	0 10 1
the morning of the beat & 2010	ON Site 7AM this MARNING
	SPILFORM.XLS
а <b>1</b>	Prol/Mykol/Forms

200

Page 9 of 31

Released to Imaging: 3/7/2023 12:58:06 PM

•

#### BREAKS, SPILLS AND LEAKS REPORT

#### 8. SITE ASSESMENT

Page 10 of 31



. .

Released to Imaging: 3/7/2023 12:58:06 PM









Received by OCD: 8/31/2022 12:43:44 PM

#### Status Report

;

Well/Location Na	ime: Anadarko	Field Supervisor: Junior Orquiz	
Location: Unit F	Section 27,	T21S-R24E	Eddy County, NM
Latitude:		Longitude:	API# 30-015-22212
		Mineral Owner: Federal	Lease No.

Directions: SOUTH ON 285 TO KINCAID ROAD, TURN WEST AND GO DOWN TO PENASCO GAS PLANT, FOLLOW EAST FENCE NORTH TO LOCATION

SITE RANKING IS ZERO (0), Depth to Ground Water: <100' (approx.100'), Wellhead Protection Area: No, Distance to Surface Water Body: >1000'.

Date.	Sight Tratection Comment
9102910 1075/2010	Sight Inspection Comment Inspected spill took samples ran in Lab. TPH was out of
	Fande
11/8/10	Somples showed High GROS Jerry & Amanda reevaluated spill decided battery is in a high profile area and downsizing the battery was the bat when
11/17/10	Jerry & Amanda reevaluated spill decided battery is
	in a high profile area and downsizing the battery was the
	best Mole.
11/23/10	New bern was built and time frame was est to reconstruct batteny. Clean up will begin on the west side
	reconstruct battery Clean up will begin on the west side
12/6/10	Talked to S. Medrano. He said tanks were being cleaned.
	Tanks should be removed Friday and excavation will
	likely start Monday Dec. B.
	emoined Bratcher to give him notice of reconstruction. See email
12/14/10	excavation undertant began. Visible contamination
	at 2.5' depth. Area size approx 50'x30'
1/4/10	Soccon Medrano called said excavation was complete
16/10	Sampled sent to cardnial on 1/7/10
1/14/10	Samples came back within limits for site ranking of zero
FUGUL	emailed Junior told him it was ok to backfill
5/19/11	BackFill & reconstruction of Battery begin.
9127111	Regust closure.
	1

11/23/2010



Anadarko Pardue Farms ANQ Com #1 Closure Report #nMLB1031337060



August 30, 2022

# Appendix C NMOCD Correspondence

#### Amanda Trujillo

Sent: Monday, December 06, 2010 3:40 PM

To: 'Bratcher, Mike, EMNRD'

Cc: Jerry Fanning

Subject: RE: Anadarko Pardue ANQ Com

Mike:

In addressing the release at the Anadarko Pardue Battery, we have decided to downsize the battery, due to decreased production. I wanted to give you heads up in the event anyone from the OCD decided to take a look at the release and wondered why there so much work being done. I will contact you when we are ready to do the witnessed sampling.

Thank you,

Amanda N. Trujillo Environmental Scientist Yates Petroleum Corporation Office 575-748-4310 Cell 575-703-6537 Email atrujillo@yatespetroleum.com

> -----Original Message----- **From:** Amanda Trujillo **Sent:** Thursday, October 14, 2010 5:25 PM **To:** 'Bratcher, Mike, EMNRD' **Subject:** RE: Anadarko Pardue ANQ Com

Attached is the C-141

Thank you 🙂

Amanda N. Trujillo Environmental Scientist Yates Petroleum Corporation Office 575-748-4310 Cell 575-703-6537 Email atrujillo@yatespetroleum.com

> -----Original Message-----From: Amanda Trujillo Sent: Friday, September 10, 2010 4:03 PM To: 'Bratcher, Mike, EMNRD' Cc: Jerry Fanning Subject: Anadarko Pardue ANQ Com

Mr. Mike Bratcher:

Yates Petroleum reports a release at the following location:

Anadarko Pardue ANQ Com Sec. 27,Township 21 South, Range 24 East Eddy County Date of Release: 09/07/10 Approximately 18 barrels of Oil were released Approximately 10 barrels were recovered Released to Imaging: 3/7/2023 12:58:06 PM

12/6/2010

Released to Imaging: 3/7/2023 12:58:06 PM

Cause of release as been isolated and repairs are in progres.

If you should have any questions please feel free to contact me at the number below.

Amanda N. Trujillo Environmental Scientist Yates Petroleum Corporation Office 575-748-4310 Cell 575-703-6537 Email atrujillo@yatespetroleum.com



Anadarko Pardue Farms ANQ Com #1 Closure Report #nMLB1031337060



August 30, 2022

# Appendix D Original Closure Report

District I         District II         301 W. Grand Avenue, Artesia, NM 88240         District III         1000 Rio Brazos Road, Aztec, NM 87410         District IV         1220 S. St. Francis Dr., Santa Fe, NM 87505         Name of Company         Yates Petroleum Corporation         Address         104 S. 4 <sup>TH</sup> Street         Facility Name         Anadarko Pardue ANQ Battery	Energy Mineral Oil Conse 1220 Sour Santa I Release Notificat OPERATO OGRID Number 25575 API Number 30-015-22212 Mineral Owner	ervation Divi th St. Franci Fe, NM 8750 ion and Corre R Contact Amanda Truj Telephone N 575-748-147 Facility Type Gas well	Resources ision s Dr. )5 ctive Action [ iillo o. 1	Initial Repo Order I 2RP- Lease I	Number	
Federal	Federal					
		ON OF RELE		P+/32 . 5 '	Contraction	
Unit LetterSectionTownshipRangeF2721S24E	Feet from the Nort 2310	h/South Line North	Feet from the 1980	East/West Line West	County Eddy	
					· · · · · ·	
True of Dalage	NATUR	E OF RELEA		17.1		
Type of Release Oil		Volume of I 18 bbl	Kelease	10	Recovered	
Source of Release Valve not fully closed		Date and Hour of Occurrence Date and Hour of Discovery 9/7/2010 9/7/2010 - PM				
Was Immediate Notice Given?		If YES, To Whom?				
By Whom?	No 🗌 Not Require	Mike Bratcher – NMOCD/Artesia       Date and Hour				
Amanda Trujillo - Yates Petroleum Corporation	1	09/10/2010 pm				
Was a Watercourse Reached?	No	If YES, Vol N/A	ume Impacting the	e Watercourse.		
If a Watercourse was Impacted, Describe Fully. N/A						
N/A Describe Cause of Problem and Remedial Action Circulating pump failed and catch valve ran over pick up standing fluids. A clean up crew was the Describe Area Affected and Cleanup Action Tal	r because valve was not en dispatched to remove	fully closed. Flu all visibly conta	id circulated back minated material.	through valve.	A vacuum truck was called to	
An approximate size of 21' x 10' was impacted. of at an NMOCD approved facility. Crew excav will taken and analysis ran for TPH and BTEX Ground Water: >100' (approx. 100', per New Body: >1000'; SITE RANKING IS 0. Based	The impacted area is lo ated contaminated soils once a contaminated may Mexico Office of the S	; soils were place aterial has been r State Engineer)	ed directly onto pl emoved. Chloride ; Wellhead Prote	astic. Vertical an s sampling availa ction Area: No;	d horizontal delineation samples able upon request. Depth to	
I hereby certify that the information given above	e is true and complete to	the best of my k	nowledge and un	derstand that pur		
regulations all operators are required to report a public health or the environment. The acceptant	nd/or file certain release ce of a C-141 report by t	notifications and the NMOCD ma	d perform correcti rked as "Final Re	ve actions for rel port" does not rel	leases which may endanger lieve the operator of liability	
should their operations have failed to adequately or the environment. In addition, NMOCD accept	investigate and remedi	ate contaminatio	n that pose a threa	at to ground wate	r, surface water, human health	
federal, state, or local laws and/or regulations.	nance of a C-141 report	does not reneve	the operator of re	esponsionity for c	compliance with any other	
Signature: A Curlle			OIL CONS	ERVATION	DIVISION	
Printed Name: Amanda Trujillo	Approved by I	District Supervisor	r:			
Title: Environmental Scientist	Approval Date	:	Expiration	Date:		
E-mail Address: atrujillo@yatespetroleum.com		Conditions of	Approval:		Attached	
Attach Additional Sheets If Necessary	one: 575-748-4310					
Received by						
ceiv						
Rei						

Released to Imaging: 3/7/2023 12:58:06 PM

•



Released to Imaging: 3/7/2023 12:58:06 PM

Rece

January 14, 2011

AMANDA TRUJILLO Yates Energy Petroleum Corp 105 S 4th Street Artesia, NM 88210

RE: ANADARKO PARDU BATTERY

Enclosed are the results of analyses for samples received by the laboratory on 01/07/11 14:00.

Cardinal Laboratories is accredited through Texas NELAP for:

Method SW-846 8021	Benzene, Toluene, Ethyl Benzene, and Total Xylenes
Method SW-846 8260	Benzene, Toluene, Ethyl Benzene, and Total Xylenes
Method TX 1005	Total Petroleum Hydorcarbons

Certificate number T104704398-08-TX. Accreditation applies to solid and chemical materials and non-potable water matrices.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Haloacetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Received by OCD: 8/31/2022 12:43:44 PM

Celey D.Keine

Celey D. Keene Lab Director/Quality Manager

# **N**Laboratories

87.2 %

70-130

#### Analytical Results For:

Yates Energy Petroleum Corp AMANDA TRUJILLO 105 S 4th Street Artesia NM, 88210 Fax To: (505) 748-4635

Received: 01/07/2011	Sampling Date:	01/06/2011
Reported: 01/14/2011	Sampling Type:	Soil
Project Name: ANADARKO PARDU BATTERY	Sampling Condition:	Cool & Intact
Project Number: NONE GIVEN	Sample Received By:	Jodi Henson
Project Location: NOT GIVEN		

#### Sample ID: WEST 4' BGS (H100047-01)

BTEX 8021B	mg/	kg	Analyze	d By: CMS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	01/12/2011	ND	1.72	86.1	2.00	5.22	
Toluene*	0.143	0.050	01/12/2011	ND	1.83	91.5	2.00	2.75	
Ethylbenzene*	<0.050	0.050	01/12/2011	ND	2.03	102	2.00	0.932	
Total Xylenes*	1.23	0.150	01/12/2011	ND	6.32	105	6.00	0.155	
Surrogate: 4-Bromofluorobenzene (PIL	124 %	6 70-130	S.						
Chloride, SM4500CI-B	mg/	kg	Analyze	d By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	16.0	16.0	01/10/2011	ND	432	108	400	3.64	
TPH 8015M	mg/	kg	Analyze	d By: AB					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	<10.0	10.0	01/12/2011	ND	250	100	250	4.12	
DRO >C10-C28	750	10.0	01/12/2011	ND	238	95.1	250	3.38	
Surrogate: 1-Chlorooctane	81.5	% 70-130							

#### Cardinal Laboratories

Surrogate: 1-Chlorooctadecane

PLEASE NOTE: Liability and Damages. Cardinal's lability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be lable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celevil Keine

Celey D. Keene, Lab Director/Quality Manager

\*=Accredited Analyte

Page 2 of 6

86.0 %

92.5 %

70-130

70-130

#### Analytical Results For:

Yates Energy Petroleum Corp AMANDA TRUJILLO 105 S 4th Street Artesia NM, 88210 Fax To: (505) 748-4635

Received:	01/07/2011	Sampling Date:	01/06/2011
Reported:	01/14/2011	Sampling Type:	Soil
Project Name:	ANADARKO PARDU BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	NOT GIVEN		

#### Sample ID: MIDDLE 4' BGS (H100047-02)

BTEX 8021B	mg/	kg	Analyze	d By: CMS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	01/12/2011	ND	1.72	86.1	2.00	5.22	
Toluene*	0.351	0.050	01/12/2011	ND	1.83	91.5	2.00	2,75	
Ethylbenzene*	0.261	0.050	01/12/2011	ND	2.03	102	2.00	0.932	
Total Xylenes*	2,24	0.150	01/12/2011	ND	6,32	105	6.00	0.155	
Surrogate: 4-Bromofluorobenzene (PIL	114 9	% 70-130							
Chloride, SM4500Cl-B	mg/	kg	Analyze	d By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	01/10/2011	ND	432	108	400	3.64	
TPH 8015M	mg/	kg	Analyze	d By: AB					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	51,5	10.0	01/12/2011	ND	250	100	250	4.12	
DRO >C10-C28	3840	100	01/12/2011	ND	238	95.1	250	3.38	

#### Cardinal Laboratories

Surrogate: 1-Chlorooctane

Surrogate: 1-Chlorooctadecane

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any daim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successons arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal laboratories.

Celey D.Keine

Celey D. Keene, Lab Director/Quality Manager

Page 3 of 6

\*=Accredited Analyte

Released to Imaging: 3/7/2023 12:58:06 PM

#### Analytical Results For:

Yates Energy Petroleum Corp AMANDA TRUJILLO 105 S 4th Street Artesia NM, 88210 Fax To: (505) 748-4635

Received:	01/07/2011	Sampling Date:	01/06/2011
Reported:	01/14/2011	Sampling Type:	Soil
Project Name:	ANADARKO PARDU BATTERY	Sampling Condition:	Cool & Intact
Project Number:	NONE GIVEN	Sample Received By:	Jodi Henson
Project Location:	NOT GIVEN		

#### Sample ID: EAST 4' BGS (H100047-03)

BTEX 8021B	mg,	/kg	Analyze	d By: CMS					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	01/12/2011	ND	1.72	86.1	2.00	5.22	
Toluene*	0.120	0.050	01/12/2011	ND	1.83	91.5	2.00	2.75	
Ethylbenzene*	0.159	0.050	01/12/2011	ND	2.03	102	2.00	0.932	
Total Xylenes*	1,49	0.150	01/12/2011	ND	6.32	105	6.00	0.155	
Surrogate: 4-Bromofluorobenzene (PIL	128	% 70-130							
Chloride, SM4500CI-B	mg,	/kg	Analyze	d By: HM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	<16.0	16.0	01/10/2011	ND	432	108	400	3.64	
TPH 8015M	mg,	/kg	Analyze	d By: AB					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10	35.2	10.0	01/12/2011	ND	250	100	250	4.12	
DRO >C10-C28	1980	10.0	01/12/2011	ND	238	95.1	250	3.38	
Surrogate: 1-Chlorooctane	85.4	% 70-130							
Surrogate: 1-Chlorooctadecane	82.8	% 70-130							

#### Cardinal Laboratories

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any daim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for inodental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celevi Vene

Celey D. Keene, Lab Director/Quality Manager

\*=Accredited Analyte

Page 4 of 6

PHONE (575) 393-2326 ° 101 E. MARLAND ° HOBBS, NM 88240

#### **Notes and Definitions**

S-04	The surrogate recovery for this sample is outside of established control limits due to a sample matrix effect.
ND	Analyte NOT DETECTED at or above the reporting limit
RPD	Relative Percent Difference
**	Samples not received at proper temperature of 6°C or below.
***	Insufficient time to reach temperature.
-	Chloride by SM4500CI-B does not require samples be received at or below 6°C
	Samples reported on an as received basis (wet) unless otherwise noted on report

#### Cardinal Laboratories

#### \*=Accredited Analyte

Released to Imaging: 3/7/2023 12:58:06 PM

PLEASE NOTE: Liability and Damages. Cardinal's lability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be lable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of the services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise. Results relate only to the samples identified above. This report shall not be reproduced except in full with written approval of Cardinal Laboratories.

Celevi Tune

Celey D. Keene, Lab Director/Quality Manager

Page 5 of 6



Ā

Released to Imaging: 3/7/2023 12:58:06 PM



Anadarko Pardue Farms ANQ Com #1 Closure Report #nMLB1031337060



August 30, 2022

# Appendix E Current C-141 Closure

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Page 28 of 31

Incident ID	nMLB1031337060
District RP	2RP-468
Facility ID	
Application ID	

#### **Release Notification**

#### **Responsible Party**

Responsible Party EOG Resources, Inc.	OGRID 7377	
Contact Name Chase Settle	Contact Telephone 575-748-1471	
Contact email Chase_Settle@eogresources.com	Incident # (assigned by OCD) nMLB1031337060	
Contact mailing address 104 S. 4th Street, Artesia, NM 88210		

#### **Location of Release Source**

Latitude 32.45146

Longitude	-104.48801
aimal degrees to 5 deai	mal places)

(NAD 83 in decimal degrees to 5 decimal places)

Site Name Anadarko Pardue Farms ANQ Com #1	Site Type Battery
Date Release Discovered 09/07/2010	API# (if applicable) <b>30-015-22212</b>

Unit Le	tter Section	Township	Range	County
F	27	21S	24E	Eddy

Surface Owner: State Federal Tribal Private (Name: Pardue & Joyce

#### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls) 18	Volume Recovered (bbls) 10
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
Cause of Release Plea	se refer to the original C-141 for details of 2RP	-468.

Page	2
1 age	~

#### **Oil Conservation Division**

Incident ID	nMLB1031337060
District RP	2RP-468
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by	
19.15.29.7(A) NMAC?	
🗌 Yes 🔽 No	
If YES, was immediate no	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

#### **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

 $\checkmark$  The source of the release has been stopped.

 $\bigvee$  The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Chase Settle

Signature: Chase Settle

Title: Rep Safety & Environmental Sr Date: 08/30/2022

\_\_\_\_\_

email: Chase Settle@eogresources.com

Telephone: 575-748-1471

**OCD Only** 

Received by:

Date:

Page 6

Oil Conservation Division

Incident ID	nMLB1031337060
District RP	2RP-468
Facility ID	
Application ID	

Page 30 of 31

#### Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report. A scaled site and sampling diagram as described in 19.15.29.11 NMAC Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection) Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)  $\checkmark$  Description of remediation activities I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete. 
 Printed Name:
 Chase Settle
 Title:
 Rep Safety & Environmental Sr

 Signature:
 Chase Settle
 Date:
 08/30/2022
 email: Chase\_Settle@eogresources.com Telephone: 575-748-1471 **OCD Only** Date: 8/31/2022 Received by: OCD Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations. Closure Approved by: <u>Ashley Maxwell</u> Date: <u>3/7/2023</u> Title: Environm Printed Name: Ashley Maxwell Title: Environmental Specialist

.

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	139879
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By		Condition Date
amaxwell	None	3/7/2023

Page 31 of 31

.

Action 139879