District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

## **Release Notification and Corrective Action**

Name of Company OXY USA Inc.		OPERA'	ГOR	<b>⊠</b> Init	ial Report	$\boxtimes$	Final Report	
Facility Name Bravo Dome Gathering System	Name of Company OXY USA Inc. Contact Eric Maestas				-			
Surface Owner State Libby								
Unit Letter	Facility Name Bravo Dome Gathering System	Facility Typ	e Carbon Dioxi	de Gathering Sy	stem			
Unit Letter   Section   Township   Range   Feet from the   North/South Line   Feet from the   East/West Line   County	Surface Owner State Libby Mineral Owner	r State Libby		API N	API No.30-021-20418			
LatitudeN 35 54.7360LongitudeW -103 34.4189								
Latitude	Unit Letter   Section   Township   Range   Feet from the   No	rth/South Line	Feet from the	East/West Line	County			
NATURE OF RELEASE  Type of Release Carbon Dioxide Gas  Volume of Release 620MCF  Volume Recovered None  Source of Release Pipeline Vent  Date and Hour of Occurrence (6/16/2015 9:00 AM	G 6 19 32 1700	South 1700		West	West Harding			
Type of Release Carbon Dioxide Gas  Source of Release Pipeline Vent  Date and Hour of Occurrence (6/16/2015 9:00 AM  Was Immediate Notice Given?  Mes Immediate Notice Given?  Yes No Not Required  By Whom? Eric Maestas  Date and Hour 6/16/2015 9:00 AM  Was a Watercourse Reached?  Yes No  If YES, Volume Impacting the Watercourse.  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.  Describe Area Affected and Cleanup Action Taken.*  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health								
Source of Release Pipeline Vent    Date and Hour of Occurrence   6/16/2015 9:00 AM								
Was Immediate Notice Given?  Was Immediate Notice Given?  Yes No Not Required  By Whom? Eric Maestas  Date and Hour 6/16/2015 11:20 AM  Was a Watercourse Reached?  Yes No  If YES, Volume Impacting the Watercourse.  If YES, Volume Impacting the Watercourse.  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.  Describe Area Affected and Cleanup Action Taken.*  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health			-+					
By Whom? Eric Maestas  Date and Hour 6/16/2015 11:20 AM  Was a Watercourse Reached?  Yes No  If YES, Volume Impacting the Watercourse.  Describe Cause of Problem and Remedial Action Taken.*  Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.  Describe Area Affected and Cleanup Action Taken.*  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health		4						
Was a Watercourse Reached?  Yes No  If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.*  Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.  Describe Area Affected and Cleanup Action Taken.*  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health	Was Immediate Notice Given? If YES, To Whom?							
If a Watercourse was Impacted, Describe Fully.*  Describe Cause of Problem and Remedial Action Taken.* Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.  Describe Area Affected and Cleanup Action Taken.*  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health								
Describe Cause of Problem and Remedial Action Taken.* Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipeline was depressurized and repaired.  Describe Area Affected and Cleanup Action Taken.*  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health		If YES, Vo	If YES, Volume Impacting the Watercourse.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health	Describe Cause of Problem and Remedial Action Taken.* Internal Corrosion on 24" Steel Pipeline developing pinhole leak. Pipel	line was depress	urized and repaire	d.	، بیا	FIVED OCD		
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other	I hereby certify that the information given above is true and complete to regulations all operators are required to report and/or file certain release public health or the environment. The acceptance of a C-141 report by should their operations have failed to adequately investigate and remed	e notifications as the NMOCD m iate contaminati	nd perform correct arked as "Final Re on that pose a thre	tive actions for rel eport" does not rel eat to ground wate	leases which lieve the oper r. surface wa	may en ator of ter. hur	danger liability nan health	
federal, state, or local laws and/or regulations.	federal, state, or local laws and/or regulations.	T GOES HOL TELLET					oniei	
Signature: Approved by Environmental Specialist: Approved by Environmental Specialist:		Approved by	Das					
Title: HFS Coordinator Approved by Environmental Specialist:  Approved by Environmental Speciali		01/20/15						
E-mail Address: CCIL - Maestus @ OKy. Com Conditions of Approval:	E-mail Address: EriL - Maestus @ Oxy. Com			· •				
Date: //6/Z0/5 Phone: (575) 420-7825 N/A Attach Additional Sheets If Necessary			N/A					

## Lowe, Leonard, EMNRD

From: Eric\_Maestas@oxy.com

**Sent:** Tuesday, June 16, 2015 11:21 AM

To: Lowe, Leonard, EMNRD; Sanchez, Daniel J., EMNRD; Eddie\_Corley@oxy.com;

Mike\_Kelly2@oxy.com; Charles\_Terry@oxy.com

**Cc:** Lynn\_Clay@oxy.com; Sharon\_Reid@oxy.com; Lloyd\_Stark@oxy.com;

Bradey\_Holland@oxy.com; Eric\_Maestas@oxy.com; Tommy\_Pugh@oxy.com

**Subject:** Reportable Vent NW Leg 10 Bravo Dome

We will be venting down the NW portion of Leg 10 to repair a leak on the 24" steel Pipeline. The reportable Vent Volume for this is 620 MCF.

Thank you,

Eric Maestas HES Ops Coordinator OXY Bravo Dome Sheep Mountain cell: (575)420-7825