Submit I Copy To Appropriate District

1625 N. French Dr., Hobbs, NM 88240

District I ~ (575) 393-6161

03/31/21

DATE

Released to Imaging: 4/7/2021 4:12:12 PM

Form C-103

Revised July 18, 2013

WELL API NO.

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Date    NOTICE OF INTENTION TO:	Larra
Santa Fe, NM 87505   G. State Oil & Gas L B-3623-1	FEE
1220 S.S. Francis Dr., Santa Fe, NM   B-3823-1	
SUNDRY NOTICES AND REPORTS ON WELLS   To Lease Name or Unifice the processor of the proce	
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PRMIT" ("FORM C-101) FOR SUCH	Init Agreement Name
1. Type of Well: Oil Well	
2. Name of Operator Apache Corporation 3. Address of Operator 303 Veterans Airpark Lane. Ste. 3000. Midland. TX 79705  4. Well Location Unit Letter B: 1300 feet from the N line and 2345 feet from the Section 5 Township 185 Range 28E NMPM CO  11. Elevation (Show whether DR, RKB, RT, GR, etc.) 365 GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Date of Notice of Notice, Report or Other Date of Notice of Not	724
3. Address of Operator  3.03 Veterans Airpark Lane. Ste. 3000. Midland, TX 79705  4. Well Location Unit Letter B: 1300 feet from the N line and 2345 feet from the Section 5 Township 18S Range 28E NMPM CONTROL OF INTENTION TO: SUBSEQUENT REPORT OF INTENTION TO: SUBSEQUENT REPORT REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CASING/CEMENT JOB CASING/CEMENT JOB CASING/CEMENT JOB CASING/CEMENT JOB CASING/CEMENT JOB CONTROL OF STATING any proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, in of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  1. 03/29/21 Port at 3348's sqc2'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg. 2. 03/30/21 Port at 3348's sqc2'd 90 sx class C cmt. Tag TOC at 1500' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt at 5505' Tag TOC at 1500' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report on the found at OCD Web. Www.emnrd.state.m.)	:12A
4. Well Location Unit Letter B : 1300 feet from the N line and 2345 feet from the Section 5 Township 185 Range 28E NMPM C	
4. Well Location Unit Letter B: 1300 feet from the N line and 2345 feet from the Section 5 Township 18S Range 28E NMPM CO  11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3697 GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Dax NOTICE OF INTENTION TO: SUBSEQUENT REPORT REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAUL OR ALTER CASING MULTIPLE COMPL COMMENCE DRILLING OPNS. PAUL OR ALTER CASING MULTIPLE COMPL COMMENCE DRILLING OPNS. PAUL OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, it of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  1. 03/29/21 Perf at 3348* sqc19 09 sx class C cmt. Tag TOC at 5600* inside 5 1/2 csg. 2. 03/30/21 Perf at 3348* sqc19 09 sx class C cmt. Tag TOC at 3000* inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248* to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of the found at OCD Wet www.emnrd.state.nm	ildcat
Section 5 Township 18S Range 28E NMPM CO 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3685 CGR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da NOTICE OF INTENTION TO: SUBSEQUENT REPORT REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUC OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDON SYSTEM OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, i of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  13. Describe proposed or completion or recompletion. (Clearly state all pertinent details, and give pertinent dates, i of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  13. Describe proposed or completion. (Clearly state all pertinent details, and give pertinent dates, i of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  13. Describe proposed or completion or recompletion.  14. O3/29/21 3504 25 sx class C cmt at 3855'. Tag TOC at 3500' inside 5 1/2 csg.  15. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  26. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  27. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  28. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  29. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' ins	
Section 5 Township 18S Range 28E NMPM CO 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3685 CGR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Da NOTICE OF INTENTION TO: SUBSEQUENT REPORT REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUC OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDON SYSTEM OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, i of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  13. Describe proposed or completion or recompletion. (Clearly state all pertinent details, and give pertinent dates, i of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  13. Describe proposed or completion. (Clearly state all pertinent details, and give pertinent dates, i of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  13. Describe proposed or completion or recompletion.  14. O3/29/21 3504 25 sx class C cmt at 3855'. Tag TOC at 3500' inside 5 1/2 csg.  15. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  26. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  27. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  28. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  29. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' inside 5 1/2 csg.  20. O3/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3500' ins	the E line
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3652 GR  12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Date	County Eddy
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Date NOTICE OF INTENTION TO:    NOTICE OF INTENTION TO:   SUBSEQUENT REPORT	Eddy Eddy
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   AL  TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   P./  PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB   CASING/CEMENT JOB    OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, it of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach welling proposed completion or recompletion.  1. 03/29/21 Spot 25 sx class C cmt at 5855'. Tag TOC at 5600' inside 5 1/2 csg. 2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retainer (Subsequent Report of be found at OCD Web. www.emnrd.state.nm.)	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   AL TEMPORARILY ABANDON   CHANGE PLANS   COMMENCE DRILLING OPNS.   P./ PULL OR ALTER CASING   MULTIPLE COMPL   CASING/CEMENT JOB    DOWNHOLE COMMINGLE    CLOSED-LOOP SYSTEM   OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, i of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach welli proposed completion or recompletion.  1. 03/29/21 Spot 25 sx class C cmt at 5855' Tag TOC at 5600' inside 5 1/2 csg. 2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retaine (Subsequent Report of be found at OCD Web. www.emnrd.state.nm.)	
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILLING OPNS. PAUL OR ALTER CASING  MULTIPLE COMPL  CASING/CEMENT JOB  CASING/CEMENT JOB  TO CHARGE PLANS  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, is of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  1. 03/29/21 Spot 25 sx class C cmt at 5855'. Tag TOC at 5600' inside 5 1/2 csg. 2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web www.emnrd.state.nm).	ata
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PPULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB COMMENCE COMMINGLE CLOSED-LOOP SYSTEM OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, it of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach welling proposed completion or recompletion.  1. 03/29/21 Spot 25 sx class C cmt at 5855'. Tag TOC at 5600' inside 5 1/2 csg. 2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web www.emnrd.state.nm	ORT OF:
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB  DOWNHOLE COMMINGLE  CLOSED-LOOP SYSTEM OTHER:  Attach welliproposed completion or recompletion.  MAC: For Multiple Completions: Attach welliproposed completion or recompletion.  ATTACH STATE OF THE POWNER AND	AND A
DOWNHOLE COMMINGLE  CLOSED-LOOP SYSTEM  OTHER:  OTHER:	AND A
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, is of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  1. 03/29/21 Spot 25 sx class C cmt at 5855'. Tag TOC at 5600' inside 5 1/2 csg.  2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg.  3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web www.emnrd.state.nm).	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, is of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  1. 03/29/21 Spot 25 sx class C cmt at 5855', Tag TOC at 5600' inside 5 1/2 csg. 2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web.).	10 mm
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach well proposed completion or recompletion.  **TH con wide Tag USP**  1. 03/29/21 Spot 25 sx class C cmt at 5855'. Tag TOC at 5600' inside 5 1/2 csg.  2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg.  3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web www.emnrd.state.nm).	:
proposed completion or recompletion.  MZEN RTH coun wide Tag USB?  1. 03/29/21 Spot 25 sx class C cmt at 5855'. Tag TOC at 5600' inside 5 1/2 csg.  2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg.  3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web www.emnrd.state.nm).	
2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Websel www.emnrd.state.nm).	ioore diagram or
2. 03/30/21 Perf at 3348' sqz'd 90 sx class C cmt. Tag TOC at 3000' inside 5 1/2 csg. Spot 25 sx class C cmt at 2099'. Tag TOC at 1825' inside 5 1/2 csg. 3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web www.emnrd.state.nm).	
Tag TOC at 1825' inside 5 1/2 csg.  3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Webstern Marker). Subsequent Report of be found at OCD Webstern Marker. P&A complete.	
3. 03/31/21 Circulate 135 sx class C cmt from 1248' to surface inside 5 1/2 csg. Cut off wellhead and remove. Install dry hole marker. P&A complete.  Approved for plugging under bond is retained (Subsequent Report of be found at OCD Webselm under State.nm)	
Approved for plugging under bond is retained (Subsequent Report of be found at OCD Web www.emnrd.state.nm	
under bond is retaine (Subsequent Report of be found at OCD Web www.emnrd.state.nm	
under bond is retaine (Subsequent Report of be found at OCD Web www.emnrd.state.nm	
(Subsequent Report of be found at OCD Web www.emnrd.state.nm	ng of well bore only. Liability
be found at OCD Web www.emnrd.state.nm	ed pending receipt of C-103
www.emnrd.state.nm	
Spud Date: Rig Release Date:	
pud Date: Rig Release Date:	1
	74.0
hereby certify that the information above is true and complete to the best of my knowledge and belief.	

State of New Mexico

Energy, Minerals and Natural Resources

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 23041

## **CONDITIONS OF APPROVAL**

Operator	:	_	OGRID:	Action Number:	Action Type:
	APACHE CORPORATION	303 Veterans Airpark Ln	873	23041	C-103P
#1000	Midland, TX79705				

OCD Reviewer	Condition
gcordero	None