

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: GISSLER B Well Location: T17S / R30E / SEC 11 / County or Parish/State: EDDY /

NWSE /

...

NM

Well Number: 55 Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM2748 Unit or CA Name: Unit or CA Number:

US Well Number: 300153724300S1 **Well Status:** Producing Oil Well **Operator:** EOG RESOURCES

INCORPORATED

Accepted for record – NMOCD gc 6/02/2021

Notice of Intent

Type of Submission: Notice of Intent

Type of Action Plug and Abandonment

Date Sundry Submitted: 05/20/2021 Time Sundry Submitted: 09:51

Date proposed operation will begin: 05/28/2021

Procedure Description: Please see attached. Thank you.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Gissler_B_55_5_20_21_20210520095126.pdf

Conditions of Approval

Specialist Review

Gissler_B_55_Sundry_ID_2388209_P_A_20210522172417.pdf

Page 1 of 2

Well Location: T17S / R30E / SEC 11 /

NWSE /

County or Parish/State: Page 2 of

Well Number: 55

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMNM2748

Unit or CA Name:

Unit or CA Number:

US Well Number: 300153724300S1

Well Status: Producing Oil Well

Operator: EOG RESOURCES

INCORPORATED

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: TINA HUERTA Signed on: MAY 20, 2021 09:51 AM

Name: EOG RESOURCES INCORPORATED

Title: Regulatory Specialist

Street Address: 104 SOUTH FOURTH STREET

City: Artesia State: NM

Phone: (575) 748-4168

Email address: tina_huerta@eogresources.com

Field Representative

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

BLM Point of Contact

BLM POC Name: LONG VO BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345972 BLM POC Email Address: lvo@blm.gov

Disposition: Approved Disposition Date: 05/22/2021

Signature: Long Vo

Page 2 of 2

Prairie Chicken

APZ: 30-015-37243

EOG Resources, Inc. plans to plug and abandon this well as follows:

- 1. MIRU all safety equipment as needed. NU BOP. POOH with production equipment.
- 2. Set a CIBP at 2786 ft with 56 sx Class C cement on top to 2233 ft. WOC and tag. This will cover Leak test CIBP
- Grayburg Jackson perfs, San Andres, Grayburg and Queen tops.

 3. Perforate at 1739 ft. Spot a 25 50 Class C cement plug from 1739 ft 1344 ft. This will cover Seven Rivers top. 6.544, Yetes
- 4. Perforate at 506 ft. Spot a 52 sx Class C cement plug from 506 ft up to surface. WOC and tag. Back fill as needed. Verific surface
- 5. Cut off wellhead and install dry hole marker. Clean location as per regulated.

Wellbore schematics attached

Sx Cmt Circ/TOC	Gis	Gissler B #55 Proposed	Sec	-TWN-RNG	Sec-TWN-RNG: Sec. 11-17S-30E FOOTAGES: 2475' FSL & 2475' FEL	30E 2475' FEL		API:	API: 30-015-37243 GL: 3729		
A A A A A A A A A A	Plug 3: Surface plug							KB:			
The control of the			0								
Part	The second		CASIN	G DE I AIL					об натачения выполнения от пределения выполнения выстительным выполнения выпо		
FOREMATION TOPS S172 15.5 J-555 O 4.492 1100 Circle Circ			#	HOLE SIZE	SIZE	WGHT	GRADE	Тор		Circ/TOC	TOC Method
PPITD: 3.545 MD PART PORMATION 10			4	12 1/4	8 2/8	24	J-55	0	-	Circ	
PBTD: 3,545 MD PBTD: 3,542 MD PBTD: 3,542 MD PBTD: 3,545 MD PBTD			œ	7 7/8	5 1/2	15.5	J-55	0		Circ	
FORMATION TOPS	·										
Formation Top		W	FORMA	VIION TOPS							
Salt 456 Salt 4442 Salt 452 Salt 456 Sal					Formation	Тор			evited data participation of the state of th	Top	
Vales Vales 1414	Divis 9. Cough Division to				Salt	45	9		- Anna Carlo de Carlo		-
TUBING DETAIL # Joints Description Length Perforation Detail A Jackson 4,335 4,335 (3787) Greyburg 3,640 4,067 (3787) Greyburg 3,640 4,067 (3787) Creyburg Creyburg 3,640 3,757 (3787) Plugs Plugs Plugs Plugs Plugs Plugs TTOP A492 MD Perforation Detail Perforation Detail # SX Class Top A Jackson 2,836 3,399 (3787) TTOP 4482 MD Perforation Detail # SX Class Top Plugs TTOP A492 MD Perforation Detail # SX Class Top A Jackson C NNN NAM Plugs TTOP December Inv Name of England TTOP A492 MD Perforation Detail # NAM Province of England TTOP A492 MD Perforation Detail # SX Class Top # SX Class Top # SX Class Top # NNN NAM Province England TTOP Browned Inv Name of England TTOP A492 MD	do vinera rob				Yates	141	4		San Andres	3007	-
TUBING DETAIL # Joints Description Length # Joints Description Length # Joints Description Length # Greyburg # Greyburg # Greyburg Greyburg					Seven Rivers	168	6				
TUBING DETAIL # Joints Description Length Perforation Detail					Queen	229	10				
TUBING DETAIL # Joints Description Length Perforation Detail	- Control of the Cont										
# Joints Description Length Perforation Detail Formation Top Bottom 4,352 4,365 Bottom 4,067 Greyburg C. Jackson Jackso			TUBING	DETAIL							
Perforation Detail Formation Detail Formation Detail Formation Detail Formation Detail Formation Top Bottom A Greyburg B Jackson C Jac			#	Joints	Description	Length	go	Ω	-	Top (ftKB):	Btm (#KB
Perforation Detail Formation Top Bottom Greyburg A Jackson 4,332 4,385 Greyburg C Jackson 3,640 4,067 Greyburg C Jackson 3,640 3,757 C Jackson 3,640 3,757 C Jackson 2,836 3,399 Plugs # SX Class Top PBTD: 3,545 MD PPTD: 4,492 MD Proposed have Notwell Education					2-7/8" Tubing & SN	@ 3418					3417
Performation Top Bottom Formation Top Bottom Formation Top Bottom 4,332 4,365											
Formation Top Bottom	Plug 1: CIBP + Greyburg		remora	and the same							
A Jackson 4,332 4,365 B Jackson 4,040 4,067 C Greyburg C Jackson 3,640 3,757 C Greyburg C Jackson 3,640 3,757 C Greyburg C Jackson 3,640 3,757 Plugs # SX Class Top PBTD: 3,545 MD PBTD: 3,545 MD PREPRINCE BLACKSON 2,836 C C MN 1844 TD: 4,492 MD PREPRINCE BLACKSON C MN 1844	Jackson perfs + San Andres				Тор	Bottom	Tre	atment			
B Jackson 4,040 4,067 C Jackson 3,640 3,757 C Greyburg C Jackson 3,399 D Jackson 2,836 3,399 Plugs # SX Class Top PBTD: 3,545 MD TD: 4,492 MD Prepared by Modern England Prepared by Modern England Prepared by Modern Modern Englan	dot		and the same of th	Greyburg Jackson Greyburg	4,332				1000 gals 15% acid	doį	
C Jackson 3,640 3,757				Jackson	4,040				4000 dale 15% acid	doi	
B PBTD: 3,545 MD TD: 4,492 MD TD: 4,492 MD				Greyburg	0700				1000 State 10.78 acro	200	
B PBTD: 3,545 MD TD: 4,492 MD D Greyburg Careyburg Careyburg D Jackson Cares Cass Top Cass T				100000	3,640	-		Personal Security Sec	2500 gals 15% acid	doj	
B PBTD: 3,545 MD TD: 4,492 MD TD: 4,492 MD PPTD: 9,492 MD PPTD: 9,644 PD PPTD: 9,645 MD PPTD: 9,644 PD PPTD: 9,645 MD PPTD: 9,645 MD	CIBP @ 3550' w/30' cement		The second secon	Greyburg Jackson	2,836		2500 gals 15%	NEFE ac	cid/slick water frac 1/3	163,711 gals wa 40/70 sand	ater w/20,180
Plugs											
Pilugs	CIBP @ 3960' w/30' cement										
# SX Class Top Bottom			Plugs								
B PBTD: 3,545 MD TD: 4,492 MD 1 56 C 2.233 2.786 553 Andreas top + Grayburg top + Queen top C 1739 395 Seven Rivers top C 1739 1			#	SX	Class	Top	Bottom		otes		Tag
3,545 MD Prepared by Many E E4004	CIBP @4250' w/30' cement		-	56	υ	2,233		553 A	BP + Greyburg Jackson p	erfs + San	>
3,545 MD Prepared by Manual E (1907)			2	99%	O			395 Sc	even Rivers top		z
3,545 MD Prenared hv. Maxwi E E40004			67	52	O	, 0		506 S	off top + Casing shoe + Su	ríace oluo	>
3,545 MD 4,492 MD										n	-
4,492 MD		3,545									
		4,492		Prenared	hv. Naomi E 5/10/24				refrestive de l'écrete de resultant en action de l'écret grandes de comma de la tende amount de la		

Perf D

Perf

Perf B

Perf A

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of
 Operations must include adequate measures for stabilization and reclamation of disturbed lands.
 Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD
 process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2720

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 29203

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	29203
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/2/2021