Form 3160-5


UNITED STATES


FORM APPROVED

(June 2019) D	EPARTMENT OF THE INTERIOR	Expires: October 31, 2021		
	REAU OF LAND MANAGEMEN		5. Lease Serial No.	IMNM97874
Do not use this	NOTICES AND REPORTS ON Soform for proposals to drill or I. Use Form 3160-3 (APD) for se	to re-enter an	6. If Indian, Allottee	or Tribe Name
SUBMIT	IN TRIPLICATE - Other instructions on pa	age 2	7. If Unit of CA/Agree	ement, Name and/or No.
1. Type of Well Oil Well Ga	s Well Other		8. Well Name and No	BEAR BRYANT 31 FEDERAL/1
2. Name of Operator CIMAREX EN	NERGY COMPANY OF COLORADO		9. API Well No. 3001	534906
3a. Address 600 N MARIENFELD	The state of the s	o. (include area code) 1800	10. Field and Pool or E EMPIRE/E EMP	Exploratory Area
4. Location of Well (Footage, Sec., 3 SEC 31/T16S/R29E/NMP	T.,R.,M., or Survey Description)		11. Country or Parish EDDY/NM	, State
12. Cl	HECK THE APPROPRIATE BOX(ES) TO I	NDICATE NATURE OF NOT	ICE, REPORT OR OT	HER DATA
TYPE OF SUBMISSION		TYPE OF AC	TION	
✓ Notice of Intent Subsequent Report Final Abandonment Notice	Alter Casing Hy Casing Repair Ne Change Plans Plu	draulic Fracturing Recolution Recolution Recolution Recolution Tem	luction (Start/Resume) lamation omplete porarily Abandon er Disposal	Water Shut-Off Well Integrity ✓ Other
the Bond under which the work completion of the involved oper completed. Final Abandonment is ready for final inspection.) 1) SET 4-1/2" CIBP @ 6,70 6,700'-6,495' (4-1/2" LNR. TCLASS "C" CMT. @ 4,208'-TOC. 5) CIRC. TO SURF. (3' B.G.L.; WELD ON STEEI DURING THIS PROCEDUR REQUIRED DISPOSAL, PE		n file with BLM/BIA. Required completion or recompletion in a nts, including reclamation, have 4-1/2" CIBP X CSG.; PUMFAT. @ 6,120'-5,960' (T/ABO) LASS "C" CMT. @ 3,165'-3, TYATES, 13-3/8" CSG. SHOOLE MARKER.	subsequent reports more new interval, a Form 3 re been completed and P (25) SXS. CLASS "); WOC X TAG TOC. 1,035' (9-5/8" CSG. SIDE). 6) DIG OUT X C	ast be filed within 30 days following 160-4 must be filed once testing has been the operator has detennined that the site C" CMT. @ 3) PUMP (25) SXS. HOE); WOC X TAG
	g is true and correct. Name (Printed/Typed)	Agent		
DAVID EYLER / Ph: (432) 687-3		Title		
Signature		Date	01/07/2	022
oted for record – NMOCD gc 2/8	THE SPACE FOR FEI	DERAL OR STATE OF	ICE USE	
Approved by LONG VO / Ph: (575) 234-5972	/ Approved	Petroleum Enç		02/07/2022 Date
	cached. Approval of this notice does not warra or equitable title to those rights in the subject conduct operations thereon.			
				

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)





PLUG AND ABANDONMENT **CONDITIONS OF APPROVAL**

OPERATOR'S NAME:

Cimarex Energy Company of Colorado

LEASE NO .: |

NMNM97874

WELL NAME & NO.:

Bear Bryant 31 Federal 1

US Well Number:

3001534906

LOCATION: | Section 31, T.16 S., R.29 E., NMPM

COUNTY: | Eddy County, New Mexico

6814

- 1) SET 4-1/2" CIBP @ 6,700"; CIRC. WELL W/ M.L.F.; PRES. TEST 4-1/2" CIBP X CSG.; PUMP (2/5) SXS. CLASS "C" CMT. @ 6,700' 6,495' (4-1/2" LNR. TOP). 6814' to 6495' WOC &TH GT
- 2) PUMP (25) SXS. CLASS "C" CMT. @ 6,120'-5,960' (T/ABO); WOC X TAG TOC. (6040' to 5429')
- 3) PUMP (25) SXS. CLASS "C" CMT. @ 4,208' 4,068' (T/GLOR.). (4188' to 4046')
- 4) PUMP (25) SXS. CLASS "C" CMT. @ 3,165'-3,035' (9-5/8" CSG. SHOE); WOC X TAG TOC.
- 5) CIRC. TO SURF. (105) SXS. CLASS "C" CMT. @ 863'-3' (T/YATES, 13-3/8" CSG. SHOE).
- 6) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE

DURING THIS PROCEDURE WE PLAN TO USE THE CLOSED-LOOP SYSTEM W/ A STEEL TANK AND HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

Approval Subject to General Requirements and Special Stipulations Attached

- No more than 3000 feet between cement plugs in cased hole.
- Wait on Cement and Tag Top of Cement Requirement:
 - 1. Shoe, Top of Salt, Base of Salt, DV tool, Perforate and Squeeze, Open Perforation.
 - 2. Formation plug is optional if a solid base is established and confirmed.

Sundry ID: 2651692

Sundry ID	2651692	2					
Plug Type	Ton				T		Philosoppia
Surface Plug	Тор	Bottom	Length	Tag	Sacks	Notes	
Shoe Plug	0.00 157.00		and the last of th	Tag/Verify			Territoria de la constantina della constantina d
Top of Salt @ 345	291.55		- Company of the Comp	Tag/Verify			
Base of Salt @ 640	583.60			Tag/Verify			_
	300.00	030.00	100.40	Tag/Verify			
				base no			
				need to			
				Tag			
				(CIBP			-
				present			-
				and/or			To annual to the last of the l
				Mechanic			- Indiana
				al Integrity			-
				Test), If			-
				Perf &			Distance and Dista
				Sqz then			Politika
				Tag, Leak			Name of the Owner, where
				Test all			
				CIBP if no		Spot from 863' to	
ates @ 813	754.87	863.00		Open	S	surface. Verify at	The second
	.01.07	000.00	108.13	Perforatio		Surface.	and the same
noe Plug	3050.00	3150.00	100 00	Γag/Verify	25 000	Spot from 3150' to	The same of
	Tributania a			f solid		050' WOC and Tag	
				ase no		3165 to 3035	10
				eed to		, , , , ,	-
			1	ag			
			1	CIBP	and the same of th		
			100	resent	-		
				nd/or			
				lechanic			
				Integrity			
				est), If			
				erf &			
				gz then			
				ag, Leak est all			
			lc:	RP if no			
rieta @ 4138	4046.62		CI	BP if no	Qn	ot from 4188' to	

The state of the s							
				If solid			
				base no			
				need to	8		
				Tag	anada ana		
				(CIBP			
		The state of the state of		present			The state of the s
				and/or			
			suring and a suring a	Mechani	i		
The state of the s				al Integri			
				Test), If	ity		and the state of t
				Perf &			To de la constitución de la cons
17 - 17 - 17 - 17 - 17 - 17 - 17 - 17 -				Sqz then			
And a second				Tag, Lea			
				Test all	"		
				CIBP if n			
ADO: DI				Open	U	0-215	
ABO in Plateform Shelf @ 6040	5929.60	6090.00	160.4	0 Perforation	25	Spot from 5929' to	
Shoe Plug	6495.00	6595.00		0 Tag/Verif		00 6090' 6096'	5929
				If solid	У		
				base no			
				need to			
				Tag			
				(CIBP			and a second sec
				present			A CONTRACTOR OF THE CONTRACTOR
				and/or			
			3	Mechanic			
				al Integrity			
				Test), If			
				Perf &			
				Sqz then			
				Tag, Leak			
				Test all		Leak Test CIBP,	
				CIBP if no		Spot from 6814' to	and the second s
CIBP Plug	6770.00	221111		Open		6495'. WOC and	larasione à las
	6779.00	6814.00		Perforatio	35.00	0 Tag	- I
			1	If solid			
and the state of t				base no			Michigan
The state of the s			- 1	need to			Proposition and Proposition an
				Tag			
			1	(CIBP			
				present			
				and/or			
				Mechanic			respondent and the second and the se
			5	al Integrity			and the same of th
				Γest), If			
			1	Perf &			
				Sqz then			The same of the sa
				ag, Leak			and the second
				est all			
			1,-	יו ממוי			i i
				IBP if no			
olfcamp @ 7135	7013 65 7	185 00)pen	del per de como misso que a que		
olfcamp @ 7135 rforations Plug (If No CIBP)	7013.65 7 7767.00 10	185.00		Open Perforatio		Not Necessary Not Necessary	

hoe Plug	10395.00	10285.00		Perforatio Tag/Verify	Not Necessary Not Necessary
orrow @ 10235	10082 65	10005.00		Open	
				CIBP if no	
				Test all	
				Tag, Leak	
				Sqz then	
			ra-ju-	Perf &	
				Test), If	
				al Integrity	
				Mechanic	
				and/or	
				present	
				Tag (CIBP	
			1	need to	
				base no	
				If solid	

No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs

Class H >7500'

Class C<7500'

Fluid used to mix the cement in R111P shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.

Critical, High, Medium, Secretary: Top of salt to surface if no salt take the deepest fresh water. R111P: 50' from bottom of salt to surface

Class C: 1.32 ft^3/sx Class H: 1.06 ft^3/sx

Onshore Order 2.III.G Drilling Abandonment Requirements: "All formations bearing usable-quality water, oil, gas, or geothermal resources, and/or a prospectively valuable deposit of minerals shall be

Cave Karst/Potash Cement	High Top	of Salt to surface
Shoe @	207.00 3100.00	KGP@ 68641
Shoe @ Shoe @	10445.00 10338.00	TOC @ 6545.00
Perforatons Top @	7817.00	Perforations 10073.00

CIBP @

6814.00

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 79563

CONDITIONS

Operator:	OGRID:
CIMAREX ENERGY CO. OF COLORADO	162683
600 N. Marienfeld Street	Action Number:
Midland, TX 79701	79563
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	2/8/2022