(June 2019)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

Expires: October 31, 20	OMB No. 1004-0137
	Expires: October 31, 20

### **SUNDRY NOTICES AND REPORTS ON WELLS**

),	Lease Serial No.	NMNM92160		
5	If Indian Allotte	or Tribe Name		

	form for proposals to drill or to re-e Use Form 3160-3 (APD) for such pr			
SUBMIT IN	TRIPLICATE - Other instructions on page 2	7. If Unit o	of CA/Agreemer	nt, Name and/or No.
1. Type of Well  Oil Well  Gas W		8. Well Na	me and No. CH	OSA DRAW 27 FEDERAL/3
2. Name of Operator CIMAREX ENE	RGY COMPANY OF COLORADO	9. API We	<sup>1 No.</sup> 3001537	180
	TREET SUITE 600, MIDL 3b. Phone No. (include		nd Pool or Expl	
OOO II IM II ILLO O	(432) 571-7800		lanos/WILDCA	τ
4. Location of Well (Footage, Sec., T., F.	R.,M., or Survey Description)	11. Countr	y or Parish, Stat	e
SEC 27/T25S/R26E/NMP		EDDY/N	IM	
12. CHE	CK THE APPROPRIATE BOX(ES) TO INDICAT	E NATURE OF NOTICE, REPO	RT OR OTHER	DATA
TYPE OF SUBMISSION		TYPE OF ACTION		
✓ Notice of Intent	Acidize Deepen Alter Casing Hydraulic F	Production (Star	t/Resume)	Water Shut-Off Well Integrity
Cubacquant Panart	Casing Repair New Constr	ruction Recomplete		Other
Subsequent Report	Change Plans Plug and Al	oandon Temporarily Ab	andon	
Final Abandonment Notice	Convert to Injection Plug Back	Water Disposal		
the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)  1) PUMP (60) SXS. CLASS H CMT. @ 8,706-8,497 (4-1/2 LNR.TOP, T/WLCP.); WOC X TAG TOC. 2) ATTEMPT TO CIRC. WELL W/ M.L.F. 3) PUMP (50) SXS. CLASS C CMT. @ 5,435-5,285 (T/BNSG.). 4) PUMP (60) SXS. CLASS C CMT. @ 2,879-2,715 (7 CSG.DAMAGE); WOC X TAG TOC. 5) PUMP (115) SXS. CLASS C CMT. @ 1,870-1,463 (T/DLWR., 9-5/8 CSG. SHOE, B/SALT, 7 DV TOOL); WOC X TAG TOC. 6) PUMP (35) SXS. CLASS C CMT. @ 1,073-973 (T/SALT); WOC X TAG TOC. 7) CIRC. (110) SXS. CLASS C CMT. @ 456-3 (13-3/8 CSG. SHOE). 8) DIG OUT X CUT OFF WELLHEAD 3 B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE A CLOSED-LOOP SYSTEM W/ A STEEL TANK X HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.				
14. I hereby certify that the foregoing is SARAH JORDAN / Ph: (432) 620-	42.657.3533 Inte		3/08/2 03/02/2023	3
	THE SPACE FOR FEDERA	L OR STATE OFICE US	Accepted Accepted	for record – NMOCD gc 3/9/2023
Approved by LONG VO / Ph: (575) 234-5972 / /	Approved	Petroleum Engineer Title	Date	01/30/2023
	shed. Approval of this notice does not warrant or	Office CARLSBAD		

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States

(Instructions on page 2)

which would entitle the applicant to conduct operations thereon.

any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Gas Well

(June 2019)

1. Type of Well

Oil Well

### UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

Е	expires: October 31, 2
5. Lease Serial No.	NINANINAO 24 GO

### SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

Other

NMNM92160
6. If Indian, Allottee or Tribe Name
 7. If Unit of CA/Agreement, Name and/or No.
 8. Well Name and No. CHOSA DRAW 27 FEDERAL/3
 CHOSA DRAW 27 FEDERAL/3

2. Name of Operator CIMAREX ENER	RGY COMPANY OF COLOR	RADO		9. API Well No. 30015	37180
3a. Address 600 N MARIENFELD STREET SUITE 600, MIDL 3b. Phone No. (include area code) (432) 571-7800		10. Field and Pool or Ex Los Medanos/WILD			
4. Location of Well (Footage, Sec., T.,R	.,M., or Survey Description)			11. Country or Parish, S	State
SEC 27/T25S/R26E/NMP				EDDY/NM	
12. CHE	CK THE APPROPRIATE BOX	K(ES) TO INDICATE NATURE	OF NOTI	CE, REPORT OR OTHI	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Produ	uction (Start/Resume)	Water Shut-Off
- Notice of Intent	Alter Casing	Hydraulic Fracturing	Recla	amation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Reco	mplete	Other .
Subsequent report	Change Plans	Plug and Abandon	Temp	oorarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Wate	r Disposal	

- 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)
  - 1) PUMP (60) SXS. CLASS H CMT. @ 8,706-8,497 (4-1/2 LNR.TOP, T/WLCP.); WOC X TAG TOC.
  - 2) ATTEMPT TO CIRC. WELL W/ M.L.F.
  - 3) PUMP (50) SXS. CLASS C CMT. @ 5,435-5,285 (T/BNSG.).
  - 4) PUMP (60) SXS. CLASS C CMT. @ 2,879-2,715 (7 CSG.DAMAGE); WOC X TAG TOC.
  - 5) PUMP (115) SXS. CLASS C CMT. @ 1,870-1,463 (T/DLWR., 9-5/8 CSG. SHOE, B/SALT, 7 DV TOOL); WOC X TAG TOC.
  - 6) PUMP (35) SXS. CLASS C CMT. @ 1,073-973 (T/SALT); WOC X TAG TOC.
  - 7) CIRC. (110) SXS. CLASS C CMT. @ 456-3 (13-3/8 CSG. SHOE).
  - 8) DIG OUT X CUT OFF WELLHEAD 3 B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER.


DURING THIS PROCEDURE WE PLAN TO USE A CLOSED-LOOP SYSTEM W/ A STEEL TANK X HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

14. I hereby certify that the foregoing is true and correct. Name ( <i>Printed/Typed</i> )  SARAH JORDAN / Ph: (432) 620-1909  432. 687. 3033	Regulatory Analyst			
DAVID A. EYLER	AGENT 03/08/23 Date 03/02/2023			
THE SPACE FOR FEDERAL OR STATE OFICE USE				


THE SPACE FOR FEDERAL OR STATE OFICE USE			
Approved by	5	04/00/0000	
LONG VO / Ph: (575) 234-5972 / Approved	Petroleum Engineer Title	01/30/2023  Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.	Office CARLSBAD		

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



DAE 03/08/23



## PLUG AND ABANDONMENT CONDITIONS OF APPROVAL

<b>OPERATOR'S NAME:</b>	Cimarex Energy Company of Colorado
LEASE NO.:	NMNM92160
WELL NAME & NO.:	Chosa Draw 27 Federal 3
<b>US Well Number:</b>	3001537180
LOCATION:	Section 27, T.25 S., R.26 E., NMPM
COUNTY:	Eddy County, New Mexico
Sundry ID:	2708576
Karst:	□Low □Medium □High ⊠Critical
Potash:	☐Secretary ☐R111P
Special Area:	☐Prairie Chicken ☐Capitan Reef

- 1) Spot cement from 8965' to 8410'. WOC and Tag. If below tag depth pump from last tag to 8410'. WOC and Tag. Repeat until tag depth of 8410' is met. 75 sxs CL H or until tag depth is met. (KOP, Shoe, Top of Liner, Wolfcamp)
- 2) Spot cement from 5340' to 5187'. WOC and Tag. 50 sxs CL C. (Bone Springs)
- 3) Spot cement from 2879' to 2687'. WOC and Tag. 60 sxs cl C. (Casing Damage)
- 4) Spot cement from 1903' to 1447'. WOC and Tag. 115 sxs Cl C. (Delaware, Shoe DV tool)
- 6) PUMP (35) SXS. CLASS "C" CMT. @ 1,073'-973' (T/SALT); WOC X TAG TOC.
- 7) CIRC. (110) SXS. CLASS "C" CMT. @ 456'-3' (13-3/8" CSG. SHOE).
- 8) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CSGS. X INSTALL DRY HOLE MARKER. DURING THIS PROCEDURE WE PLAN TO USE A CLOSED-LOOP SYSTEM W/ A STEEL TANK X HAUL CONTENTS TO THE REQUIRED DISPOSAL, PER OCD RULE 19.15.17.

# **Approval Subject to General Requirements and Special Stipulations Attached**

- No more than 3000 feet between cement plugs in cased hole.
- Wait on Cement and Tag Top of Cement Requirement:
  - 1. Shoe, Top of Salt, Base of Salt, DV tool, Perforate and Squeeze, Open Perforation.
  - 2. Formation plug is optional if a solid base is established and confirmed.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

### **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 195039

### **CONDITIONS**

Operator:	OGRID:
CIMAREX ENERGY CO. OF COLORADO	162683
600 N. Marienfeld Street	Action Number:
Midland, TX 79701	195039
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
gcordero	After tagging plug at 8410' - test casing 500psi/30 min. and leak test	3/9/2023