I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Payan B Guey TITLE Regulatory Supervisor DATE 6/2/2023

Type or print name Ryan Curry E-mail address: ryan@vfpetroleum.com PHONE: 432-683-3344

For State Use Only

APPROVED BY: TITLE Petroleum Specialist DATE 6/9/23

Conditions of Approval (if any):

From: <u>Alvarado, David, EMNRD</u>

To: <u>Bill Pierce</u>

Subject: Re: [EXTERNAL] Request change in plugging method

Date: Thursday, April 20, 2023 1:38:08 PM

Good Bill,

I see no problem of the above changes.

V-F Petroleum will follow the conditions for plugging and abatmete procedures forward. Please attach this email with your C-103 Subsequent Report.

Regards,

David Alvarado EMNRD OCD C- 505-670-8745

Thanks, David.

From: Bill Pierce <bill@vfpetroleum.com>
Sent: Thursday, April 20, 2023 9:52:51 AM

To: Alvarado, David, EMNRD < David. Alvarado@emnrd.nm.gov>

Subject: [EXTERNAL] Request change in plugging method

CAUTION: This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Mr. Alvarado,

V – F Petroleum Inc. requests a change in the plugging method to be utilized on the following well:

Oxy Mako State Com #001 API Number: 30-015-29337

Unit Letter J

Section 5 – T19S – R29E Eddy County, New Mexico

V-F respectfully requests the we be allowed to leave the existing 5 $\frac{1}{2}$ " production casing intact and utilize the perf and squeeze method of plugging the well.

We feel this change will enhance the quality of the cement plugs placed in the wellbore and of course it is inherently safer to leave the casing intact from an operational stand point.

If you need any additional information regarding this request, please feel free to contact our production foreman Chris Mabrey @ 432 664-2451 or the Operations Manager Bill Pierce @ 432 683-3344.

Thank you for your time and consideration in this matter.

Regards,
Bill Pierce
Operations Manager
V – F Petroleum Inc.
O: 432 683-3344

e-mail: bill@vfpetroleum.com

Work Detail
Oxy Mako State Com #1
30-015-29337
P&A Summary

03/24/23	Load tubing with 33 barrels and casing with 10 barrels. Work on WH bolts. Broke top nuts and cut bottom nuts. LD tree and release on & off tool to remove wrap around. Nipple up BOP. Pull out of hole w/250 joints of 2 3/8" tubing; tally out of hole. Had drag coming off bottom. SWI. SDFN.
03/25/23	No press on well. Finish POOH w/tubing; no packer recovered, had upper half of On & Off tool. Tool looks good; RIH w/same. Attempt to latch up on packer, unable to do so. Pick up swive, . wash off top of packer, latch upon same and release. RD swivel. SDFW.
03/28/23	SICP 0 psi., SITP 300#. Bled pressure off tubing and run in hole w/packer. Pick up two joints. Packer has bad drag in 20# csg. Pull out of hole w/packer and 2 joints of tail pipe. LD packer and start running in hole w/open ended tubing w/ 4' perf sub on bottom. Run in hole to 7,600'. SDFN.
03/29/23	No press on well., finish RIH w/tubing. Tag up on fill @ 10,700'. Pump down tubing and attempt to wash tubing string deeper, unable to get any deeper. Contact NMOCD rep and he said to set CIBP @ 11,700'. POOH w/tubing. SDFN.
03/30/23	No press on well. RU wireline and run in hole w/4 $\frac{1}{2}$ " junk basket gage ring and set dwn at 10,586'. Contact OCD rep and instructed to clean out fill. RD wireline and pick up 4 5/8" bit and csg scraper w/6 – 3 $\frac{1}{2}$ " drill collars. Tag @ 10,590' bit bouncing. Circ clean. Had metal cuttings. Contact OCD rep and instructed to set CIBP @ 10,590'. RD swivel and pull out of hole w/70 stands. SDFN.
03/31/23	Pull out of hole with collars and bit. RU wireline and run in hole w/CIBP. Set at 10,574.5' and RD wireline. Run in hole w/4' per sub and 45 stands tbg. SDF high winds. SWI. SDFN.
04/01/23	Run in hole with tubing to CIBP at 10,574.5'. Nipple up B-1 flange and land on BOP. SWI for future cement work. Ready to RD WSU and release all equipment. SD high winds.
04/17/23	MIRU WSU, prepare to pump cement. RU Big E and set balanced 25 sacks of Class H cement plug on top of CIBP at 10,574'. POOH w/tubing to depth of 9,500', SDFN.
04/18/23	Run in hole and tag cement plug at 10,350'. Pull out of hole w/15 stands of tubing pulling wet. Finish pulling out of hole utilizing mud bucket and vacuum truck. Find cement in last four joints. RU Apollo Wireline, RIH w/4 ½" gauge ring junk basket, tag at 10,312'. Run in hole w/CIBP and set at same at depth of 10,312, RD wireline truck. Run in hole w/tubing and set 25 sacks Class H balanced plug on top of CIBP. Pull out of hole w/15 stands. SWI. SDFN.
04/19/23	Finish TIH w/tubing, tag cement plug at 9,805'. RU Big E cement pump truck. Attempt to establish circulation down tubing, pressured up to 3,000#, could not pump down tubing. RD cement pump truck and pull out of hole w/tubing, found 21 joints plugged, last 10 joints were clean. SDFN.
04/20/23	Run in hole w/tubing to depth of 9,800'. SDFN. No cement pump truck available until tomorrow.
04/21/23	RU cement pump truck, computer on mixing blender would not communicate with mixing pump. Wait on mechanic for 4 hours, fixed problem and resumed operations. Mixed and pumped 35 sacks Class H with 16 barrels of plug mud ahead of slurry; balance plug at 9,700'. Pull out of hole with tubing to 9,100', reversed out tubing with clean fluid. WOC 4 hours, RIH and tagged plug @ 9,390'. Pull out of hole with tubing to depth of 8,950'. Attempt to break circulation, unable to do
04/23/23	so. RD cement pump truck, SDFN. Pull wet tubing string out of hole utilizing mud bucket and vacuum truck. Found cement plug in tubing 300' above end of tubing string, approximately ½ sack of cement. Clean out cement plug and run in hole to depth of 8,950' to pump 25 sack plug.

Work Detail
Oxy Mako State Com #1
30-015-29337
P&A Summary

04/25/23

RU cement pump truck, pumped balanced 25 sack Class H cement plug pumping 16 bbls mud ahead of plug at depth of 8,950'. Pull out of hole with tubing and depth of 7,800' and reverse tubing clean. While WOC, attempted to pressure test casing; established circulation up annulus of intermediate casing and production casing. TIH and tagged cement plug @ 8,705'. Pull out of hole with tubing and perforated sub. Run in hole with 5 ½" AD-1 tension packer, set at depth of 5,000'. Attempted to pressure test casing above packer and were not able to gain any pressure or load backside. Pressure up below packer to 500#, casing pressure tested successfully. Have hole in production casing above depth of 5,000'. Run in hole w/packer to depth of 7,900'. Ready to perf and squeeze, SDFN.

04/26/23

Set AD-1 packer at depth of 7,675'. RU Apollo Wireline; run in hole w/6 shot through tubing perforating gun, perforated 6 holes at depth of 8,575'. POOH w/wireline and RU Big E cement pump truck. Pressured to 2,000# psi, held, could not pump into perforations. Run in hole with perforating gun and perforated 6 holes at depth of 8,590'. Were able to pump into perorations, squeezed 75 sacks Class H cement with NMOCD personnel wanting top of plug no lower than 8,413'. WOC 3 hours. POOH w/54 joints of tubing laying same down in singles, set packer at depth of 6,180'. Run in hole w/perforating gun and tag cement plug at 8,255', NMOCD personnel OK'd plug top. Pull perforating gun to depth of 6,990'. Perforate 6 squeeze holes and pumped 50 sacks of Class C cement into squeeze holes displacing same with 9.2 ppg plug mud. SDFN.

04/27/23

Run in hole w/perforating gun, tagged previous plug top @ depth of 6,842'. Pull up w/perforating gun and shoot 6 squeeze holes at depth of 5,000'. Pull packer to depth of 3,590'; pumped 50 sack Class C neat plug and squeezed into perforations @ 5,000'. WOC 3 hours and pulled packer to depth of 2,093'. Set packer and press tested 5 ½" casing to 500# psi, held OK. Ran perforating gun and perforated 6 squeeze holes at depth of 3,050'. Squeeze perforations @ 3,050' with 100 sacks of Class C cement successfully. SDFN.

04/28/23

Pull out of hole w/34 jts tbg. Set pkr at 1,020'. Run in hole w/6 shot through tbg perf gun. Tag previous plug at 2,200'. Perf csg at 2,000'. Pmp 75 sacks Class C net cmt. Squeeze at 1,400# psi. SI WOC 3 hrs. Pull out of hole w/tbg to 300'. Run in hole w/perf gun. Tag plug at 1,100'. Shoot final holes at 445'. Pull out of hole w/wireline. RD. LD tbg and tbg equipment. Remove BOP. Install B-1 flange on WH. Start off w/cmt and circ to surf. SI intermediate csg and squeeze w/total of 150 sacks of Class C. SI and RD cmt pmpg WSU.

04/29/23

Check out cmt levels and cmt didn't fall back. Pick up tbg to be inspected and tested 292 jts. Line

up for tanks to be cleaned. Dig out cellar and remove WH and install marker.

05/01/23 Install dry hole marker

06/02/2023

 Well:
 OXY Mako State Com #1
 Operator:
 V-F Petroleum Inc.

 Location:
 1370 FSL and 1650 FEL
 Field:
 Turkey Track Morrow, W.

 Sec 5 T-19-S R-28-E
 Elevation:
 GL=
 3399

 Eddy County, New Mexico
 KB-GL=
 18

 API#
 30-015-29337
 KB=
 3417

WELLBORE SCHEMATIC AFTER PLUG ND ABANDONMENT Casing & Cement TD Hole Sz Tops & Perfs 17 1/2" 395 13 3/8" 48# CSG w/ 620 sx CMT cement plug @ 445' TOC Surface 75 sack cement plug @ 2,000', TOC 1,100' 9.5 ppg plug mud 100 sack cement plug 3,050' TOC 2,200' 3000 $8\,5/8$ " 24# & 32# CSG w/ 1550 sx CMT 7 7/8" T Bone Springs @ 3,727' 9.5 ppg plug mud 50 sacks cement @ 5,000' 50 sack cement plug @6,990', TOC 6,842' 9.5 ppg plug mud 75 sack cement plug 8,590', TOC 8,255' T Wolfcamp @ 8,900' TOC @ 8700 by CBL 25 sack cement plug @ 8,950', TOC 8,705' 9.5 ppg plug mud T Cisco @ 9,672' 35 sack balanced plug @ 9,700', TOC 9,390' Top of Canyon 9,906 9.5 ppg plug mud Top of Strawn 10,142' 25 sack balanced plug, TOC 9,805' 25 sack balanced plug, TOC 10,350' T Atoka @ 10,426' CIBP @ 10,574.5' Atoka Perfs: 10,519' - 10,594' T Morrow @ 10,638' - Model D Packer @ 11,094' w/blanking plug Morrow Perfs: 11,226' - 11,236' PBTD 11,313' 11370 5 1/2" 17# & 20# CSG w/ 450sx CMT

REMARKS: Wellbore after Plugging and abandonment Operations.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 223221

CONDITIONS

Operator:	OGRID:
V-F PETROLEUM INC	24010
P.O. Box 1889	Action Number:
Midland, TX 79702	223221
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By		Condition Date
john.harrison	None	6/9/2023