Sundry Print Report

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

COM

Well Name: FREEDOM 31 FEDERAL Well Location: T20S / R29E / SEC 31 / County or Parish/State: EDDY /

SWNW /

Well Number: 1 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Lease Number: NMNM04825 Unit or CA Name: 1 FREEDOM 31 FED Unit or CA Number: COM NMNM109678

US Well Number: 3001532546 Well Status: Producing Gas Well Operator: MEWBOURNE OIL

COMPANY

Notice of Intent

Sundry ID: 2730027

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 05/10/2023 Time Sundry Submitted: 07:16

Date proposed operation will begin: 05/10/2023

Procedure Description: See attached procedure & before and after wellbore schematics requesting to plug & abandon the subject well.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Freedom_31_Fed_Com__1_WBS_After_20230510071446.pdf

Freedom_31_Fed_Com__1_WBS_Before_20230510071434.pdf

 $Freedom_31_Fed_Com_1_Plugging_Procedure_20230510071304.pdf$

County or Parish/State: EDDY/200 eived by OCD: 6/28/2023 12:58:49 PM Well Name: FREEDOM 31 FEDERAL Well Location: T20S / R29E / SEC 31 /

COM SWNW /

Type of Well: CONVENTIONAL GAS

Unit or CA Name: 1 FREEDOM 31 FED

NMNM109678 COM

US Well Number: 3001532546 Operator: MEWBOURNE OIL Well Status: Producing Gas Well

COMPANY

Allottee or Tribe Name:

Unit or CA Number:

NM

Conditions of Approval

Specialist Review

Well Number: 1

FREEDOM 31 FEDERAL COM 1 2730027 COA AND PROCEDURE 20230627142136.pdf

Operator

Lease Number: NMNM04825

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: JACKIE LATHAN Signed on: MAY 10, 2023 07:15 AM

Name: MEWBOURNE OIL COMPANY

Title: Regulatory

Street Address: PO Box 5270

City: Hobbs State: NM

Phone: (575) 393-5905

Email address: Jlathan@mewbourne.com

Field

Representative Name: Logan Craig

Street Address: PO Box 5270

City: Hobbs State: NM **Zip:** 88241

Phone: (575)393-5905

Email address: lcraig@mewbourne.com

BLM Point of Contact

Signature: KEITH IMMATTY

BLM POC Name: KEITH P IMMATTY BLM POC Title: ENGINEER

BLM POC Phone: 5759884722 BLM POC Email Address: KIMMATTY@BLM.GOV

Disposition: Approved Disposition Date: 06/27/2023

Merribourne Oil Comparing

COMPLETION PROCEDURE

Submitted By: L. Craig

Wellname:	Freedom 31 Fed Com #1		
Location:	1800' FNL & 660' FWL Sec 31, T20S, R29E Eddy Co, NM		
Date:	5/3/23		
Csg Set:	11900'	Surf Csg:	20" 94# H40 BTC set @ 405'
	5 ½" 17# HCP110 & N80	Inter #1:	13 %" 54.5# J55 set @ 1187'
Morrow Perfs:	11408' – 11657'	Inter #2:	8 %" 32# J55 set @ 3026'
:		Tbg:	2 3/8" 6.5# N80
-		Tbg set @:	11390'

Well is uneconomic & is ready to be plugged & abandoned.

Procedure:

- 1) MIRU BCM turnkey plugging crew.
- 2) ND tree, NU BOP.
- 3) Release pkr & POOH w/tbg.
- RIH w/5 ½" CIBP & set @ 11333'. Top Morrow perf @ 11408', top Morrow @ 11356'.
- 5) Circulate 265 bbls 9.0# MLF spacer & spot 25 sks Class H neat cmt (205' ±) on top of CIBP.
- 6) WOC 4 hrs. Tag plug @ 11194' or higher.
- 7) LD pipe to 9194' (top Wolfcamp @ 9144').
- 8) Spot 25 sks Class H neat cmt (205' ±).
- 9) WOC 4 hrs & tag plug @ 9094' or higher.
- 10)LD pipe to 7730' (TOC @ 7680').
- 11)Spot 25 sks Class H neat cmt (205' ±).
- 12)WOC 4 hrs & tag plug @ 7630 or higher.
- 13)POOH w/tbg.
- 14)RIH w/wireline & perforate 5 $\frac{1}{2}$ " csg @ 5772' (top BSPG @ 5722'). Circ MLF out 5 $\frac{1}{2}$ " annulus to surface.
- 15)RIH w/tbg & pkr to 5300'. Set pkr & set balanced plug squeezed through the perfs w/55 sks Class C neat cmt (250' ±).
- 16)WOC 4 hrs & tag plug @ 5672' or higher.
- 17)POOH w/tbg.
- 18)RIH w/wireline & perforate 5 ½" csg @ 3388' (top Delaware @ 3338').
- 19)RIH w/tbg & pkr to 3000'. Set pkr & set balanced plug squeezed through the perfs w/55 sks Class C neat cmt (250' ±).
- 20)WOC 4 hrs & tag plug @ 3288' or higher.
- 21)POOH w/tbg.
- 22)RIH w/wireline & perforate 5 $\frac{1}{2}$ " csg @ 3076' (8 $\frac{5}{8}$ " shoe @ 3026').
- 23)Load well, shut in backside & test 8 %" shoe to 500# to make sure it holds.
- 24)RIH w/tbg & pkr to 2700'. Set pkr & set balanced plug squeezed through the perfs w/45 sks Class C neat cmt (150' ±).
- 25)WOC 4 hrs & tag plug @ 2976' or above.
- 26)POOH w/tbg.
- 27)RIH w/wireline & perforate 5 ½" csg @ 1237' (13 ¾" shoe @ 1187').
- 28)RIH w/tbg & pkr to 800'. Set pkr & set balanced plug squeezed through the perfs w/45 sks Class C neat cmt (150' ±)
- 29)WOC 4 hrs & tag plug @ 1137' or above.
- 30)POOH w/tbg.
- 31)RIH w/wireline & perforate 5 ½" csg @ 455' (20" shoe @ 405').
- 32)RIH w/tbg & pkr to 100'. Set pkr & set balanced plug squeezed through the perfs w/45 sks Class C neat cmt (150' ±)
- 33)WOC 4 hrs & tag plug @ 355' or above.

Freedom 31 Federal Com #1


Messibousine Oil Company

COMPLETION PROCEDURE

- 34)POOH w/tbg.
- 35)RIH w/wireline & perforate 5 ½" csg @ 200'. 36)Circulate cmt to surface (approximately 30 sks required).
- 37)WOC & confirm that wellbore remains full.
- 38)Cut off WH & install dry hole marker. Cut off anchors & clean location.


Freedom 31 Federal Com #1 WBS

1800' FNL & 660' FWL, Sec. 31 - T20S - R29E Eddy Co, NM



Freedom 31 Federal Com #1 WBS

1800' FNL & 660' FWL, Sec. 31 - T20S - R29E Eddy Co, NM



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 233915

CONDITIONS

Operator:	OGRID:
MEWBOURNE OIL CO	14744
P.O. Box 5270	Action Number:
Hobbs, NM 88241	233915
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
john.harrisor	Accepted for record - NMOCD JRH 6/29/23. BLM approved P&A 6/27/23	6/29/2023