District I - (575) 393-6161 Energy, Minerals and Natural Resources Rev 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 OH. CONSERVATION DIVISION OH. CONSERVATION DIVISION	Form C-103 vised July 18, 2013
District II _ (575) 748 1283	20000
	20908
District III – (505) 334-6178 1220 South St. Francis Dr. 5. Indicate Type of Lease	EE 🗆
<u>District IV</u> – (505) 476-3460 Santa Fe, NM 87505 6. State Oil & Gas Lease N	
1220 S. St. Francis Dr., Santa Fe, NM 87505 329709	
SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agr	reement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH State EF COM	
PROPOSALS.) 1. Type of Well: Oil Well	
2. Name of Operator Raybaw Operating, LLC 9. OGRID Number 33022	20
3. Address of Operator 2626 Cole Avenue, Suite 300 10. Pool name or Wildcat	
Dallas, 1X 75204 Inbe: Permo Penn 4. Well Location	
	۸/ انست
Section 06 Township 11S Range 34E NMPM County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
4196' (GR)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT (
A STATE OF THE PROPERTY OF THE	NG CASING
TEMPORARILY ABANDON	
DOWNHOLE COMMINGLE	
CLOSED-LOOP SYSTEM	
OTHER: OTHER: OTHER: OTHER: OTHER:	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore d	ng estimated date
proposed completion or recompletion.	augram or
Rigged up well servicing equipment 6/24/2021. Pressured tubing to 500 psi. Dropped to 200 psi, HIT.	
Unseated pump (paraffin present). Swabbed tubing while pulling rods. Ran paraffin knife & recovered smaparaffin. Changed equipment. Used swab cup (hard dry paraffin present). Ran full swab cup to 5000' and	all amount of recovered
just a fair the state of the st	100000100
larger amount of paraffin.	
larger amount of paraffin.	
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down.	o went through 51'. Lay plugged joint
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay	o went through 51'. Lay plugged joint
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need Rigged down & released rig 7/1/2021. Returned well to production.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need Rigged down & released rig 7/1/2021. Returned well to production.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need Rigged down & released rig 7/1/2021. Returned well to production.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need Rigged down & released rig 7/1/2021. Returned well to production. Spud Date: O6/24/2021 Rig Release Date: 07/01/2021 I hereby certify that the information above is true and complete to the best of my knowledge and belief.	o went through (51'. Lay plugged joint y down 3 joints ded.
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need Rigged down & released rig 7/1/2021. Returned well to production. Spud Date: O6/24/2021 Rig Release Date: O7/01/2021 I hereby certify that the information above is true and complete to the best of my knowledge and belief.	o went through 51'. Lay plugged joint y down 3 joints
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need Rigged down & released rig 7/1/2021. Returned well to production. Spud Date: O6/24/2021 Rig Release Date: 07/01/2021 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Figure Argument PHONE: 28 Type or print name Nancy J. Winn E-mail address:nwinn@sbcglobal.net PHONE: 28	o went through (51'. Lay plugged joint y down 3 joints ded.
larger amount of paraffin. TOH w/tubing (82 stands, approx 5215'). Ran swab in tubing & tagged obstruction @ approx 5515'. Swab obstruction. Stopped at 5919' and recovered hard paraffin plug @ 5915', Pulled tubing & found plug at 58 down. TOH w/tubing & lay down 2 3/8" mechanical SN. Cleaned out SN and removed SV. TOH w/kill string & lay above SN. Picked up new PS w/BP-SN-PC Blast joint-White Band joint. TIH while testing tubing to 6000 psi. TIH with replacement pump. Ran unit @ 10% & will increase as need Rigged down & released rig 7/1/2021. Returned well to production. Spud Date: O6/24/2021 Rig Release Date: O7/01/2021 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE Angle An	o went through 151'. Lay plugged joint y down 3 joints ded.

District III

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 39407

CONDITIONS

Operator:	OGRID:
RAYBAW Operating, LLC	330220
2626 Cole Avenue	Action Number:
Dallas, TX 75204	39407
	Action Type:
	[C-103] Sub. Workover (C-103R)

CONDITIONS

Created By		Condition Date
kfortner	None	7/28/2023