
Coincid by Opp Po Appropriate 3 strict 9:06 PM	State of New Mexico	Form C-103 ¹ of 5
<u>District I</u> – (575) 393-6161 I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resource	WELL API NO.
011 5. 1 list 5t., Altesia, 1414 00210	OIL CONSERVATION DIVISION	N 30-025-34372 5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87505		19520
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION	AND REPORTS ON WELLS O DRILL OR TO DEEPEN OR PLUG BACK TO A I FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name North Hobbs G/SA Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas W	Vell Other	8. Well Number 523
2. Name of Operator		9. OGRID Number 157984
Occidental Permian LTD 3. Address of Operator		10. Pool name or Wildcat
P.O. Box 4294 Houston, TX 77210-	4294	HOBBS; GRAYBURG-SAN ANDRES
4. Well Location		
Unit Letter F: 200		
Section 33	Township 18S Range 38E	NMPM County LEA
	Elevation (<i>Show whether DR, RKB, RT, GL</i> 2' (GL)	R, etc.)
12. Check Appro	priate Box to Indicate Nature of No	otice, Report or Other Data
TEMPORARILY ABANDON	G AND ABANDON REMEDIAL COMMENC	SUBSEQUENT REPORT OF: WORK
CLOSED-LOOP SYSTEM OTHER:	Plugback ✓ OTHER:	
13. Describe proposed or completed o	perations. (Clearly state all pertinent detail EE RULE 19.15.7.14 NMAC. For Multip	ils, and give pertinent dates, including estimated date ble Completions: Attach wellbore diagram of
See planned procedure attached.		
Spud Date:	Rig Release Date:	
I hereby certify that the information above	•	wledge and belief.
SIGNATURE Roni Mather	TITLE Regulatory Advis	or DATE 12/15/2023
Type or print name Roni Mathew For State Use Only	E-mail address: roni_mat	hew@oxy.com PHONE: (713) 215-7827
- A	TITLE Compliance Offi	icer A


Job Plan:

- 1. POOH w/ ESP Equipment.
- 2. PU & RIH w/ bit to PBTD.
- 3. PU & RIH w/ CIBP. Set CIBP $^{\sim}4223'$. Dump bail 10' cmt on top CIBP.
- 4. PU & RIH w/ ESP Equipment.
- 5. Return well to production.

Current WBD



Proposed WBD



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 295267

CONDITIONS

Operator:	OGRID:
OCCIDENTAL PERMIAN LTD	157984
P.O. Box 4294	Action Number:
Houston, TX 772104294	295267
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By		Condition Date
kfortner	Perform PWOT BHT	1/9/2024