## State Of New Mexico Energy, Minerals and Natural Resources Department

26-Aug-24

## HILCORP ENERGY COMPANY

**Pre Enforcement Notification** 

1111 Travis Street Houston, TX 77002

## Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

| [30-045-23374] BOLIN A #001A   |  | OGRID: 372171  | F-34-29N-08W 1740 FNL 1700 FWL |                          |
|--|--|--|--------------------------------|--------------------------|
| Inspection D   | ate Type Inspection  | Inspector  | Inspection No.                 |                          |
| 8/26/2024 Routine Inspect  |  | [EZM] Eileen Medrand   | iEZM2423938742                 |                          |
| Violation Title  |  |  |                                | Corrective<br>Action Due |
| cEZM2423957548 19.15.16.8 Sign on Wells Illegible or Unreadable  |  |  |                                | 11/24/2024               |
| (The well sign operator sticker is peeling and is not visible from 50 feet and needs to be replaced.)  |  |  |                                |                          |
| cEZM2423957549 19.15.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Noncompliance with Requirements (Construction, Operations or Closure) |  |  |                                | 11/24/2024               |
| (The below grade tank contains hydrocarbons that need to be removed.)  |  |  |                                |                          |
| cEZM2423957550 19.15.29 Releases Surface Leaks/Spills  |  |  |                                | 11/24/2024               |
|  | (Location has staining around the                                    | compressor that needs to be  | removed.)                      |                          |
| cEZM2423957551   | 19.15.17 Pits, Closed-Loop System (Construction, Operations or Close | 5.17 Pits, Closed-Loop Systems, Below Grade Tanks and Sumps Noncompliance with Requirements nstruction, Operations or Closure) |                                |                          |
| (The below grade tank base is not visible and needs to be dugout.)   |  |  |                                |                          |

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

Oil Conservation Division \* 1000 Rio Brazos Road \* Aztec, NM 87410 Phone: 505-334-6178 \* Fax: 505-334-6170 \* www.emnrd.nm.gov