

Santa Fe Main Office

Phone: (505) 476-3441 Fax: (505) 476-3462

General Information

Phone: (505) 629-6116

Online Phone Directory Visit:

<https://www.emnrd.nm.gov/ocd/contact-us/>State of New Mexico  
Energy, Minerals and Natural ResourcesForm C-103  
Revised July 18, 2013OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <b>30-025-26423</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Leamex</b>
8. Well Number <b>23</b>
9. OGRID Number <b>331199</b>
10. Pool name or Wildcat

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator <b>Maverick Permian LLC</b>	
3. Address of Operator <b>1000 Main Street Ste 2900 Houston, TX 77002</b>	
4. Well Location Unit Letter <b>F</b> : <b>1980</b> feet from the <b>North</b> line and <b>1980</b> feet from the <b>West</b> line Section <b>24</b> <b>17S</b> Township <b>33E</b> Range <b>NMPM</b> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

Notify OCD 24 hrs. prior to any work done. [gilbert.cordero@emnrd.nm.gov](mailto:gilbert.cordero@emnrd.nm.gov)

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Maverick Permian is requesting approval of the attached plan to P&A

Spud Date:

Rig Release Date:

\*\*\*SEE ATTACHED COA's\*\*\*

MUST BE PLUGGED BY 8/1/25

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Nicole Lee TITLE Regulatory Lead DATE 8/27/2024

Type or print name Nicole Lee E-mail address: nicole.lee@mavresources.com PHONE: 713-437-8097  
**For State Use Only**

APPROVED BY: [Signature] TITLE Staff Manager DATE 8/28/24  
 Conditions of Approval (if any):



1111 Bagby Street • Suite 1600  
Houston • Texas • 77002  
713-437-8000

**Leamex 23  
P&A Procedure**

**Notes:**

See CBL and Adjust cement as needed

**Procedure:**


1. Set CIBP @ 4,355' - Test casing 500psi/30min, bubble test - Run CBL to surface
2. Spot 35' of cement via bailer runs. Wait 6 hrs and tag @ 4320' or higher.
3. Mix, Pump, and Spot 15 sx of Class C cement @ 3,900'. WOC 6 hrs. TAG and Record. Isolates Queen Formation.
4. Mix, Pump, and Spot 15 sx of Class C cement @ 2,930'. WOC 6 hrs. TAG and Record. Isolates Yates Formation.
5. Perf 5-1/2" Csg @ 1588'. Attempt SQZ. Do not exceed 500 psi on the squeeze. Mix, Pump, and SQZ 250' cmt plug. WOC 6 hrs, Tag & Record. Isolates Ruster formation
6. Surface Plug: Perf 5-1/2" Csg @ 350'. Attempt SQZ. Do not exceed 500 psi on the squeeze. Mix, Pump, and SQZ 350' cmt plug. Circulate to sfc and top fill
7. Cut wellhead and install dry hole marker



# LEAMEX 23 Wellbore Diagram

Well Header					
API # 3002526423		State NEW MEXICO		County LEA	District PERMIAN CONVENTIONAL
Division PERMIAN	Business Unit MAVERICK PERMIAN		Region RG_SE_NEW_MEXICO	Area A_GEMSTONE_CAPROCK	Total Depth (ft/B) 4,688.0

Wellbore Sections											
Section Des		Size (in)	Act Top (ft/B)	Act Top (TVD) (ft/B)	Act Btm (ft/B)	Act Btm (TVD) (ft/B)	Start Date	End Date			
SURFAC		12 1/4	12.0		410.0		11/23/1979	11/23/1979			
PROD1		7 7/8	410.0		4,688.0		11/24/1979	11/29/1979			
Casing Strings											
Casing String: Surface 8 5/8" Set Depth: 410.0											
Casing Description		Run Date	OD (in)	OD Nom M.	ID (in)	ID Nom M.	Wt/Len (lb/ft)	String Grade	Length (ft)	Top (ft/B)	Set Depth
Surface		11/23/1979 00:00	8 5/8	8 5/8	8.10	8.097	24.00	K-55	398.00	12.0	
Item Des	Joints in Tail	OD (in)	ID (in)	Wt (lb/ft)	Grade	Len (ft)	Qty	Top (ft/B)	Btm (ft/B)	Top (TVD) (ft/B)	Btm (TVD) (ft/B)
Casing Joints	0	8 5/8		8.097	24.00	K-55		398.00		12.0	410.0
Casing String: Production 4 1/2" Set Depth: 4,688.0											
Casing Description		Run Date	OD (in)	OD Nom M.	ID (in)	ID Nom M.	Wt/Len (lb/ft)	String Grade	Length (ft)	Top (ft/B)	Set Depth
Production		11/30/1979 00:00	4 1/2	4 1/2	4.00	4	11.60	N-80	4,676.00	12.0	
Item Des	Joints in Tail	OD (in)	ID (in)	Wt (lb/ft)	Grade	Len (ft)	Qty	Top (ft/B)	Btm (ft/B)	Top (TVD) (ft/B)	Btm (TVD) (ft/B)
Casing Joints	0	4 1/2		4	11.60	N-80		4,676.00		12.0	4,688.0
Cement											
Surface Casing Cement											
Cementing Start Date		Cementing End Date				String Surface, 410.0ft/B					
11/23/1979 01:00											
Slg #	Pump Start Date	Pump End Date				Top (ft/B)	Btm (ft/B)		Top (TVD) (ft/B)		Btm (TVD) (ft/B)
1	11/23/1979					12.0	410.0				
Production Casing Cement											
Cementing Start Date		Cementing End Date				String Production, 4,688.0ft/B					
11/30/1979 01:00											
Slg #	Pump Start Date	Pump End Date				Top (ft/B)	Btm (ft/B)		Top (TVD) (ft/B)		Btm (TVD) (ft/B)
1	11/30/1979					12.0	4,688.0				
Cement Plug											
Cementing Start Date		Cementing End Date				String Production, 4,688.0ft/B					
11/30/1979 02:00											
Slg #	Pump Start Date	Pump End Date				Top (ft/B)	Btm (ft/B)		Top (TVD) (ft/B)		Btm (TVD) (ft/B)
1	11/30/1979					4,643.0	4,688.0				
Tubing Strings											
Set Depth: 4,557.4											
Run Job	String	String Ma.	OD Nom M.	ID (in)	ID Nom M.	Wt (lb/ft)	String Grade	Top (ft/B)	Set Depth	Len (ft)	
REPAIR DOWNHOLE FAILURE, 9/18/2013 07:30		2 3/8	4.052	2.00	1.65	4.70	J-55	12.0		4,545.3	7
Item Des	Len (ft)	OD (in)	ID (in)	Wt (lb/ft)	Grade	Tally Job Run	Tally Len (ft)	Top (ft/B)	Btm (ft/B)	Top (TVD) (ft/B)	Btm (TVD) (ft/B)
Tubing	4,157.6	2 3/8	2.00	4.70	J-55	0		12.0	4,169.7		
MARKER JTS	6.00	2 3/8	2.00	4.70	J-55	0		4,169.7	4,175.7		
Tubing	62.90	2 3/8	2.00	4.80	J-55	0		4,175.7	4,238.6		
Anchor 4.5 X 2 3/8	2.75	4.052	2.00			0		4,238.6	4,241.3		
Tubing	283.27	2 3/8	2.00	4.70	J-55	0		4,241.3	4,524.6		
TK-99	31.66	2 3/8	2.00	4.70	J-55	0		4,524.6	4,556.3		
Pump Seating Nipple	1.10	2 3/8	1.65			0		4,556.3	4,557.4		
Rod Strings											
Set Depth: 4,558.4											
Rod Description	Set De.	Run Date	Run Job	OD (in)	Wt (lb/ft)	String Gr.	Top (ft/B)	Set De.	Set De.	String Components	
Rod	4,558.4	9/25/2013	REPAIR DOWNHOLE FAILURE, 9/18/2013 07:30	3/4		D Spec KD	-5.6			Gas Anchor/Dip Tube, Rod Insert Pump, Sinker Bar, Sucker Rod, Rod Guide, Sucker Rod, Sucker Rod, Polished Rod	
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
22.00	1 1/2	1					-5.6		16.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
1,575.00	7/8	63				D Spec KD	16.4		1,591.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
2,800.00	3/4	112				D Spec KD	1,591.4		4,391.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
50.00	3/4	2				D Spec KD	4,391.4		4,441.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
2.00	3/4	1				D Spec KD	4,441.4		4,443.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
50.00	1 1/4	2				C	4,443.4		4,493.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
2.00	3/4	1				D Spec KD	4,493.4		4,495.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
50.00	1 1/4	2				C	4,495.4		4,545.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
12.00	1 1/16	1				C	4,545.4		4,557.4		
Length (ft)	OD Nominal (in)	Quantity	ID (in)	Weight/Length (lb/ft)		Grade	Top Depth (ft/B)		Bottom Depth (ft/B)		
1.00	1	1					4,557.4		4,558.4		
Perforations											
Date	Top (ft/B)	Btm (ft/B)	Top (TVD) (ft/B)	Btm (TVD) (ft/B)	Shot Dens (shots/ft)	Calculated Shot Total	Btm - Top (ft)				
6/5/2001 00:00	4362	4569				44	207				
12/18/1979 00:00	4408	4550				85	142				
Deviation Surveys											
Date	Description				Job						
Survey Data											
MD (ft/B)	Incl (°)	Azim (°)	Method	TVD (ft/B)	VS (ft)	Depart (ft)	NS (ft)	EW (ft)	DLS (°/100ft)	Build (°/100ft)	Turn (°/100ft)
											Unwrap Displace



State: New Mexico  
County: Lea  
Field:  
Spud Date: 11/23/1979  
KB: 11.5

Maverick Resources  
Well: Leamex 23  
API# 30-025-26423

Proposed WBD  
8/27/2024

Surface Casing: 8-5/8" 24# K-55 . Cmt w/  
600 sx to sfc

MD

MD

410'

350'

1338'

1588'

2730'

2930'

3700'

3900'

4307'

4337'

4362'

4,550'

Surface Plug: Perf 5-1/2" Csg @ 350'. Attempt SQZ. Do not exceed 500 psi on the squeeze. Mix, Pump, and SQZ 350' cmt plug. Circulate to sfc and top fill

Rustler Plug: Perf 5-1/2" Csg @ 1588'. Attempt SQZ. Do not exceed 500 psi on the squeeze. Mix, Pump, and SQZ 250' cmt plug. WOC, Tag & Record. (Isolates Rustler formation)

Mix, Pump, and Spot 30 sx of Class C cement @2930'. WOC 4 hrs. TAG and Record. Isolates Yates Formation.

Mix, Pump, and Spot 30 sx of Class C cement @3900'. WOC 4 hrs. TAG and Record. Isolates Queen Formation.

Spot 35' of cement @ 4307' Wait 4 hours and tag

Set CIBP @ 4337' and bail 25' of cement

Perfs f/ 4,362'- 4,550'

## INDICATE FORMATION

Southeastern New M

T. Anhy _____	T. Cany _____
T. Salt _____	T. Straw _____
U. <del>San</del> Rustler 1488'	T. Aoki _____
T. Yates 2830'	T. Moss _____
T. 7 Rivers _____	T. Devo _____
T. Queen 3794'	T. Sibbi _____
T. Grayburg 4216'	T. Mono _____
T. San Andres 4575'	T. Sipe _____
T. Glorieta _____	T. McKs _____
T. Paddock _____	T. Elter _____
T. Blinbry _____	T. Gr. V _____
T. Tubb _____	T. Gran _____
T. Drinkard _____	T. Dela _____
T. Abo _____	T. Bons _____
T. Wolfcomp _____	T. _____
T. Penna _____	T. _____
T. Cisco (Bough C) _____	T. _____

No. 1, from.....to.....

Production Csg: 4.5" 11.6# N-80.Cmt w/ 4688'  
1500 sx to sfc

**State of New Mexico**  
**Energy, Minerals and Natural Resources Department**  
**Oil Conservation Division**  
**Standard Plugging Conditions**



This document provides OCD's general plugging conditions of approval. It should be noted that the list below may not cover special plugging programs in unique and unusual cases, and OCD expressly reserves the right to impose additional requirements to the extent dictated by project conditions. The OCD also reserves the right to approve deviations from the below conditions if field conditions warrant a change. A C-103F NOI to P&A must be approved prior to plugging operations. Failure to comply with the conditions attached to a plugging approval may result in a violation of 19.15.5.11 NMAC, which may result in enforcement actions, including but not limited to penalties and a requirement that the well be re-plugged as necessary.

1. Notify OCD office at least 24 hours before beginning work and seek prior approval to implementing any changes to the C-103 NOI to PA.
  - North Contact, Monica Kuehling, 505-320-0243, [monica.kuehling@emnrd.nm.gov](mailto:monica.kuehling@emnrd.nm.gov)
  - South Contact, Gilbert Cordero, 575-626-0830, [gilbert.cordero@emnrd.nm.gov](mailto:gilbert.cordero@emnrd.nm.gov)
2. A Cement Bond Log is required to ensure strata isolation of producing formations, protection of water and correlative rights. A CBL must be run or be on file that can be used to properly evaluate the cement behind the casing.

Note: Logs must be submitted to OCD via OCD permitting. A copy of the log may be emailed to OCD inspector for faster review times, but emailing does not relieve the operators obligation to submit through OCD permitting.

3. Once Plugging operations have commenced, the rig must not rig down until the well is fully plugged without OCD approval. If gap in plugging operations exceeds 30 days, the Operator must file a subsequent sundry of work performed and revised NOI for approval on work remaining. At no time shall the rig be removed from location if it will result in waste or contamination of fresh water.
4. Insure all bradenheads have been exposed, identified and valves are operational prior to rig up.
5. Fluids must be placed between all cement plugs mixed at 25 sacks per 100 bbls of water.
  - North, water or mud laden fluids
  - South, mud laden fluids
6. Closed loop system is to be used for entire plugging operation. Upon completion, contents of steel pits are to be hauled to an OCD permitted disposal facility.
7. Class of cement shall be used in accordance with the below table for depth allowed.

Class	TVD Lower Limit (feet)
Class A/B	6,000
Class I/II	6,000
Class C or III	6,000
Class G and H	8,000
Class D	10,000

Class E	14,000
Class F	16,000

8. After cutting the well head any "top off cement jobs" must remain static for 30 minutes. Any gas bubbles or flow during this 30 minutes shall be reported to the OCD for approval of next steps.
9. Trucking companies being used to haul oilfield waste fluids (Commercial or Private) to a disposal facility shall have an approved OCD C-133 permit.
  - A copy of this permit shall be available in each truck used to haul waste products.
  - It is the responsibility of the Operator and Contractor to verify that this permit is in place prior to performing work.
  - Drivers shall be able to produce a copy upon request of an OCD Compliance Officer.
10. Filing a [C-103] Sub. Plugging (C-103P) will serve as notification that the well has been plugged.
11. A [C-103] Sub. Release After P&A (C-103Q) shall be filed no later than a year after plugging and a site inspection by OCD Compliance officer to determine if the location is satisfactorily cleaned, all equipment, electric poles and trash has been removed to meet OCD standards before bonding can be released.
12. Produced water or brine-based fluids **may not** be used during any part of plugging operations without **prior OCD approval**.
13. Cementing;
  - All cement plugs will be neat cement and a minimum of 100' in length. 50' of calculated cement excess required for inside casing plugs and 100% calculated cement excess required on outside casing plugs.
  - If cement does not exist between or behind the casing strings at recommended formation depths, the casing perforations will be shot at 50' below the formation top and the cement retainer shall be set no more than 50' from the perforations.
  - WOC (Wait on Cement) time will be:
    - 4 hours for accelerated (calcium chloride) cement.
    - 6 hours on regular cement.
  - Operator must tag all cement plugs unless it meets the below condition.
    - The operator has a passing pressure test for the casing annulus and the plug is only an inside plug.
  - If perforations are made operator must tag all plugs using the work string to tag unless given approval to tag with wireline by the correct contact from COA #1 of this document.
    - This includes plugs pumped underneath a cement retainer to ensure retainer seats properly after cement is pumped.
  - Cement can only be bull-headed with specific prior approval.
  - Squeeze pressures are not to exceed the exposed formations frac gradient or the burst pressure of the casing.
14. A cement plug is required to be set from 50' below to 50' above (straddling) formation tops, casing shoes, casing stubs, any attempted casing cut offs, anywhere the casing is perforated, DV tools.
  - Perforation/Formation top plug. (When there is less than 100ft between the top perforation to the formation top.) These plugs are required to be started no greater than

50ft from the top perforation. However, the plug should be set below the formation top or as close to the formation top as possible for the maximum isolation between the formations. The plug is required to be a 100ft cement plug plus excess.

- Perforation Plug when a formation top is not included. These plugs are required to be started within 50ft of the top perforation. The plug is required to be a 100ft cement plug plus excess.
- Cement caps on top of bridge plugs or cement retainers for perforation plugs, that are not straddling a formation top, may be set using a bailer with a minimum of 35' of cement in lieu of the 100' plug. The bridge plug or retainer must be set within 50ft of the perforations.
- Perforations are required below the surface casing shoe if cement does not exist behind the casing, a 30-minute minimum wait time will be required immediately after perforating to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. If gas is detected contact the OCD office for directions.

15. No more than 3000 feet is allowed between cement plugs in cased hole and no more than 2000 feet is allowed in open hole.

16. Formation Tops to be isolated with cement plugs, but not limited to are:

- Northwest See Figure A
- South (Artesia) See Figure B
- Potash See Figure C
  - In the R-111-P (Or as subsequently revised) Area a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts that are common to the section penetrated and in suitable proportions, not more than 3% calcium chloride (by weight of cement) will be considered the desired mixture whenever possible, woe 4 hours and tag, this plug will be 50' below the bottom and 50' above the top of the Formation.
- South (Hobbs) See Figure D1 and D2
- Areas not provided above will need to be reviewed with the OCD on a case by case basis.

17. Markers

- Dry hole marker requirements 19.15.25.10.

The operator shall mark the exact location of plugged and abandoned wells with a steel marker not less than four inches in diameter set in cement and extending at least four feet above mean ground level. The marker must include the below information:

  1. Operator name
  2. Lease name and well number
  3. API number
  4. Unit letter
  5. Section, Township and Range
- AGRICULTURE (Below grade markers)

In Agricultural areas a request can be made for a below ground marker. For a below ground marker the operator must file their request on a C-103 notice of intent, and it must include the following;

  - A) Aerial photo showing the agricultural area
  - B) Request from the landowner for the below ground marker.

C) Subsequent plugging report for a well using a below ground marker must have an updated C-102 signed by a certified surveyor for SHL.

Note: A below ground marker is required with all pertinent information mentioned above on a plate, set 3' below ground level, a picture of the plate will be supplied to OCD for record, the exact location of the marker (longitude and latitude by GPS) will be provided to OCD. OCD requires a current survey to verify the location of the below ground marker, however OCD will accept a GPS coordinate that were taken with a GPS that has an accuracy of within 15 feet.

18. If work has not commenced within 1 year of the approval of this procedure, the approval is automatically expired. After 1 year a new [C-103] NOI Plugging (C-103F) must be submitted and approved prior to work.



Figure A

North Formations to be isolated with cement plugs are:

- San Jose
- Nacimiento
- Ojo Alamo
- Kirtland
- Fruitland
- Picture Cliffs
- Chacra (if below the Chacra Line)
- Mesa Verde Group
- Mancos
- Gallup
- Basin Dakota (plugged at the top of the Graneros)
- Deeper formations will be reviewed on a case-by-case basis

Figure B

South (Artesia) Formations to be isolated with cement plugs are:

- Fusselman
- Montoya
- Devonian
- Morrow
- Strawn
- Atoka
- Permo-Penn
- Wolfcamp
- Bone Springs
- Delaware , in certain areas where the Delaware is subdivided into;
  - 1. Bell Canyon
  - 2. Cherry Canyon
  - 3. Brushy Canyon
- Any salt sections
- Abo
- Yeso
- Glorieta
- San Andres
- Greyburg
- Queen
- Yates

## Figure C

## Potash Area R-111-P

## T 18S – R 30E

Sec 10 Unit P. Sec 11 Unit M,N. Sec 13 Unit L,M,N. Sec 14 Unit C -P. Sec 15 Unit A G,H,I,J,K,N,O,P. Sec 22 Unit All  
except for M. Sec 23, Sec 24 Unit C,D,E,L, Sec 26 Unit A-G, Sec 27 Unit A,B,C

## T 19S – R 29E

Sec 11 Unit P. Sec 12 Unit H-P. Sec 13. Sec 14 Unit A,B,F-P. Sec 15 Unit P. Sec 22 Unit A,B,C,F,G,H,I,J K,N,O,P. Sec 23.  
Sec 24. Sec 25 Unit D. Sec 26 Unit A- F. Sec 27 Unit A,B,C,F,G,H.

## T 19S – R 30E

Sec 2 Unit K,L,M,N. Sec 3 Unit I,L,M,N,O,P. Sec 4 Unit C,D,E,F,G,I-P. Sec 5 Unit A,B,C,E-P. Sec 6 Unit I,O,P. Sec 7 – Sec  
10. Sec 11 Unit D, G—P. Sec 12 Unit A,B,E-P. Sec 13 Unit A-O. Sec 14-Sec 18. Sec 19 Unit A-L, P. Sec 20 – Sec 23. Sec  
24 Unit C,D,E,F,L,M,N. Sec 25 Unit D. Sec 26 Unit A-G, I-P. Sec 27, Sec 28, Sec 29 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 32  
Unit A,B,G,H,I,J,N,O,P. Sec 33. Sec 34. Sec 35. Sec 36 Unit D,E,F,I-P.

## T 19S – R 31E

Sec 7 Unit C,D,E,F,L. Sec 18 Unit C,D,E,F,G,K,L. Sec 31 Unit M. Sec 34 Unit P. Sec 35 Unit M,N,O. Sec 36 Unit O,P.

## T 20S – R 29E

Sec 1 Unit H,I,P. Sec 13 Unit E,L,M,N. Sec 14 Unit B-P. Sec 15 Unit A,H,I,J,N,O,P. Sec 22 Unit A,B,C,F,G,H,I,J,O,P. Sec  
23. Sec 24 Unit C,D,E,F,G,J-P. Sec 25 Unit A-O. Sec 26. Sec 27 Unit A,B,G,H,I,J,O,P. Sec 34 Unit A,B,G,H. Sec 35 Unit  
A-H. Sec 36 Unit B-G.

## T 20S – R 30E

Sec 1 – Sec 4. Sec 5 Unit A,B,C,E-P. Sec 6 Unit E,G-P. Sec 7 Unit A-H,I,J,O,P. Sec 8 – 17. Sec 18 Unit A,B,G,H,I,J,O,P.  
Sec 19 Unit A,B,G,H,I,J,O,P. Sec 20 – 29. Sec 30 Unit A-L,N,O,P. Sec 31 Unit A,B,G,H,I,P. Sec 32 – Sec 36.

## T 20S – R 31E

Sec 1 Unit A,B,C,E-P. Sec 2. Sec 3 Unit A,B,G,H,I,J,O,P. Sec 6 Unit D,E,F,J-P. Sec 7. Sec 8 Unit E-P. Sec 9 Unit E,F,J-P.  
Sec 10 Unit A,B,G-P. Sec 11 – Sec 36.

## T 21S – R 29E

Sec 1 – Sec 3. Sec 4 Unit L1 – L16,I,J,K,O,P. Sec 5 Unit L1. Sec 10 Unit A,B,H,P. Sec 11 – Sec 14. Sec 15 Unit A,H,I. Sec  
23 Unit A,B. Sec 24 Unit A,B,C,D,F,G,H,I,J,O,P. Sec 25 Unit A,O,P. Sec 35 Unit G,H,I,J,K,N,O,P. Sec 36 A,B,C,F – P.

## T 21S – R 30E

Sec 1 – Sec 36

## T 21S – R 31E

Sec 1 – Sec 36

T 22S – R 28E

Sec 36 Unit A,H,I,P.

T 22S – R 29E

Sec 1. Sec2. Sec 3 Unit I,J,N,O,P. Sec 9 Unit G – P. Sec 10 – Sec 16. Sec 19 Unit H,I,J. Sec 20 – Sec 28. Sec 29 Unit

A,B,C,D,G,H,I,J,O,P. Sec 30 Unit A. Section 31 Unit C – P. Sec 32 – Sec 36

T 22S – R 30E

Sec 1 – Sec 36

T 22S – R 31E

Sec 1 – Sec 11. Sec 12 Unit B,C,D,E,F,L. Sec 13 Unit E,F,K,L,M,N. Sec 14 – Sec 23. Sec 24 Unit

C,D,E,F,K,L,M,N. Sec 25

Unit A,B,C,D. Sec 26 Unit A,BC,D,G,H. Sec 27 – Sec 34.

T 23S – R 28E

Sec 1 Unit A

T 23S – R 29E

Sec 1 – Sec 5. Sec 6 Unit A – I, N,O,P. Sec 7 Unit A,B,C,G,H,I,P. Sec 8 Unit A – L, N,O,P. Sec 9 – Sec 16. Sec 17 Unit

A,B,G,H,I,P. Sec 21 – Sec 23. Sec 24 Unit A – N. Sec 25 Unit D,E,L. Sec 26. Sec 27. Sec 28 Unit A – J, N,O,P. Sec 33

Unit A,B,C. Sec 34 Unit A,B,C,D,F,G,H. Sec 35. Sec 36 Unit B,C,D,E,F,G,K,L.

T 23S – R 30E

Sec 1 – Sec 18. Sec 19 Unit A – I,N,O,P. Sec 20, Sec 21. Sec 22 Unit A – N, P. Sec 23, Sec 24, Sec 25. Sec 26 Unit

A,B,F-P. Sec 27 Unit C,D,E,I,N,O,P. Sec 28 Unit A – H, K,L,M,N. Sec 29 Unit A – J, O,P. Sec 30 Unit A,B. Sec 32 A,B. Sec

33 Unit C,D,H,I,O,P. Sec 34, Sec 35, Sec 36.

T 23S – R 31E

Sec 2 Unit D,E,J,O. Sec 3 – Sec 7. Sec 8 Unit A – G, K – N. Sec 9 Unit A,B,C,D. Sec 10 Unit D,P. Sec 11 Unit G,H,I,J,M,N,O,P. Sec 12 Unit E,L,K,M,N. Sec 13 Unit C,D,E,F,G,J,K,L,M,N,O. Sec 14. Sec 15 Unit A,B,E – P.

Sec 16 Unit

I, K – P. Sec 17 Unit B,C,D,E, I – P. Sec 18 – Sec 23. Sec 24 Unit B – G, K,L,M,N. Sec 25 Unit B – G, J,K,L. Sec 26 – Sec

34. Sec 35 Unit C,D,E.

T 24S – R 29E

Sec 2 Unit A, B, C, D. Sec 3 Unit A

T 24S – R 30E

Sec 1 Unit A – H, J – N. Sec 2, Sec 3. Sec 4 Unit A,B,F – K, M,N,O,P. Sec 9 Unit A – L. Sec 10 Unit A – L, O,P. Sec 11.

Sec 12 Unit D,E,L. Sec 14 Unit B – G. Sec 15 Unit A,B,G,H.

T 24S – R 31E

Sec 3 Unit B – G, J – O. Sec 4. Sec 5 Unit A – L, P. Sec 6 Unit A – L. Sec 9 Unit A – J, O, P. Sec 10 Unit B – G, K – N. Sec

35 Unit E – P. Sec 36 Unit E, K, L, M, N.

T 25S – R 31E

Sec 1 Unit C, D, E, F. Sec 2 Unit A – H.

Figure D1 and D2

South (Hobbs) Formations to be isolated with cement plugs are:

The plugging requirements in the Hobbs Area are based on the well location within specific areas of the Area (See Figure D1). The Formations in the Hobbs Area to be isolated with cement plugs are (see Figure D2)

Figure D1 Map




Figure D2 Formation Table

100' Plug to isolate upper and lower fresh water zones (typically 250' to 350')						
Northwest Shelf	Captan Reef Area	Transition Zone	San Simon Channel	South Vacuum Structure	Delaware Basin	Central Basin Platform
Granit Wash (Detrital basement material and fractured pre-Cambrian basement rock)	Siluro-Devonian	Morrow	Siluro-Devonian	Ellenburger	Siluro-Devonian	Granit Wash (Detrital basement material, fractured pre-Cambrian basement rock and fracture Mafic Volcanic intrusives).
Montoya	Mississippian	Atoka	Morrow	McKee	Morrow	Ellenburger
Fusselman	Morrow	Strawn	Wolfcamp	Siluro-Devonian	Atoka	Connell
Woodford	Atoka	Cisco	Abo Reef	Woodford	Strawn	Waddell
Siluro-Devonian	Strawn	Pennsylvanian	Bone Spring	Mississippian	Pennsylvanian	McKee
Chester	Pennsylvanian	Wolfcamp	Delaware	Barnett Shale	Lower Wolfcamp	Simpson Group
Austin	Wolfcamp	Bone Spring	San Andres	Morrow	Upper Wolfcamp	Montoya
Mississippian	Abo Reef, if present	Delaware	Queen	Atoka	Wolfcamp	Fusselman
Morrow	Abo, if present	San Andres	Yates	Strawn	Third Bone Spring Sand (Top of Wolfbone)	Silurian
Atoka	Queen, if present	Grayburg-San Andres	Base of Salt	Canyon	First Bone Spring Sand (Top of Lower Bone Spring)	Devonian
Lower Pennsylvanian	Bone Spring	Queen	Rustler	Pennsylvanian	Bone Spring	Strawn
Cisco-Canyon	Delaware	Seven Rivers		Blinbry	Brushy Canyon	Pennsylvanian
Pennsylvanian	Base Capitan Reef	Yates		Bone Spring	Delaware (Base of Salt)	Wolfcamp
Bough	Seven Rivers	Base of Salt		San Andres	Rustler	Abo
Wolfcamp	Yates	Rustler		Queen		Abo Reef
Abo	Top Capitan Reef			Base of Salt		Drinkard
Abo Reef, if present	Base of Salt			Rustler		Tubb
Yeso (Township 15 South to Township 17 South)	Rustler					Blinbry
Drinkard or Lower Yeso (Township 15 South to Township 17 South)						Paddock
Tubb (Township 15 South to Township 17 South)						Glorieta
Blinbry (Township 15 South to Township 17 South)						San Andres
Paddock (Township 15 South to Township 17 South)						Grayburg
Glorieta						Grayburg-San Andres
San Andres						Queen
Queen (Township 15 South to Township 17 South)						Seven Rivers
Seven Rivers (Township 15 South to Township 17 South)						Yates
Yates (Township 15 South to Township 17 South)						Base of Salt
Base of Salt						Rustler
Rustler						

**District I**  
1625 N. French Dr., Hobbs, NM 88240  
Phone:(575) 393-6161 Fax:(575) 393-0720

**District II**  
811 S. First St., Artesia, NM 88210  
Phone:(575) 748-1283 Fax:(575) 748-9720

**District III**  
1000 Rio Brazos Rd., Aztec, NM 87410  
Phone:(505) 334-6178 Fax:(505) 334-6170

**District IV**  
1220 S. St Francis Dr., Santa Fe, NM 87505  
Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico**  
**Energy, Minerals and Natural Resources**  
**Oil Conservation Division**  
**1220 S. St Francis Dr.**  
**Santa Fe, NM 87505**

CONDITIONS

Action 378423

CONDITIONS

Operator: Maverick Permian LLC 1000 Main Street, Suite 2900 Houston, TX 77002	OGRID: 331199
	Action Number: 378423
	Action Type: [C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	CBL must be submitted to OCD via OCD Permitting prior to submitting C-103P	8/28/2024