Received by OCD: 10/21/2024 3:41:28 PM

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

5 Leasa Serial No.

6. If Indian, Allottee or Tribe Name

NMNM-0155494A

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals

abandoned well	. Use Form 3160-3 (/	APD) for su	ch proposa	is.	1	
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit of CA/Agreement, Name and/or No	
I. Type of Well					NMNM82050x	
✓ Oil Well Gas Well Other					9 Well Mame and Mo	Cato San Andres Unit # 160
2. Name of Operator Marshall & Wil	nston, Inc for Cano Petrole	um of new Me	deo, Inc.		9. API Well No. 30-00	05-20151
3a Address P.O. Box 50880 Midland, TX 79710		3b. Phone No. (include area code) (432) 684-6373			10. Field and Pool or Exploratory Arca Sen Andres - Cato Unit	
4. Location of Well (Footage, Sec., T. 1980' FSL 1980 FWL, NESW 28	010)			11. Country or Parish, Chaves NM	State
12. CH	ECK THE APPROPRIATE B	OX(ES) TO IN	DICATE NATUI	RE OF NOT	ICE, REPORT OR OTH	IER DATA
TYPE OF SUBMISSION			т	YPE OF AC	TION	
Notice of Intent Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	New	en autic Fracturing Construction and Abandon	Rect	luction (Start/Resume) amation amplete porarily Abandon	Water Shut-Off Well Integrity Other
Final Abandonment Notice	Convert to Injection	Plug	Back	Wate	er Disposal	
- Pump 100sx @ 2146 - POH	b' Drill and clean out and or 2592' - POH - SDFD - Spot 40 sx @ 2478' - WC KEvin B and spotted 50 st in B approved another 50 - SDFD A approved spotting 50 sx B' - POH - WOC - RIH tag (1 100sx @ 1421' per Jenni 21' - POH - WOC - RIH tag (1 150 sacks per Jennifer @ ot 100 sx per Jennifer @ ot 100 sx per Jennifer - PC oot 25 sx @ 1203' per Jenni 25sx - POH - WOC - RII WOC - R	n 9/27/22 got of the property	town to 2592° g t 2380 - call Ke XC - RiH lag @ @ 2216° POH I spot 50 SX @ 100 sx @ 1528 DC - RiH lag @ kt 100 sx @ 133 WOC - SDFD FD EIH tag @ 1128 lest casing to 5	ot approved vin Bussell 12308' - spa - WOC - Ri 1600' - PO ' per Jennif 1421' SDF 76' per Jenni ' - spot 25 s	I to spot plug - spot 50 sx @ 2380' ot 50 sx @ 2308' - PC If tag @ 2146' - Jenn oH - WOC - RIH tag @ fer Sanchez - SDFD D nifer - POH -WOC - Si sx @ 1128' per Jennil	*-POPH - SDFD 3H - SOFD 3H - SOFD 3H - Sanchez oked pumping 100 sx 3 1528' - poh - Kevin approved 50 DFD 4er - POH - WOC SDFD
4 I hereby certify that the foregoing is May Hard	true and correct. Name (Printing 5	2	Title JP	Sem	lero	
Signature // // Call	- UDEC		Date 12	120	1	
-	THE SPACE	FOR FEDE	RAL OR ST	ATE OF	CE USE	
Approved by JENNIFER SANCH	EZ Date: 2023.01.05 09:56:20 -07'0	0,	Title Pe	troleum	n Engineer _{Da}	01/05/2023

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Office

RFO

(Instructions on page 2)

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Plug And Abandonment Procedure Cato San Andres Unit 160

1980' FSL & 1980' FWL, Section 28, T 8S, R 30E Chaves County, NM / API 30-005- 20151

Marshall & Winston, Inc. respectfully requests permission to plug and abandon this well as follows:

- 1. Place CIBP at 3,305' (50'-100' above top perf) with minimum of 25 sx of Class C cement on top. WOC and TAG.
- 2. Place a balanced Class C cement plug from 1,500' 900' to seal the Yates and Salt formations.
- 3. Perf at 350' and squeeze Class C cement to surface to seal the 8-5/8" casing shoe.
- 4. Place Dry hole marker below ground.
- 5. Complete Surface Reclamation once well bore has been plugged, contact rflores@blm.gov for additional information_

Notify BLM-Roswell (575) 622-5335 24 hours prior to commencing plugging operations

Received by OCD: 10/21/2024 3:41:28 PM

API #: 30-005-20151
Permit No.

Project No.

Cato San Andres Unit #160 Chaves County, NM


AT MA

P&A Wellbore Diagram NE

Dry Hole: Days:

TD: 3560'

NESW Sec. 28, T-8-8, R-30-E. 1980' FSL & 1980' FWL



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 394307

CONDITIONS

Operator:	OGRID:
MARSHALL & WINSTON INC	14187
P.O. Box 50880	Action Number:
Midland, TX 79710	394307
	Action Type:
	[C-103] Sub. Plugging (C-103P)

CONDITIONS

Created By	Condition	Condition Date
loren.diede	None	11/21/2024