
eized by CGP i J 265/20124 Bistic 00 P	M State of New Me	exico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natu	ural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	J DIVISION	30-045-339275. Indicate Type of Lease
District III - (505) 334-6178	1220 South St. Fran	ncis Dr.	STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 8'	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			B-11571
87505	CES AND REPORTS ON WELLS	2	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS.			7. Lease Name of Onit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICA	ATION FOR PERMIT" (FORM C-101) F	OR SUCH	Sponge Bob SWD
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well 🗌 Other SWD		8. Well Number
		_	1
2. Name of Operator			9. OGRID Number
Dugan Production Corp.			006515 10. Pool name or Wildcat
3. Address of Operator PO Box 420, Farmington, NM 87499-0420			SWD; Morrison Bluff Entrada (96162)
4. Well Location			S (D, Morrison Dran Endada () 0102)
	feet from the <u>South</u> line a	and 1910 fact fro	m the West line
Unit Letter <u>K</u> : 2300			
Section 36 T	Yownship 30N Range 11. Elevation (Show whether DR	14W NMPM	San Juan County
	5608' GR	, KKB, KI, GK, etc.)
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or complet of starting any proposed work proposed completion or recom	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL MIT ed operations. (Clearly state all propertion). SEE RULE 19.15.7.14 NMAC	REMEDIAL WOR COMMENCE DR CASING/CEMEN OTHER: ertinent details, and	ILLING OPNS. P AND A
Dugan Production Corp. requestsNotify NMOCD 24 hours before	permission to conduct an MIT on the	e well per the followin	g procedure:
 Conduct 24 hr Bradenhead test on Hook Wilson Pressure Testing Se Verify pressure recorder charts, g Pressure test 5½" 17# & 15.5#, J- 7062'-7222'. Pressure test at the NMOCD requires Conduct kill test. 	n the well per NMOCD requirements. ervice's pressure truck to 5½" injectio gauge, and spring for test requirements	on casing. s. Check calibration da ted Arrowset injection ressures at the beginnir	ate on meter. packer set @ 7023'. Entrada perforations are at
 Conduct 24 hr Bradenhead test on Hook Wilson Pressure Testing Se Verify pressure recorder charts, g Pressure test 5½" 17# & 15.5#, J- 7062'-7222'. Pressure test at the NMOCD requ Conduct kill test. Submit signed pressure recorder of 	n the well per NMOCD requirements. ervice's pressure truck to 5 ¹ / ₂ " injectio gauge, and spring for test requirements -55 casing from surface to Nickel plat tired pressure for 30 minutes. Note pro-	on casing. s. Check calibration da ted Arrowset injection ressures at the beginnir re test to NMOCD.	ate on meter. packer set @ 7023'. Entrada perforations are at
 Conduct 24 hr Bradenhead test of Hook Wilson Pressure Testing Se Verify pressure recorder charts, g Pressure test 5½" 17# & 15.5#, J- 7062'-7222'. Pressure test at the NMOCD requined Conduct kill test. Submit signed pressure recorder of Returned well back to injection. 	n the well per NMOCD requirements. ervice's pressure truck to 5½" injectio gauge, and spring for test requirements -55 casing from surface to Nickel plat uired pressure for 30 minutes. Note pro- chart and subsequent report of pressur Rig Release Dat	on casing. s. Check calibration da ted Arrowset injection ressures at the beginnir re test to NMOCD. te:	ate on meter. packer set @ 7023'. Entrada perforations are at ng and end of 30 minutes.
 Conduct 24 hr Bradenhead test of Hook Wilson Pressure Testing Se Verify pressure recorder charts, g Pressure test 5¹/₂" 17# & 15.5#, J. 7062'-7222'. Pressure test at the NMOCD requined Conduct kill test. Submit signed pressure recorder of Returned well back to injection. 	n the well per NMOCD requirements. ervice's pressure truck to 5½" injectio gauge, and spring for test requirements -55 casing from surface to Nickel plat uired pressure for 30 minutes. Note pre- chart and subsequent report of pressur Rig Release Dat	on casing. s. Check calibration da ted Arrowset injection ressures at the beginnir re test to NMOCD. te:	ate on meter. packer set @ 7023'. Entrada perforations are at ng and end of 30 minutes.
 Conduct 24 hr Bradenhead test of Hook Wilson Pressure Testing Se Verify pressure recorder charts, g Pressure test 5¹/₂" 17# & 15.5#, J. 7062'-7222'. Pressure test at the NMOCD requined Conduct kill test. Submit signed pressure recorder of Returned well back to injection. Spud Date: I hereby certify that the information ab SIGNATURE Aliph Reum	n the well per NMOCD requirements. ervice's pressure truck to 5½" injectio gauge, and spring for test requirements. -55 casing from surface to Nickel plat tired pressure for 30 minutes. Note pre- chart and subsequent report of pressur Rig Release Dat ove is true and complete to the best ####################################	on casing. s. Check calibration da ted Arrowset injection ressures at the beginnir re test to NMOCD. te: st of my knowledge pering Supervisor	ate on meter. packer set @ 7023'. Entrada perforations are at ng and end of 30 minutes.
 Conduct 24 hr Bradenhead test of Hook Wilson Pressure Testing Se Verify pressure recorder charts, g Pressure test 5¹/₂" 17# & 15.5#, J. 7062'-7222'. Pressure test at the NMOCD requined Conduct kill test. Submit signed pressure recorder of Returned well back to injection. Spud Date: I hereby certify that the information ab SIGNATURE Aliph Reena, P.E.	The well per NMOCD requirements. E-mail address: _Alip	on casing. s. Check calibration da ted Arrowset injection ressures at the beginnir re test to NMOCD. te: st of my knowledge pering Supervisor	ate on meter. packer set @ 7023'. Entrada perforations are at ng and end of 30 minutes. and belief. DATE <u>12/5/24</u> pduction.com PHONE: <u>505-360-9192</u>

.

Dugan Production Corp. requests permission to conduct an MIT on the well per the following procedure:

- Notify NMOCD 24 hours before pressure test.
- Conduct 24 hr Bradenhead test on the well per NMOCD requirements.
- Hook Wilson Pressure Testing Service's pressure truck to 5½" injection casing.
- Verify pressure recorder charts, gauge, and spring for test requirements. Check calibration date on meter.
- Pressure test 5½" 17 & 15.5#, J-55 casing from surface to Nickel plated Arrowset injection packer set @ 7023'. Entrada perforations are at 7062'-7222'.
- Pressure test at the NMOCD required pressure for 30 minutes. Note pressures at the beginning and end of 30 minutes.
- Conduct kill test.
- Submit signed pressure recorder chart and subsequent report of pressure test to NMOCD.
- Return well back to injection

Current Injection Wellbore Schematic Dugan Production Corp. Sponge Bob SWD # 1 API: 30-045-33927 Sec 36 T30N R14W Injection Zone: Morrison Bluff Entrada



Released to Imaging: 12/6/2024 6:53:54 AM

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
DUGAN PRODUCTION CORP	6515
PO Box 420	Action Number:
Farmington, NM 87499	409239
	Action Type:
	[C-103] NOI General Sundry (C-103X)

CONDITIONS

Created By	Condition	Condition Date
mkuehling	None	12/6/2024

Page 4 of 4