Phone: (505) 476-3441 Fax: (55) 476-3462	State of New Mexico State of New Mexico		Form C-163 Revised July 18, 2013	
General Information Phone: (505) 629-6116	Energy, Minerals and Na		WELL API NO.	0, 2013
nling Dhang Directory Visit.	OIL CONSERVATIO		30-039-05634	
Online Phone Directory Visit: https://www.emnrd.nm.gov/ocd/contact-us/ 1220 South St. Francis Dr.		4	5. Indicate Type of Lease	
	Santa Fe, NM 8		STATE STATE 5. State Oil & Gas Lease No.	
)		5. State off & Gus Lease 110.	
DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"		LUG BACK TO A	7. Lease Name or Unit Agreement N C P STATE	ame
PROPOSALS.) 1. Type of Well: Oil Well 🔲 G	as Well 🛛 Other		8. Well Number 004	
2. Name of Operator NANCY WILCOX E QUALLS			9. OGRID Number 15501	
 Address of Operator PO BOX 420 FARMINGTON, NM 8 	7410		 Pool name or Wildcat BALLARD PICTURED CLIFFS 	
4. Well Location				
Unit Letter P:_990	feet from the _FSL	line and 1190	feet from theFELlin	ne
Section 2 Township	24N Range 06W	NMPM	County RIO ARRIBA	
	11. Elevation (Show whether D	DR, RKB, RT, GR, etc.)		
	6466'			
PULL OR ALTER CASING I DOWNHOLE COMMINGLE I	CHANGE PLANS	COMMENCE DRILL CASING/CEMENT J		
CLOSED-LOOP SYSTEM		OTHER:		
). SEE RULE 19.15.7.14 NMA ppletion.	C. For Multiple Comp	give pertinent dates, including estimat oletions: Attach wellbore diagram of g and abandon the above Nancy Wilc	
ualls well. Please see attached work				
4/3/1959]			

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Heather Huntington	Permitting Technican	12/23/24
Type or print name <u>Heather Huntington</u> For State Use Only	E-mail address:hhuntington@enduringresources.com	_ PHONE: _505-636-9751
APPROVED BY:	_TITLE	_DATE

CP STATE 004 30-039-05634 P&A WORK SUMMARY

11/19/24-PJSM. RU WOR AWS 748. SITP 150 psi. SICSP 150 psi. SICP 255 psi. SIBHP 0 psi. Bleed well down to 0 psi. ND Upper wellhead. LD 68 jnts1" NU cap string w/ 3 gas lift mandrels. Brake off rusted up 9" wellhead cap. Hammering on cap & pilling w/ 60" pipe wrench. Tried to pull tbg hanger pulling from 0-70k & jarring on tbg hanger. Could not get tbg hanger out. SIW. Secure well. Drain up equipment & secure for the night. John Durham NMOCD Rep on location.


11/20/24-PJSM. SITP 130 psi. SICP 240 psi. SIBHP 0 psi. Blow well down. RU tbg hanger jack. Pulled 30k on top flange. Tighten nuts down on tbg hanger jack applying more pressure to tbg hanger while hammering on wellhead. Pulled threads out of tbg hanger. NUBOP. RU work floor. Tbg tongs & slips. Wait on tbg spear. Spear 2 3/8 tbg w/ 1.992 grapple. RU tbg hanger jack. Pulled 30k on top flange while tightening down nut on tbg hanger jack to apply more pressure to tbg hanger while hammering on wellhead. Pulled spear out of 2 3/8" tbg. RD tbg anger jack. PU & MU spear w/ new 1.992 grapple. x-over. 3 3/4 jars, 16' of 3 3/4 subs, intensifier & pick up sub. Strung into 2 3/8" tbg. Pulled up & set off jars @ 45K. Spear pulled out of 2 3/8' tbg & tore up grapple. SWI. Secured well, secure & drain up equipment for night. John Durham NMOCD Rep on location.

11/21/24- PJSM. SITP 60 psi. SICP 110 psi. SIBHP 0 psi. bleed well down to 0 psi. Spear into 2 3/8 tbg w/ 4' extension on spear & new 2.023 grapple set off jars 3 times w/no movement. String out of 2 3/8" tbg. Pump 50 bbls fresh water down 5 1/2" csg to kill well. Heat up wellhead. String back into 2 3/8" tbg set off jars got tbg hanger free. 2 3/8" tbg was split 2' blow upset. RD jarring assembly. LD 73 jnts 2 3/8" J-55 tbg. Bottom 4 jnts were covered in heavy scale. PU & MU 5 1/2" csg scrapper on 2 3/8" WS. RIH W/ 68 jnts to 2140'. POOH w/ 2 3/8" WS & 5 1/2 Csg scraper to surface standing back 34 strands of 2 3/8' tbg in derrick. PU & MU 5 1/2" CR on 2 3/8" WS RIH to 2140' set CR. Sting out of CR load hole w 22 bbls freshwater & rolled hole w/ 50 bbls freshwater. Pressure test 5 1/2" csg to 650 psi held good test. Bleed off pressure. Could not pump cmt below CR bulk truck was down. POOH w/ setting tool. RU wireline truck. Ran CBL log from 2138' to surface. RD Wireline truck. SWI. Secure well. secure & drain up equipment for night. John Durham NMOCD Rep on location.

11/22/24- PJSM. SICP 0 psi. SIBHP 0 psi. MU CR stringer on 2 3/8"WS & RIH to 2140'. String into CR could not get an inj rate below CR. String out of CR. Got approval to put a balance plug on top of CR. Pump plug #1 to cove Pictured Cliffs perfs. Top of CR. Fruitland & Kirtland formation tops. Inside balance plug 2140'-1693' (447' plug). Mix & pump 52 sxs 10.6 bbls 15.8 ppg class g cmt dwn 2 3/8" WS. Disp w/ 6.5 bbls fresh water. LD 14 jnt 2 3/8" WS. POOH w/ 2 3/8" WS & CR stringer to surface standing tbg back in derrick. RU wireline truck. RIH w/ 3 1/8" 4 SPF perf gun. Shot 5 1/2" csg @ 1646'. RD wire line truck. Load hole w/ 3 bbls freshwater pressured up to 720 psi trying to get an inj rate multiple times & could not get an inj rate. Got approval from NMOCD to pump an inside balance plug to cover the Ojo Alamo formation top. MU 2 2/8" tag sub 0n 2 3/8" WS & RIH to 1700'. Pump plug #2 to cover Ojo Alamo formation top. Inside balance plug 1700'- 1446' (254' plug) mix & pump 30 sxs 6 bbls 15.8 ppg class g cmt down 2 3/8" WS. Disp w/ 5.5 bbls freshwater. Ld 10 jnts. POOH w/ 2 3/8" WS & tag sub to surface standing tbg back in derrick. SWI. Secure well, Secure & drain up equipment for the weekend. SDFWE. John Durham NMOCD Rep on location.


11/25/24- PJSM. SICP 0 psi. SIBHP 0 psi. MU 2 3/8 tag sub on 2 3/8' WS. RIH tag plug #2 Ojo Alamo plug @ 1434' (162' above Ojo Alamo formation top @ 1596'). LD 27 jnt 2 3/8" WS. POOH w/ 2 3/8" WS & tag sub to surface standing tbg back in derrick. RU wire line truck. RIH w 3 1/8" 4 SPF perf gun

shot 5 1/2" csg @ 588' (Nacimiento formation). RD wireline truck. Load hole. Establish circ down 5 1/2" csg up 9 5/8 SC circ 25 bbls to waste pit to clean up well. RIH w/ 2 3/8" WS. LD 2 3/8 WS to surface. Pump plug #3 to cover Nacimiento formation top, 9 5/8 SC shoe. 9 5/8 SC to surface & fill 5 1/2" to surface. Mix & pump 177 sxs 36.2 bbls 15.8 ppg class g cmt dwn 5 1/2' csg up 9 5/8" SC circ 4 bbl good cmt to surface. RD tbg tongs slips & work floor, NDBOP & wash out BOP. NUWH. WOC. 5 1/2" TOC @ 2' from surface. Cut off wellhead. 9 5/8" SC TOC @ surface. Weld on P&A marker. Topped off casings & wellhead cellar w 20 sxs 4 bbls class g cmt. THIS WELL IS PLUGGED. RD AWS WOR 748 & AWS cmt package. Drain up equipment, Released WOR & cmt package. John Durham NMOCD Rep on location.



Received by OCD: 12/23/2024 11:10 Page 5 of 12

Received by OCD: 12/23/2024 11:10: Page 6 of 12



n X

More

My Location



Details

Address Cuba, NM 87013 United States

Coordinates 36.33692° N, 107.43269° W

Report Something Missing



Received by OCD: 12/23/2024 11:11 Page 9 of 12



Received by OCD: 12/23/2024 11:10Page 10 of 12





Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
ENDURING RESOURCES, LLC	372286
6300 S Syracuse Way	Action Number:
Centennial, CO 80111	414748
	Action Type:
	[C-103] Sub. Plugging (C-103P)
CONDITIONS	

Created By	Condition	Condition Date
loren.diede	None	12/30/2024

Action 414748

Page 12 of 12

.