

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT Sundry Print Report

Well Name: BURCH KEELY UNIT

Well Location: T17S / R29E / SEC 23 / NWNW / 32.8264123 / -104.0529973

County or Parish/State: EDDY /

Well Number: 36

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMLC028793C

Unit or CA Name: BURCH KEELY UNIT

Unit or CA Number:

NMNM88525X

US Well Number: 3001522093

Well Status: Producing Oil Well

Operator: SPUR ENERGY

PARTNERS LLC

# **Notice of Intent**

Sundry ID: 2776676

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 02/26/2024

**Time Sundry Submitted: 11:27** 

Date proposed operation will begin: 03/01/2023

Procedure Description: Please find procedure and WBDs attached for your review. Thank you

# **Surface Disturbance**

Is any additional surface disturbance proposed?: No

#### **NOI Attachments**

**Procedure Description** 

BKU\_\_36\_NOI\_P\_A\_Submittal\_20240226112656.pdf

APPROVAL SUBJECT TO GENERAL REQUIREMENTS AND SPECIAL STIPULATIONS ATTACHED Well Name: BURCH KEELY UNIT

Well Location: T17S / R29E / SEC 23 / NWNW / 32.8264123 / -104.0529973

County or Parish/State: EDDY /

NM

Well Number: 36

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMLC028793C

Unit or CA Name: BURCH KEELY UNIT

Unit or CA Number: NMNM88525X

**US Well Number: 3001522093** 

Well Status: Producing Oil Well

Operator: SPUR ENERGY

PARTNERS LLC

### Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: SARAH CHAPMAN

Signed on: FEB 26, 2024 11:27 AM

Name: SPUR ENERGY PARTNERS LLC

Title: Regulatory Director

Street Address: 9655 KATY FREEWAY SUITE 500

City: HOUSTON

State: TX

Phone: (281) 642-5503

Email address: SCHAPMAN@SPURENERGY.COM

# Field

Representative Name:

Street Address:

City:

State:

Zip:

Phone:

Email address:

Form 3160-5 (June 2019)

# **UNITED STATES** DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2021

. Lease Se	erial No.	NMLC028793C

BUREAU OF LAND MANAGEMENT		5. Lease Serial No.	LC028793C	
SUNDRY NOTICES AND REPORTS ON Do not use this form for proposals to drill or abandoned well. Use Form 3160-3 (APD) for su	6. If Indian, Allottee or T			
SUBMIT IN TRIPLICATE - Other instructions on pa		7. If Unit of CA/Agreem	ent, Name and/or No.	
1. Type of Well		BURCH KEELY UNIT	/NMNM88525X	
Oil Well Gas Well Other		8. Well Name and No. Bl	URCH KEELY UNIT/36	
2. Name of Operator SPUR ENERGY PARTNERS LLC		9. API Well No. 300152	2093	
	. (include area code)	10. Field and Pool or Exp	ploratory Area	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)	11. Country or Parish, State			
SEC 23/T17S/R29E/NMP		EDDY/NM		
12. CHECK THE APPROPRIATE BOX(ES) TO IN	DICATE NATURE OF NOTION	CE, REPORT OR OTHER	R DATA	
TYPE OF SUBMISSION	TYPE OF ACT	TON		
Notice of Intent Acidize Dee	- Innered	action (Start/Resume)	Water Shut-Off Well Integrity	
		mplete	Other	
Change Plans	The state of the s	orarily Abandon	Control Control	
Final Abandonment Notice Convert to Injection Plug  13. Describe Proposed or Completed Operation: Clearly state all pertinent details,	Personnel	Disposal		
the Bond under which the work will be perfonned or provide the Bond No. on completion of the involved operations. If the operation results in a multiple co-completed. Final Abandonment Notices must be filed only after all requirements ready for final inspection.)  Please find procedure and WBDs attached for your review.  Thank you	unletion or recompletion in a r	new interval a Form 2160	A must be filed once testing her have	
<ol> <li>I hereby certify that the foregoing is true and correct. Name (Printed/Typed)</li> <li>SARAH CHAPMAN / Ph: (281) 642-5503</li> </ol>	Regulatory Director			
	Title			
Signature (Electronic Submission)	Date	02/26/2024	<b>L</b>	
THE SPACE FOR FED	ERAL OR STATE OF	CE USE		
Approved by  Long Vo  Conditions of approval, if any, are attached. Approval of this notice does not warrant certify that the applicant holds legal or equitable title to those rights in the subject to which would entitle the applicant to conduct operations thereon.  Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for a any false, fictitions or fraudulent statements or representations as to see the section in the subject to the section of the section in the subject to the section in	office CFO	0		
any false, fictitious or fraudulent statements or representations as to any matter with  (Instructions on page 2)	ın ıts jurisdiction.			

Released to Imaging: 1/6/2025 10:10:11 AM

#### **GENERAL INSTRUCTIONS**

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

# SPECIFIC INSTRUCTIONS

Item 4 - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

Item 13: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment. If the proposal will involve **hydraulic fracturing operations**, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

#### **NOTICES**

The privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and granting approval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.

The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.

BURDEN HOURS STATEMENT: Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect offhis form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

# **Additional Information**

# **Location of Well**

0. SHL: NWNW / 330 FNL / 330 FWL / TWSP: 17S / RANGE: 29E / SECTION: 23 / LAT: 32.8264123 / LONG: -104.0529973 ( TVD: 0 feet, MD: 0 feet ) BHL: NWNW / 330 FNL / 330 FWL / TWSP: 17S / SECTION: / LAT: 0.0 / LONG: 0.0 ( TVD: 0 feet, MD: 0 feet )


# **Burch Keely Unit #036 P&A Procedure**


- 1. Set 5-1/2" CIBP @ 2322'. Pressure test casing to 500 psi for 30 minutes. Run CBL from 2322'surface. Spot 25 sx of class C cmt from 2322'-2222'. WOC & Tag.
- 2. Spot 25 sx of class C cmt from 1898'-1798'. WOC & Tag. (T/Queen) 1865 to 1746
- 3. Perf @ 446' and sqz 45 sx of cmt from 446'-346'. WOC & Tag. (8-5/8" Shoe) @ 410! to 342 (In 13 385 / 4. Perf @ 100' and sqz 46 sx of Class C cmt from 100'-surface. 360' to surface. (In 31 585 / 00 t 41) Out (9 585)

  5. Verify cmt to surface on all annuli. Cutoff Wellhead. Weld on Below Ground Dryhole Marker. 585

4 spot 25 585 of class C cont from 1027' to 917'. (Yates @ 977')

Spot 25 sxs of class C cont from 920' to 811'. (B. Salt@ 870')





# BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-689-5981.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours. Tagging the plug means running in the hole with a string of tubing or drill pipe and placing sufficient weight on the plug to ensure its integrity. Other methods of tagging the plug may be approved by the BLM authorized officer or BLM field representative.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** 

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified *BY PHONE* (numbers listed in 2. Notifications) minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds). A weep hole shall be left if a metal plate is welded in place.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



# **United States Department of the Interior**

## **BUREAU OF LAND MANAGEMENT**

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

# **Reclamation Objectives and Procedures**

**Reclamation Objective:** Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any/all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip (across the slope and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech/Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Jose Martinez-Colon Environmental Protection Specialist 575-234-5951

Mark Mattozzi Environmental Protection Specialist 575-234-5713

Robert Duenas Environmental Protection Specialist 575-234-2229

Doris Lauger Martinez Environmental Protection Specialist 575-234-5926

Jaden Johnston Environmental Protection Asst. (Intern) 575-234-6252

Sundry ID	2776676						
Plug Type	Тор	Bottom	Length	Tag	Sacks	Cement Class	Notes
riug Type	ТОР	Bottom	Lengui	ray	Sacks	Class	Notes
Surface Plug	0.00	100.00	100.00	Tag/Verify			
				If solid			
				base no need to			
				Tag			
				(CIBP present			
				and/or			
				Mechanic al Integrity			
				Test), If			
				Perf & Sqz then			
				Tag, Leak			
				Test all CIBP if no			Perforate and squeeze from 300'
				Open			to surface. (In
Fresh Water @ 250	197.50	300.00	102.50	Perforatio	77.00	C	31/Out 46) Verify at surface.
Tresh Water & 250	137.50	300.00	102.00	113	77.00		surface.
8.625 inch- Shoe Plug	342.04	446.00	103.96	Tag/Verify			
							Perforate and squeeze from 470'
							to 342'. (In 13
Top of Salt @ 420	365.80	470.00	104 20	Tag/Verify	32.00	C	sxs/Out 19 sxs) WOC and Tag.
							Spot cement from
Base of Salt @ 870	811.30	920.00	108.70	Tag/Verify	25.00	С	920' to 811'.
				16 11			
				If solid base no			
				need to			
				Tag (CIBP			
				present			
				and/or Mechanic			
				al Integrity			
				Test), If Perf &			
				Sqz then			
				Tag, Leak Test all			
				CIBP if no			
				Open Perforatio			Spot cement from
Yates @ 977	917.23	1027.00	109.77		25.00	С	1027' to 917'.

		1		ı			1
				If solid			
				base no			
				need to			
				Tag			
				(CIBP			
				present			
				and/or			
				Mechanic			
				al Integrity			
				Test), If			
				Perf &			
				Sqz then			
				Tag, Leak			
				Test all			
				CIBP if no			
				Open			
				Perforatio			Spot cement from
Queen @ 1815	1746.85	1865.00	118.15	ns	25.00	С	1865' to 1746'.
				If solid			
				base no			
				need to			
				Tag (CIBP			
				present			
				and/or			
				Mechanic			
				al Integrity			
				Test), If			
				Perf &			
				Sqz then			
				Tag, Leak			
				Test all			Set CIBP at 2322'.
				CIBP if no			Spot 25 sxs on top.
				Open			Run CBL from top of
		2222		Perforatio	0.5.5		cement to surface.
CIBP Plug	2287.00	2322.00	35.00		25.00	C	Leak test CIBP.
Perforations Plug (If No CIBP)	2322.00 2439.85	3514.00 2565.00		Tag/Verify			
San Andres @ 2515 5.5 inch- Shoe Plug	2439.85 3441.73	3577.00	125.15	Tag/Verify			
a.a men- ande Piug	3441./3	3311.00	135.27	rag/verity			

No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs in cased hole. Class H > 7500' Class C < 7500'

Fluid used to mix the cement in R111P shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.

Medium, Secretary: Top of salt to surface If no salt take the deepest fresh water or Karst Depth

High, Critical: Bottom of Karst to surface or Deepest fresh water, whichever is greater R111P: 50 Feet from Base of Salt to surface.

Class C: 1.32 ft^3/sx Class H: 1.06 ft^3/sx

Onshore Order 2.III.G Drilling Abandonment Requirements: "All formations bearing usable-quality water, oil, gas, or geothermal resources, and/or a prospectively valuable deposit of minerals shall be protected.

Cave Karst/Potash Cement Requirement:	<u>Medium</u>	Top of Salt to surface	
8.625 inch- Shoe Plug @ 5.5 inch- Shoe Plug @	396.00 3527.00		
Perforatons Top @	2372.00	Perforations	3464.00

CIBP @ 2322.00

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory <a href="https://www.emnrd.nm.gov/ocd/contact-us">https://www.emnrd.nm.gov/ocd/contact-us</a>

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 416269

#### **CONDITIONS**

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	416269
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By		Condition Date
loren.diede	NOTE: This well was plugged 03-27-2024. NMOCD did not recieve P&A NOI until 01-02-2025. NOI is approved retroactive.	1/6/2025