eceived by QCD to Appropriate 2:51:39 P	M State of New Me	exico	Form C-103 of	
Office District I – (575) 393-6161	Energy, Minerals and Natu		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240	Energy, ministrate and interest in the secure of		WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-045-13117	
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of L	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87		STATE 6. State Oil & Gas Le	FEE 🛛
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa PC, INIVI 87505		FI	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Un	
			MOR	RIS A
			8. Well Number	)
1. Type of Well: Oil Well ☐ Gas Well ☒ Other  2. Name of Operator			9. OGRID Number	
HILCORP ENERGY COMPAN	HILCORP ENERGY COMPANY			171
3. Address of Operator			10. Pool name or Wil	dcat
382 Road 3100, Aztec, NM 8741	0		Aztec Pictured Cliffs	
4. Well Location	1750	11	1000	D4 1:
Unit Letter I : Section 14 Tow	1750 feet from the South nship 30N Range 11W		1090 feet from the County San Juan	East line
Section 14 Tow	nship 30N Range 11W 11. Elevation (Show whether DR,			
	602			
12. Check Ap	propriate Box to Indicate Na	ture of Notice, R	eport or Other Data	
NOTICE OF IN	TENTION TO:	l Sur	SEQUENT REPO	RT ∩F·
PERFORM REMEDIAL WORK □	PLUG AND ABANDON 🛛	REMEDIAL WORK		TERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI		ND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT		<b>_</b>
DOWNHOLE COMMINGLE	_		_	
CLOSED-LOOP SYSTEM	_			_
OTHER:		OTHER:		1-1: 4: 4.1.1.4
	ted operations. (Clearly state all pets). SEE RULE 19.15.7.14 NMAC.			
proposed completion or recor		Tor Munipie Comp	pictions. Tittaen wende	ie diagram or
1 1 1				
Hilcorp Energy Company requests	normission to plug and abandor	the subject well t	per the attached proces	dura A alosad loon
system will be used.	permission to plug and abandon	i tile subject well p	ber the attached proce	dure. A crosed roop
system will be used.				
Spud Date:	Rig Release Date	e:		
I hereby certify that the information ab	over is true and complete to the has	t of my knowledge	and baliaf	_
Thereby certify that the information at	ove is true and complete to the bes	at of my knowledge	and belief.	
SIGNATURE <u>Priscilla Sho</u>	TITLE Operations/Regulato	ry Technician – Sr.	DATE 1/15/202	.5
Type or print name Priscilla Sh	orty E-mail address nsh	ortv@hilcorn.com l	PHONE: (505)324-5188	3
For State Use Only	D man address.psn	, <u></u>	. 1101121 (000)024 0100	<u>,                                      </u>
	TITI F		DATE	
APPROVED BY: Conditions of Approval (if any):	TITLE		DATE	
- chainond of rippioral (if ally ).				



# HILCORP ENERGY COMPANY MORRIS A 9 P&A NOI

API#:


3004513117

#### JOB PROCEDURES

- 1. Contact NMOCD and BLM (where applicable) 24 hours prior to MIRU.
- 2. Hold pre-job safety meeting. Verify cathodic is off. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.
- 3. MIRU service rig and associated equipment; NU and test BOP.
- 4. Set a 2-7/8" CIBP or CICR at +/- 2,482' to isolate the PC Perfs.
- 5. Load the well as needed. Pressure test the casing above the plug to 560 psig.
- 6. RU Wireline. Run CBL. Record Top of Cement. All subsequent plugs below are subject to change pending CBL results.
- 7. PU & TIH w/ work string to +/- 2,480'.
- 8. PLUG #1: 13sx of Class G Cement (15.8 PPG, 1.15 yield); PC Perfs @ 2,492' | PC Top @ 2,490' | FRD Top @ 2,152':
  Pump a 13 sack balanced cement plug inside the 2-7/8" casing (est. TOC @ +/- 2,052' & est. BOC @ +/- 2,482'). Wait on cement for 4 hours, tag TOC w/ work string. \*Note cement plug lengths & volumes account for excess
- 9. POOH w/ work string. TIH & perforate squeeze holes @ +/- 1,264\*. RIH w/ 2-7/8" CICR and set CICR @ +/- 1,234\*. TIH w/ work string & sting into CICR. Establish injection.
- 10. PLUG #2a: 48sx of Class G Cement (15.8 PPG, 1.15 yield); KRD Top @ 1,214' | OJO Top @ 1,099':
  Pump 47sx of cement in the 2-7/8" casing X 6-1/4" open hole annulus (est. TOC @ +/- 949' & est. BOC @ +/- 1,264'). Pump an additional 1sx of cement beneath the 2-7/8" CICR (est. TOC @ +/- 1,234' & est. BOC @ +/- 1,264'). \*Note cement plug lengths & volumes account for excess.
- 11. POOH w/ work string. Set a 2-7/8" CIBP at +/-1,224'. TIH w/ tubing/work string.
- 12. PLUG #2b: 7sx of Class G Cement (15.8 PPG, 1.15 yield); KRD Top @ 1,214' | OJO Top @ 1,099':
  Pump a 7 sack balanced cement plug on top of the CIBP (est. TOC @ +/- 999' & est. BOC @ +/- 1,224'). WOC for 4 hrs, tag TOC w/ work string. \*Note cement plug lengths and volumes account for excess.
- 13. POOH w/ work string. TIH & perforate squeeze holes @ +/- 173'. Establish circulation.
- 14. PLUG #3: 47sx of Class G Cement (15.8 PPG, 1.15 yield); Surf. Casing Shoe @ 123':
  Pump 8sx of cement in the 2-7/8" casing X 6-1/4" open hole annulus (est. TOC @ +/- 123' & est. BOC @ +/- 173'). Continue pumping 34sx of cement in the 2-7/8" casing X 8-5/8" casing annulus (est. TOC @ +/- 0' & est. BOC @ +/- 123'). Pump a 5 sack balanced cement plug inside the 2-7/8" casing (est. TOC @ +/- 0' & est. BOC @ +/- 173'). WOC for 4 hrs, tag TOC w/ work string.
- 15. ND BOP, cut off Wellhead. Top off cement in surface casing annulus, if needed. Install a P&A marker with cement to comply with regulations. Rig down, move off location, cut off anchors, and restore location.




## HILCORP ENERGY COMPANY MORRIS A 9 P&A NOI





## HILCORP ENERGY COMPANY MORRIS A 9 P&A NOI



Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 421251

### **CONDITIONS**

Operator:	OGRID:
HILCORP ENERGY COMPANY	372171
1111 Travis Street	Action Number:
Houston, TX 77002	421251
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

## CONDITIONS

Created By	Condition	Condition Date	l
mkuehling	Notify NMOCD 24 hours prior to moving on - Monitor string pressures daily report on subsequent - Submit all logs prior to subsequent	1/15/2025	