Received by OCD 1/16/2025 1:04:54 PM State of New Mexico Phone: (505) 476-3441 Fax: (55) 476-3462 Energy, Minerals and Natural Resources General Information WELL API NO. Phone: (505) 629-6116 30-039-05252 OIL CONSERVATION DIVISION Online Phone Directory Visit: 5. Indicate Type of Lease https://www.emnrd.nm.gov/ocd/contact-us/ 1220 South St. Francis Dr. STATE X FEE Santa Fe, NM 87505 6. State Oil & Gas Lease No. SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A C P STATE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number Gas Well Other 1. Type of Well: Oil Well 003 2. Name of Operator 9. OGRID Number NANCY WILCOX E QUALLS 15501 3. Address of Operator 10. Pool name or Wildcat PO BOX 420 FARMINGTON, NM 87410 **BALLARD PICTURED CLIFFS** 4. Well Location Unit Letter H : 1580 feet from the FNL line and 920 feet from the FEL Section 36 Township 24N Range 06W NMPM County RIO ARRIBA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6777' 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK □ PLUG AND ABANDON REMEDIAL WORK ALTERING CASING □ **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS.□ P AND A  $\boxtimes$ PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Pursuant to OCD Order No R-23250 Enduring Resources has been given authorization to plug and abandon the above Nancy Wilcox E Qualls well. Please see attached work summry, wellbore diagram, and pictures. 4/3/1959 Spud Date: Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief. Heather Huntington Permitting Technician 1/16/25 TITLE DATE Heather Huntington hhuntington@enduringresources.com 505-636-9751 Type or print name E-mail address: PHONE: For State Use Only APPROVED BY: **TITLE DATE** 

## CP STATE 003 30-039-05252 P&A WORK SUMMARY


12/12/24-Move AWS WOR 748 & equipment to location. PJSM. Spot base beam. RU WOR. SITP 120 psi, SICP 130 psi. SIBHP 0 psi slight puff of gas when opened. Spot cmt equipment on location. Secured well, equipment & location for the night. Clarence Smith NMOCD representative on location.

12/13/24-PJSM. Service, start & warm up equipment, SITP 120 psi. SICP 130 psi. SIBHP 0 psi slight puff when opened. Bleed well down. NDWH. Brake loose wellhead cap. NUBOP. RU work floor. Pulled tbg hanger. Pulled 10' 2 3/8" sub tbg x-over to 1 1/4 eue tbg. Change over handling tools & pipe rams to 1 /4. LD 66 jnts 1 1/4 EUE tbg & 3' perf sub. No scale on tbg. PU & MU 5 1/2" CR on 2 3/8" J-55 WS. RIH to 2078 & set CR. Sting out of CR. Rolled hole w/ 55 bbls freshwater. Pressure test 5 1/2 csg failed leak @ surface. Sting into CR got an inj rate 2.5 BPM @ 200 psi. Mix & pump 12 sxs 2.4 bbls 15.8 ppg class G cmt dwn 2 3/8" J-55 WS, Disp w/ 8 bbls freshwater. Sting out of CR. POOH w/ 2 3/8" J-55 tbg & setting tool to surface. RU wireline truck. Run CBL from 2068 to surface. RD wireline. SWI. Secure well. Drain up & secure equipment & location for the weekend. Clarence Smith NMOCD representative on location.

12/16/24- PJSM. Service, Start & warm up equipment. SICP 0 psi. SIBHP 0 psi. Pressure test 5 1/2 csg failed. RIH w/ 2 3/8 tag on 2 3/8" WS to 2078. Pump plug #2 inside balance plug to cover Fruitland, Kirtland & Ojo Alamo formation tops. Inside balance plug. 2078'-1450' (628' plug) Mix & Pump 73 sxs 14.9 bbls 15.8 ppg class g cmt down 2 3/8" tbg. disp w/ 5.6 bbls freshwater. LD 22 jnts. POOH 2 3/3" tbg to 446'. SWI. WOC. RIH & tag plug #2 TOC @ 1428'. (161' above Ojo Alamo formation top) LD 2 3/8" WS to 762'. Pressure tested 5 1/2" csg to 600 psi failed. POOH w 2 3/8" WS & 2 3/8" tag sub standing tbg back in derrick. SWI. Secured well. Drain & secure equipment & location for the night. Clarence Smith NMOCD representative on location.

12/17/24- PJSM. Service, start 7 warm up equipment. SICP 0 psi. SIBHP 0 psi. RU wireline truck. RIH w 3 1/8" 4 SPF perf gun. Shot 5 1/2" csg @ 827'. RD wireline truck. Got an inj rate dwn 5 1/2" csg up 8 5/8" SC 1 BPM @ 600 psi. MU 5 1/2" CR on 2 3/8" WS. RIH & set CR @ 762'. Stared to pump down 2 3/8" ws up 8 5/8 SC pressured up got an inj rate 1 BPM @ 850 psi. Pump plug #3 to cover Nacimiento perfs & formation top. Mix & pump 73 sxs 14.9 bbls class g cmt dwn 2 3/8 WS. Pumped 53 sxs 10.8 bbls clsss g cmt below CR on outside of 5 1/2" csg sting out of CR pump 20 sxs 4.1 bbls on top of CR. Disp w/ 2.2 bbls freshwater. (Est TOC outside 5 1/2" csg 528'. Est TOC inside 5 1/2" csg 589') LD 2 3/8" WS to 503' rev cln. POOH w/ 2 3/8" WS & setting tool to surface standing back tbg in derrick. MU 2 3/8" tag sub on 2 3/8" WS RIH tag plug #3 TOC @ 606'(171' above Nacimiento formation top @ 777') good tag. LD 2 3/8" WS to surface. RIH w/ 3 1/8" 4 SPF perf gun Shot 5 1/2" csg @ 162'. Establish circ down 5 1/2" csg up 8 5/8" SC. RD work floor. NDBOP. NUWH. Pump SC shoe & SC plug #4. Mix & pump 60 sxs class g cmt down 5 1/2" csg up 8 5/8 SC. Circ good cmt to surface. SWI. WOC. Clarence Smith NMOCD representative on location.

12/18/24- PJSM. Service, start & warm up equipment, SICP 0 psi. SIBHP 0 psi. TOC in 5 1/2' csg 28'. Cut off wellhead. TOC in 8 5/8" SC 3.5'. Weld on P&A marker. Topped off casings w/ 18 sxs glass g cmt. WELL IS PLUGGED. Rig down AWS WOR 748 & cmt equipment. Release WOR & equipment. Clarence Smith NMOCD representative on location.







# My Location





More



# Details

Address Cuba, NM 87013 United States



Coordinates

36.27209° N, 107.41412° W



Report Something Missing









Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 421696

# CONDITIONS

Operator:	OGRID:
ENDURING RESOURCES, LLC	372286
6300 S Syracuse Way	Action Number:
Centennial, CO 80111	421696
	Action Type:
	[C-103] Sub. Plugging (C-103P)

## CONDITIONS

Created By	Condition	Condition Date
loren.diede	None	1/17/2025