U.S. Department of the Interior BUREAU OF LAND MANAGEMENT Sundry Print Report

Well Name: BLANCO WASH Well Location: T24N / R9W / SEC 2 /

NENE / 36.348297 / -107.751816

County or Parish/State: SAN

JUAN / NM

Well Number: 4 Type of Well: OIL WELL

**Allottee or Tribe Name:** EASTERN NAVAJO

Lease Number: 142006031405 Unit or CA Name: Unit or CA Number:

**CORPORATION** 

#### **Notice of Intent**

**Sundry ID:** 2832885

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 01/21/2025 Time Sundry Submitted: 07:48

Date proposed operation will begin: 02/17/2025

Procedure Description: Dugan Production plans to plug and abandon the well per the attached procedure.

#### **Surface Disturbance**

Is any additional surface disturbance proposed?: No

### **NOI Attachments**

#### **Procedure Description**

Blanco\_Wash\_4\_Rec\_Plan\_12\_18\_24\_20250121074431.pdf

Blanco\_Wash\_4\_proposed\_PA\_formation\_tops\_20250121074222.pdf

 $Blanco\_Wash\_4\_proposed\_PA\_planned\_wellbore\_schematic\_20250121074211.pdf$ 

Blanco\_Wash\_4\_proposed\_PA\_current\_wellbore\_schematic\_20250121074201.pdf

Blanco\_Wash\_4\_proposed\_PA\_planned\_work\_20250121074149.pdf

eived by OCD: 1/30/2025 3:08:47 PM Well Name: BLANCO WASH

Well Location: T24N / R9W / SEC 2 /

NENE / 36.348297 / -107.751816

County or Parish/State: SAN 2 of

JUAN / NM

Well Number: 4

Type of Well: OIL WELL

Allottee or Tribe Name: **EASTERN NAVAJO** 

**Unit or CA Number:** 

Lease Number: 142006031405 **Unit or CA Name:** 

**US Well Number: 300452293800S1** 

**Operator: DUGAN PRODUCTION** 

**CORPORATION** 

# **Conditions of Approval**

#### **Additional**

BlancoWash\_4\_P\_A\_GeoReport\_20250129101954.pdf

#### **Authorized**

General\_Requirement\_PxA\_20250129164247.pdf

2832885\_4\_3004522938\_NOIA\_KR\_01292025\_20250129164141.pdf

#### **Operator**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

**Operator Electronic Signature: TYRA FEIL** Signed on: JAN 21, 2025 07:41 AM

Name: DUGAN PRODUCTION CORPORATION

Title: Authorized Representative Street Address: PO Box 420

City: Farmington State: NM

**Phone:** (505) 325-1821

Email address: tyrafeil@duganproduction.com

#### **Field**

Representative Name: Aliph Reena

Street Address: PO Box 420

City: Farmington State: NM **Zip:** 87499-0420

Phone: (505)360-9192

Email address: Aliph.Reena@duganproduction.com

## **BLM Point of Contact**

**BLM POC Name: KENNETH G RENNICK BLM POC Title:** Petroleum Engineer

**BLM POC Phone:** 5055647742 BLM POC Email Address: krennick@blm.gov

**Disposition:** Approved Disposition Date: 01/29/2025

Signature: Kenneth Rennick

Page 2 of 2

Dugan Production plans to plug and abandon the well per the following procedure:


- PU & tally 2-3/8" workstring. Run 4½" casing scraper to 6060'. **RIH & set 4½" Cement Retainer @ 6054**'. Greenhorn perforations @ 6104'-6154'.
- **Plug I:** Sting inside below the cement retainer at 6054' and squeeze Plug I w/20 sks, 23 cu ft Class G neat cement to cover the Greenhorn, Graneros & Dakota tops below the retainer. Sting out and spot plug w/12 sks on top of the cement retainer at 6054' to 5904' to cover the Greenhorn top above the retainer. **Plug I, Inside 4½" casing, 32 sks (36.8 cu ft), Greenhorn-Graneros-Dakota, 5904'-6054'.**
- Plug II: Set CIBP at 5798'. Lower Gallup perforations are @ 5848'-5858'. Spot Plug II inside 4½" casing from 5798' above the CIBP to 5648' w/12 sks (13.8 cu ft) Class G cement to cover the Lower Gallup perforations. Plug II, Inside 4½" casing, 12 sks, 13.8 cu ft, Lower Gallup Perforations, 5648'-5798'.
- **Set CIBP at 5130'.** Gallup Upper perforations are @ 5180'-5444'. Load and circulate hole. Attempt to pressure test casing to 650 psi for 30 minutes.
- Run CBL from 5130' to surface. All plugs are designed assuming good cement behind 4½" casing for this NOI. Will make necessary changes to the plugs after reviewing the CBL.
- Plug III: Spot Plug III inside 4½" casing from 5130' above the CIBP to 4980' w/12 sks (13.8 cu ft) Class G cement to cover the Upper Gallup top & perforations. Plug III, Inside 4½" casing, 12 sks, 13.8 cu ft, Upper Gallup Top & Perforations, 4980'-5130'.
- Plug IV: Spot Plug IV inside 4½" casing from 4475' to 4169' w/24 sks (27.6 cu ft) Class G cement to cover the DV tool & Mancos top. Plug IV, Inside 4½" casing, 24 sks, 27.6 cu ft, Mancos-DV, 4169'-4475'.
- **Plug V:** Spot Plug V inside 4½" casing from 3688' to 3538' to cover the Mesaverde top w/12 sks, 13.8 cu ft Class G neat cement. **Plug V, Inside 4½" casing, 12 sks, 13.8 cu ft, Mesaverde, 3538'-3688'.**
- Plug VI: Spot Plug VI inside 4½" casing from 3030' to 2880' w/12 sks, 13.8 cu ft Class G cement to cover the Lower Chacra top. Plug VI, Inside 4½" casing, 12 sks, 13.8 cu ft, Lower Chacra, 2880'-3030'.
- Plug VII: Spot Plug VII inside 4½" casing from 2560' to 2410' w/12 sks, 13.8 cu ft Class G cement to cover the Upper Chacra top. Plug VII, Inside 4½" casing, 12 sks, 13.8 cu ft, Upper Chacra, 2410'-2560'.
- **Plug VIII:** Spot Plug VIII inside 4½" casing from 1767' to 1406' w/30 sks, 34.5 cu ft Class G cement to cover the Fruitland-Pictured Cliffs tops. **Plug VIII, Inside 4½" casing, 30 sks, 34.5** cu ft, Fruitland-Pictured Cliffs, 1406'-1767'.
- **Plug IX:** Spot Plug IX inside 4½" casing from 1180' to 786' w/32 sks (36.8 cu ft) Class G cement to cover the Kirtland-Ojo Alamo tops. **Plug IX, Inside 4½" casing, 32 sks, 36.8 cu ft, Ojo Alamo-Kirtland, 786'-1180'.**
- Plug X: Spot Plug X inside 4½" casing from 270' to surface w/24 sks, 27.6 cu ft to cover the surface casing shoe to surface. Plug X, Inside 4½" casing, 24 sks, 27.6 cu ft, surface casing shoe, 0-270'.
- Cut wellhead. Tag TOC at surface. Fill cement in case needed.
- Install dryhole marker. Clean location.

#### **Current Wellbore Schematic**

Blanco Wash #4 API: 30-045-22938 Sec 2 T24N R09W 790' FNL & 790' FEL

San Juan County, NM

Lat: 36.348315, Long: -107.752313



8-5/8" J-55 43# casing @ 220'. Cemented with 140 sks Cement.

Cemented Stage I w/ 350 sks, Class B. **DV tool @ 4425**'. Stage II w/ 450 sks 65-35-12 cement. Will run CBL to determine TOC behind casing

Upper Gallup Perforations @ 5180'-5444'

Lower Gallup Perforations @ 5848'-5858'

2-3/8", 4.7# tubing set at 6138'

Graneros Perforated @ 6104'-6154'

4 1/2" 10.5 # casing @ 6415', Hole size 7-7/8"

0


#### Planned P & A Schematic

Blanco Wash #4 API: 30-045-22938

Sec 2 T24N R09W 790' FNL & 790' FEL

San Juan County, NM

Lat: 36.348315, Long: -107.752313



8-5/8" J-55 43# casing @ 220'. Cemented with 140 sks Cement.

Plug X, Inside 4  $\frac{1}{2}$ " casing, 24 sks, 27.6 Cu.ft, Surface casing shoe, 0-270'.

Plug IX, Inside 4 ½" casing, 32 sks, 36.8 Cu.ft, Ojo Alamo-Kirtland, 786'-1180'

Plug VIII, Inside 4  $\frac{1}{2}$ " casing, 30 sks, 34.5 Cu.ft, Fruitland-Pictured Cliffs, 1406'-1767'

Plug VII, Inside 4  $\frac{1}{2}$ " casing, 12 sks, 13.8 Cu.ft, Upper Chacra, 2410'-2560'

Plug VI, Inside 4  $\frac{1}{2}$ " casing, 12 sks, 13.8 Cu.ft, Lower Chacra, 2880'-3030'

Cemented Stage I w/ 350 sks, Class B. **DV tool @ 4425**'. Stage II w/ 450 sks 65-35-12 cement. Will run CBL to determine TOC behind casing

Plug V, Inside 4 1/2" casing, 12 sks, 13.8 Cu.ft, Mesaverde, 3538'-3688'

Plug IV, Inside 4 ½" casing, 24 sks, 27.6 Cu.ft, Mancos-DV, 4169'-4475'

CIBP @ 5798'. Plug III, Inside 4  $\frac{1}{2}$ " casing, 12 sks, 13.8 Cu.ft, Upper Gallup Top & Perforations, 4980'-5130'

**Upper Gallup Perforations @ 5180'-5444'** 

CIBP @ 5798'. Plug II, Inside 4  $\frac{1}{2}$ " casing, 12 sks, 13.8 Cu.ft, Lower Gallup Perforations, 5648'-5798'

Lower Gallup Perforations @ 5848'-5858'

Cement Retainer @ 6054'. Plug I, Inside 4 ½" casing, 32 sks (36.8 Cu.ft), Greenhorn-Graneros-Dakota, 5904'-6054'.

Graneros Perforated @ 6104'-6154'

4 ½" 10.5 # casing @ 6415', Hole size 7-7/8"

Blanco Wash #4 API: 30-045-22938 Sec 2 T24N R09W 790' FNL & 790' FEL San Juan County, NM

Lat: 36.348315, Long: -107.752313

Elevation ASL: 6558' GR

#### **Formation Tops**

- Surface Casing 220'
- Ojo Alamo 886'
- Kirtland 1130'
- Fruitland 1506'
- Pictured Cliffs 1717'
- Lewis 1803'
- Chacra Upper- 2510'
- Chacra Lower 2980'
- Mesaverde 3638'
- Mancos 4269'
- DV tool 4425'
- Gallup 5166'
- Upper Gallup perforations 5180'-5444'
- Lower Gallup perforations 5848'-5858'
- Greenhorn 6100'
- Greenhorn Perforations 6104'-6154'
- Graneros 6165'
- Dakota 6249'



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT Farmington District Office 6251 College Boulevard, Suite A Farmington, New Mexico 87402 http://www.blm.gov/nm



#### **CONDITIONS OF APPROVAL**

January 29, 2025

#### Notice of Intent - Plug and Abandonment

**Operator:** Dugan Production Corporation

**Lease:** 14-20-0603-1405

Well(s): Blanco Wash 4, US Well # 30-045-22938 Location: Sec 2 T24N R9W (San Juan County, NM)

Sundry Notice ID #: 2832885

The Notice of Intent to Plug and Abandon is accepted with the following Conditions of Approval (COA):

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. The following modifications to your plugging program are to be made:
  - a. Modify Plug 5 so the TOC is 2880' and the BOC is 3030' to account for the BLM geologist's pick for the Cliffhouse formation top at 2980'.
  - b. Modify Plug 6 so the TOC is 2432' and the BOC is 2582' to account for the BLM geologist's pick for the Lower Chacra formation top at 2532'.
  - c. Modify Plug 8 so the TOC is 1260' and the BOC is 1780' to account for the BLM geologist's pick for the Pictured Cliffs formation top at 1730', and for the Fruitland formation top at 1360'.
- 3. <u>Notification:</u> Farmington Office is to be notified at least 24 hours before the plugging operations commence at (505) 564 7750.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

K. Rennick 1/29/2025

# GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
  - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
  - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
  - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
  - 4.1 The cement shall be as specified in the approved plugging plan.
  - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.3 Surface plugs may be no less than 50' in length.
  - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
  - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

2

- 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
- 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
- 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
- 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
  - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
  - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain  $H_2S$ .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), through the Automated Fluid Minerals Support System (AFMSS) with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

# **BLM - FFO - Geologic Report**

Date Completed: Jan. 28 2025

Well No. Blanco Wash #4 Surf. Loc. 790 FNL 790 FEL API 30-045-22938 T. 24 N **R.9 W** Section 2 Operator State NM **Dugan Production Corp** County San Juan

Elevation (KB) 6570 Lease # N/A

| Geologic FormationsTopsRemarksOjo Alamo887F/W SandsKirtland1059Coal, GasFruitland1360Coal, GasPic. Cliffs1730GasLewis1810Upper Chacra |                            |      |           |  |  |
|---|----------------------------|------|-----------|--|--|
| Kirtland 1059 Fruitland 1360 Coal, Gas Pic. Cliffs 1730 Gas Lewis 1810  | <b>Geologic Formations</b> | Tops | Remarks   |  |  |
| Fruitland 1360 Coal, Gas Pic. Cliffs 1730 Gas Lewis 1810  | Ojo Alamo                  | 887  | F/W Sands |  |  |
| Pic. Cliffs 1730 Gas Lewis 1810   | Kirtland                   | 1059 |           |  |  |
| Lewis 1810  | Fruitland                  | 1360 | Coal, Gas |  |  |
|   | Pic. Cliffs                | 1730 | Gas       |  |  |
| Upper Chacra 2160   | Lewis                      | 1810 |           |  |  |
|   | Upper Chacra               | 2160 |           |  |  |
| Lower Chacra 2532 Gas   | Lower Chacra               | 2532 | Gas       |  |  |
| Cliffhouse 2980   | Cliffhouse                 | 2980 |           |  |  |
| Menefee 3210  | Menefee                    | 3210 |           |  |  |
| Pt. Lookout 4149  | Pt. Lookout                | 4149 |           |  |  |
| Mancos 4345 Oil, Gas  | Mancos                     | 4345 | Oil, Gas  |  |  |
| Gallup 5166 Oil, Gas  | Gallup                     | 5166 | Oil, Gas  |  |  |
| Greenhorn 5955  | Greenhorn                  | 5955 |           |  |  |
| Graneros 6101   | Graneros                   | 6101 |           |  |  |
| Dakota 6253 Gas   | Dakota                     | 6253 | Gas       |  |  |

**Remarks:** Adjust plug V to cover BLM-picked Cliffhouse Formation. Adjust plug VI to adjust BLM-picked Lower Chacra. Adjust Plug VII to cover BLM-picked Fruitland/Pictured Cliffs.

Completed by Alek Knapowski

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 426883

#### **CONDITIONS**

| Operator:             | OGRID:                              |
|-----------------------|-------------------------------------|
| DUGAN PRODUCTION CORP | 6515                                |
| PO Box 420            | Action Number:                      |
| Farmington, NM 87499  | 426883                              |
|                       | Action Type:                        |
|                       | [C-103] NOI Plug & Abandon (C-103F) |

#### CONDITIONS

| Created By |                                   | Condition<br>Date |
|------------|-----------------------------------|-------------------|
| mkuehling  | tribal - approved for record only | 1/31/2025         |