State Of New Mexico Energy, Minerals and Natural Resources Department

27-Aug-25

MATADOR PRODUCTION COMPANY

Pre Enforcement Notification

One Lincoln Centre 5400 LBJ Freeway, Ste 1500 Dallas, TX 75240

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-025-27336] YOUNG DEEP UNIT #005 OGRID: 228937 B-10-18S-32E 660 FNL 1980 FEL

Inspection DateType InspectionInspectorInspection No.8/26/2025Routine Inspection[BZL] Barbara LydickiBZL2523821443ViolationTitleCorrective Action Due

cBZL2523923070 19.15 Oil and Gas Mechanical Integrity Failure Recorded 11/24/2025

(Auto Generated Violation - MIT Failure exits.)

cBZL2523923071 19.15.26 Injection Detection of Deficient Mechanical Integrity 11/24/2025

(Received and entered operator reported failed MIT via email Unable to pressure up. WELL MUST BE SHUT IN ASAP)

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.