Office	State of New Ivie		TOIM C-1	011
<u>District I</u> - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised August 1, 2	011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-021-20538	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		DIVISION		
District III - (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE		
<u>District IV</u> – (505) 476-3460 Santa Fe, NM 8/505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM		•		
87505	EG AND DEDODMG ON WELL	1	T T N T T T T T T T T T T T T T T T T T	
	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Nam	e
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA			West Bravo Dome Unit	
PROPOSALS.)	TION FOR FERMIT (FORM C-101) IN	JK 30CH		
	Gas Well Other X CO2		8. Well Number 0420	
2 Name of Operator			9. OGRID Number	
Hess Corporation		495		
3 Address of Operator		10. Pool name or Wildcat		
3. Address of Operator PO Box 840 Seminole TX 79360				
			West Bravo Dome CO2 Gas	
4. Well Location				
Unit Letter O:	feet from the S	line and	feet from the E li	ne
Section 4	Township 18N R			
Section 1			THIN IN	Sante.
<b>是是用这个交流被选择语</b>	11. Elevation (Show whether DR	, RKB, RT, GR, etc.		
Commence of the commence of th	5431 GR			
	•			
12. Check Ar	opropriate Box to Indicate N	ature of Notice	Report or Other Data	
12. Chook rip	ppropriate Box to maleute re	atare or rvotice,		
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR		П
				片
TEMPORARILY ABANDON	CHANGE PLANS	l .	RILLING OPNS. P AND A	Ш
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB 🔲 ·	
DOWNHOLE COMMINGLE	•			
			PERF	
OTHER:		OTHER:	FERF	X
	ted operations. (Clearly state all			date
13. Describe proposed or comple		pertinent details, an	nd give pertinent dates, including estimated	date
13. Describe proposed or comple of starting any proposed work	k). SEE RULE 19.15.7.14 NMAG	pertinent details, an		date
13. Describe proposed or comple	k). SEE RULE 19.15.7.14 NMAG	pertinent details, an	nd give pertinent dates, including estimated	⊠ date
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion.	c). SEE RULE 19.15.7.14 NMAG inpletion.	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	⊠_ date
13. Describe proposed or comple of starting any proposed work	c). SEE RULE 19.15.7.14 NMAG inpletion.	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recompletion or recompletion.	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, an C. For Multiple Co	nd give pertinent dates, including estimated ompletions: Attach wellbore diagram of	date
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate of the starting any proposed work proposed completion or recommendate of the starting any proposed work for the starting any proposed work proposed work proposed work proposed work for the starting any proposed work p	k). SEE RULE 19.15.7.14 NMAG mpletion.  ne. Held prejob JSA. Tagged.  0' tag gun. RDMO RWLS.	pertinent details, and C. For Multiple Co	nd give pertinent dates, including estimated impletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or comple of starting any proposed work proposed completion or recommendation of the proposed completion of the proposed or completion of starting any proposed work proposed with the proposed or completion of starting any proposed work proposed work proposed with the proposed work proposed work proposed with the proposed work pr	x). SEE RULE 19.15.7.14 NMAG inpletion.  ne. Held prejob JSA. Tagged	pertinent details, and C. For Multiple Co	nd give pertinent dates, including estimated impletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate of the starting any proposed work proposed completion or recommendate of the starting any proposed work for the starting any proposed work proposed work proposed work proposed work for the starting any proposed work p	k). SEE RULE 19.15.7.14 NMAG mpletion.  ne. Held prejob JSA. Tagged.  0' tag gun. RDMO RWLS.	pertinent details, and C. For Multiple Co	nd give pertinent dates, including estimated impletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Shot 2886'-2896' zone with 19 Spud Date: 05/29/2012	Rig Release D	pertinent details, and C. For Multiple Co	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or complete of starting any proposed work proposed completion or recommendate of the starting any proposed work proposed completion or recommendate of the starting any proposed work for the starting any proposed work proposed work proposed work proposed work for the starting any proposed work p	Rig Release D	pertinent details, and C. For Multiple Co	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Shot 2886'-2896' zone with 19 Spud Date: 05/29/2012	Rig Release D	pertinent details, and C. For Multiple Co	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Shot 2886'-2896' zone with 19 Spud Date: 05/29/2012	Rig Release Dove is true and complete to the b	pertinent details, and C. For Multiple Co  TD and corrected atte: 06/14, sest of my knowledge.	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Shot 2886'-2896' zone with 19 Spud Date: 05/29/2012	Rig Release Dove is true and complete to the b	pertinent details, and C. For Multiple Co	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.	date
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirelingshot 2886'-2896' zone with 15 Shot 2886'-2896' zone with 15 Spud Date:  Objective of the proposed or complete of starting any proposed work proposed complete or recomplete of the proposed work proposed complete or recomplete of the proposed complete or recomplete or reco	Rig Release Depoyee is true and complete to the beauty and complete to the	pertinent details, and C. For Multiple Co  TD and corrected the correcte	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.  /2012  ge and belief.  DATE 07/06/2012	-
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirelingshot 2886'-2896' zone with 15 Shot 2886'-2896' zone with 15 Spud Date:  Objective of the proposed or complete of starting any proposed work proposed complete or recomplete of the proposed work proposed complete or recomplete of the proposed complete or recomplete or reco	Rig Release Depoyee is true and complete to the beauty and complete to the	pertinent details, and C. For Multiple Co  TD and corrected the correcte	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.  /2012  ge and belief.  DATE 07/06/2012	-
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Shot 2886'-2896' zone with 19 Spud Date:  Object 1	Rig Release Depoyee is true and complete to the beauty and complete to the	pertinent details, and C. For Multiple Co  TD and corrected atte: 06/14, sest of my knowledge.	nd give pertinent dates, including estimated ampletions: Attach wellbore diagram of d to 3035'.  /2012  ge and belief.  DATE 07/06/2012	-
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirelingshot 2886'-2896' zone with 15 Shot 2886'-2896' zone with 15 Spud Date:  Objective of the proposed or complete of starting any proposed work proposed complete or recomplete of the proposed work proposed work proposed completion or recomplete of the proposed work proposed completion or recomplete of the proposed complete of the proposed comp	Rig Release Depove is true and complete to the beauty and address.	pertinent details, and C. For Multiple Co  TD and corrected the correcte	nd give pertinent dates, including estimated completions: Attach wellbore diagram of d to 3035'.    2012     DATE   07/06/2012	-
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of starting any proposed work prop	Rig Release Depove is true and complete to the beauty and address.	pertinent details, and C. For Multiple Co  TD and corrected the correcte	nd give pertinent dates, including estimated completions: Attach wellbore diagram of d to 3035'.    2012     DATE   07/06/2012	-
13. Describe proposed or complete of starting any proposed work proposed completion or recomplete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Shot 2886'-2896' zone with 19 Spud Date:  Object of the complete of starting any proposed work proposed completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Spud Date:  Spud Date:  Object of the completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Spud Date:  Spud Date:  Object of the completion or recomplete of 14/12 MIRU Renegade Wirels Shot 2886'-2896' zone with 19 Spud Date:  Type or print name Rita C Smith	Rig Release Depove is true and complete to the beauty and address.	pertinent details, and C. For Multiple Co  TD and corrected the correcte	nd give pertinent dates, including estimated completions: Attach wellbore diagram of d to 3035'.    2012     DATE   07/06/2012	-