Submit 3 Copies To Appropriate District Office	·= · · · · ·		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural	Resources WELL API NO	May 27, 2004 O. 30-007-20652
District II 1301 W. Grand Ave., Artesia, NM 8821	OIL CONSERVATION D	IVISION 5 Indiana To	ma of Langa
District III	1220 South St. Francis	5. Indicate Ty	
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u>	Santa Fe, NM 8750	5 6. State Oil &	Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		0V - 2 2005	
SUNDRY NO	TICES AND REPORTS ON WELLS		e or Unit Agreement Name
	POSALS TO DRILL OR TO DEEPEN OF PLAIGE PLICATION FOR PERMIT" (FORM C-101) FOR S	OCH SERVATION	VPR A
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other Coalbed Meth	DIVISION 8. Well Numb	
2. Name of Operator	į,	9. OGRID Ni	ımber 180514
3. Address of Operator	PASO ENERGY RATON, L.L.C.	10. Pool name	e or Wildcat
_	BOX 190, RATON, NM 87740		ld Canyon – Vermejo Gas
4. Well Location			
	1230 feet from the South line a		<u>East</u> line
Section 2 Tov	wnship 31N Range 20E 11. Elevation (Show whether DR, RI	NMPM Colfax Cou	nty
	8,027' (GL)	XB, KI, GK, etc.)	
Pit or Below-grade Tank Application		Parameter	
Pit typeDepth to GroundwaterDistance from nearest fresh water wellDistance from nearest surface water			
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12.	Check Appropriate Box to Indicate Natur	•	
	INITENITION TO		
	INTENTION TO:	SUBSEQUENT F	-
PERFORM REMEDIAL WORK	🗍 PLUG AND ABANDON 🔲 📗 R	EMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON	☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C	_	ALTERING CASING
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING	☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C ☐ MULTIPLE COMPL ☐ C	EMEDIAL WORK [OMMENCE DRILLING OPNS. [ASING/CEMENT JOB [ALTERING CASING P AND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [PULL OR ALTER CASING OTHER: 13. Describe proposed or co	☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C ☐ MULTIPLE COMPL ☐ C ☐ O mpleted operations. (Clearly state all pert	EMEDIAL WORK [OMMENCE DRILLING OPNS. [ASING/CEMENT JOB [THER: cinent details, and give pertinent	ALTERING CASING P AND A Completion dates, including estimated date
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed	☐ PLUG AND ABANDON ☐ R ☐ CHANGE PLANS ☐ C ☐ MULTIPLE COMPL ☐ C	EMEDIAL WORK [OMMENCE DRILLING OPNS. [ASING/CEMENT JOB [THER: cinent details, and give pertinent	ALTERING CASING P AND A Completion dates, including estimated date
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion.	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di	ALTERING CASING P AND A Completion dates, including estimated date
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1st s	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated cemetage - 2136'-2139' 12 Holes	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore dient top at surface.	ALTERING CASING P AND A Completion dates, including estimated date agram of proposed completion
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1 st stage - P Schlumberger perf'd 2 nd s	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated cemetage - 2136'-2139' 12 Holes umped 135,022 scf 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 H	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore dient top at surface. In with Linear gel with 24,116 lb Holes	ALTERING CASING DATE PAND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1st s HES frac'd 1st stage - P Schlumberger perf'd 2nd s HES frac'd 2nd stage - Pu	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated cemetage - 2136'-2139' 12 Holes umped 135,022 sef 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 H mped 171,021 sef 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 H	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore dient top at surface. In with Linear gel with 24,116 lb Holes m with Linear gel with 30,136 lbs	ALTERING CASING DATE PAND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1 st s HES frac'd 1 st stage - P Schlumberger perf'd 2 nd s HES frac'd 2 nd stage - Pu Schlumberger perf'd 3 rd st HES frac'd 3 rd stage - Puschlumberger perf'd 3 rd st	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated cemetage - 2136'-2139' 12 Holes umped 135,022 scf 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 F mped 171,021 scf 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 scf 70% quality nitrogen foam	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes m with Linear gel with 30,136 lbs - 2076' 28 Holes m with Linear gel with 29,847 lbs 1	ALTERING CASING P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1 st s HES frac'd 1 st stage - P Schlumberger perf'd 2 nd s HES frac'd 2 nd stage - Pu Schlumberger perf'd 3 rd st HES frac'd 3 rd stage - Puschlumberger perf'd 3 rd st	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated cemetage - 2136'-2139' 12 Holes umped 135,022 scf 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 H mped 171,021 scf 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'-	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes m with Linear gel with 30,136 lbs - 2076' 28 Holes m with Linear gel with 29,847 lbs 1	ALTERING CASING P AND A D D D D D D D D D D D D D D D D D
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1 st s HES frac'd 1 st stage - Pu Schlumberger perf'd 2 nd s HES frac'd 2 nd stage - Pu Schlumberger perf'd 3 rd st HES frac'd 3 rd stage - Put 08/10/05 RIH tubing, rods and put	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated ceme tage - 2136'-2139' 12 Holes umped 135,022 scf 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 H mped 171,021 scf 70% quality nitrogen foar age - 2032'-2034', 2065'-2066', 2072'- mped 152,654 scf 70% quality nitrogen foam mp. The well is ready to be tested and putton above is true and complete to the best of	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes In with Linear gel with 30,136 lbs 2076' 28 Holes In with Linear gel with 29,847 lbs 1 att on production.	ALTERING CASING P AND A Completion
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1 st s HES frac'd 1 st stage - Pu Schlumberger perf'd 2 nd s HES frac'd 2 nd stage - Pu Schlumberger perf'd 3 rd st HES frac'd 3 rd stage - Put 08/10/05 RIH tubing, rods and put	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated ceme tage - 2136'-2139' 12 Holes umped 135,022 sef 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 I mped 171,021 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2066', 2072'- mped 152,654 sef 70% quality nitrogen foatage - 2032'-2066', 2072'- mped 152	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes In with Linear gel with 30,136 lbs 2076' 28 Holes In with Linear gel with 29,847 lbs 1 att on production.	ALTERING CASING P AND A
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or coof starting any proposed or recompletion. 7/17/05 Schlumberger ran Acoologous Schlumberger perf'd 1st stage - Puschlumberger perf'd 2nd stage - Puschlumberger perf'd 3rd stag	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated ceme tage - 2136'-2139' 12 Holes umped 135,022 sef 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 Hamped 171,021 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'-2006', 207	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes In with Linear gel with 30,136 lbs 2076' 28 Holes In with Linear gel with 29,847 lbs 1 It on production. Of my knowledge and belief. I for general permit or an (attached) al	ALTERING CASING P AND A P AND A Completion M dates, including estimated date agram of proposed completion s 16/30 sand. 16/30 sand. 6/30 sand. urther certify that any pit or belowternative OCD-approved plan . DATE 10/31/05
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1st stage - Pt Schlumberger perf'd 2nd stage - Pt Schlumberger perf'd 3rd stage - Pt US/10/05 RIH tubing, rods and pt I hereby certify that the information of the proposed of the proposed or co of starting any proposed or co of starting	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated ceme tage - 2136'-2139' 12 Holes umped 135,022 sef 70% quality nitrogen foa tage - 2109'-2112', 2117'-2119' 20 Hamped 171,021 sef 70% quality nitrogen foar age - 2032'-2034', 2065'-2066', 2072'-2015,000 mped 152,654 sef 70% quality nitrogen foam	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes In with Linear gel with 30,136 lbs 2076' 28 Holes In with Linear gel with 29,847 lbs 1 It on production. Of my knowledge and belief. I for general permit or an (attached) al	ALTERING CASING P AND A P AND A Completion M dates, including estimated date agram of proposed completion s 16/30 sand. 16/30 sand. 6/30 sand. irther certify that any pit or belowternative OCD-approved plan .
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or coof starting any proposed or recompletion. 7/17/05 Schlumberger ran Acoologous Schlumberger perf'd 1st stage - Puschlumberger perf'd 2nd stage - Puschlumberger perf'd 3rd stag	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated ceme tage - 2136'-2139' 12 Holes umped 135,022 sef 70% quality nitrogen foatage - 2109'-2112', 2117'-2119' 20 Hamped 171,021 sef 70% quality nitrogen foatage - 2032'-2034', 2065'-2066', 2072'-2006', 207	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes In with Linear gel with 30,136 lbs 2076' 28 Holes In with Linear gel with 29,847 lbs 1 It on production. Of my knowledge and belief. I for general permit or an (attached) al	ALTERING CASING P AND A P AND A Completion M dates, including estimated date agram of proposed completion s 16/30 sand. 16/30 sand. 6/30 sand. urther certify that any pit or belowternative OCD-approved plan . DATE 10/31/05
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1st stage - Pt Schlumberger perf'd 2nd stage - Pt Schlumberger perf'd 3nd stage - Pt Schlum	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated ceme tage - 2136'-2139' 12 Holes umped 135,022 scf 70% quality nitrogen foat tage - 2109'-2112', 2117'-2119' 20 H mage - 2032'-2034', 2065'-2066', 2072'-2006', 207	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. In with Linear gel with 24,116 lb Holes In with Linear gel with 30,136 lbs 2076' 28 Holes In with Linear gel with 29,847 lbs 1 Int on production. Of my knowledge and belief. I for general permit or an (attached) al Regulatory Analyst tchell@elpaso.com Telepho	ALTERING CASING P AND A D Completion dates, including estimated date agram of proposed completion s 16/30 sand. 16/30 sand. 16/30 sand. 16/30 sand. DATE 10/31/05 ne No. (505) 445-6785
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON PULL OR ALTER CASING OTHER: 13. Describe proposed or co of starting any proposed or recompletion. 7/17/05 Schlumberger ran Aco 08/04/05 Schlumberger perf'd 1 st stage - P Schlumberger perf'd 2 and stage - Pu Schlumberger perf'd 3 rd	PLUG AND ABANDON R CHANGE PLANS C MULTIPLE COMPL C mpleted operations. (Clearly state all pert work). SEE RULE 1103. For Multiple C ustic Cement Bond Log. Estimated ceme tage - 2136'-2139' 12 Holes umped 135,022 scf 70% quality nitrogen foat tage - 2109'-2112', 2117'-2119' 20 H mage - 2032'-2034', 2065'-2066', 2072'-2006', 207	EMEDIAL WORK OMMENCE DRILLING OPNS. ASING/CEMENT JOB THER: cinent details, and give pertinent Completions: Attach wellbore di ent top at surface. Im with Linear gel with 24,116 lb Holes In with Linear gel with 30,136 lbs 2076' 28 Holes In with Linear gel with 29,847 lbs 1 It on production. Of my knowledge and belief. I for general permit or an (attached) al	ALTERING CASING P AND A Completion Mates, including estimated date agram of proposed completion s 16/30 sand. 16/30 sand. 16/30 sand. 16/30 sand. DATE 10/31/05 10/31/05 10 No. (505) 445-6785