Submit 3 Copies To Appropriate District	State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natural Resources		[Revised March 25, 1999
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-037-20051	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		STATE	FEE 🗗
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil &	Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name of	or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			ANN KATHERYN	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			AND X-11	C (C)
1. Type of Well:			·	
Oil Well Gas Well Other				
2. Name of Operator			8. Well No.	
3. Address of Operator			9. Pool name or Wildcat)	
3. Address of Operator POBOX 1065 TUCUMCARINM			9. 1001 hans of	ev nacat
4. Well Location				
1105 1 115th 11 10th 1 1 10th 1				
Unit Letter 1: 660 feet from the WEST line and 198 feet from the SOUTH line				
Section 19	Township // I	lange 27E	NMPM QUA	YCounty
Section 19 Township ON Range 27 E NMPM QUAY County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4365' GR				
	Appropriate Box to Indicate I			
			SEQUENT RE	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WOR	K 🛚	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:	COMPLETION	OTHER: SET	aren i Dee	orete G-
12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.				
\$ 01-09-03 - SET CIBPE 6734' & PERF @ 6710'TO 6714' (10 SHUTS) - SET PERE 6606' & ACIDIZE				
W/750GAL 7.5% HCL & 20 BAH SEALERS - AUG TREATING PSI 5904. WELL ON VACUME - MADE 20 SWABRUNS WELL MAKING GAS CUT FILLD W/STrong Flair During Runs (12Bbl. H10/HE)				
3 01-14-03 - SET CIBPE 6690' i PERF From 6602 +06658 22 Shots - TIH WITBG SET PKR @6506"				
\$ ACIDIZE W/1600 GALS 7.5% HCL } SUBALLS, AUG TREATING PST 1437#@ 58PM 151P 350 -UAC				
AFTER 2 Min. OUER NITE SI 900# WELL WOUD'N'T Flow (UERY STRONG FLAIR DUVING) AFTER ROMS)				
6 01-21-03 - POH W/PKR - PERFORATE FROM 6344 to 6370 - 32 Shots - TIH W/PKR SETE 6583				
MADE 7 SWAB RUMS & WELL KICKED OFF - FLOWED & HIS & DIED - ACIDIZE W/3000 GALS HCL (7.5%)				
AUG PSI 1400#@ 6.5 BPM SWAB WELL Dry W/S/19ht GAS SHOW!				
	·	•		
hereby certify that the information :	above is true and complete to the b	est of my knowledge	and belief.	
SIGNATURE /	TITLE_	AGEUT		DATE <u>04-02-03</u>
Type or print name MIKE	OWEH		Telenh	one No.
This space for State use	n //		101001	
	16/	ICTDICT CUP)だわながたかかっ	1.1.
APPPROVED BY	TITLE	IJIKICI JUI	EKA120K	DATE 4/4/03
Conditions of approval, if any:	•			•