

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-021-20121
5. Indicate Type of Lease STATE X <input type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-5857
7. Lease Name or Unit Agreement Name WDBGU
8. Well Number 201F
9. OGRID Number 495
10. Pool name or Wildcat West Bravo Dome CO2 Gas

**SUNDARY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> CO2 Gas Well <input type="checkbox"/>
2. Name of Operator Hess Corporation
3. Address of Operator P.O. Box 840, Seminole, Texas 79360
4. Well Location Unit Letter <u>F</u> : <u>1980</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>20</u> Township <u>18N</u> Range <u>30E</u> NMPM County <u>Harding</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4439'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: Change master valve & pump out plug ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/27

MIRU Key Pressure Truck and Flowback Tank, JSA, TPC 0 psi, CPC 0 psi. Change out Master Tbg Valve to AB body. Drop 4 Soap Sticks, Pump 0.25 bbls 6% KCL down Tubing to Load and Pump out Plug at 1350 psi. Open Well to Tank. No Flow. RDMO Key Pressure Truck. Leave well Open to Test Tank for Three Hours, Well Flowing with Strong Blow. Rec 9 BLW. SI Well. RD Flowback tank.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rita C. Smith TITLE Engineering Technician DATE 11/21/2008

Type or print name Rita C. Smith E-mail address: rsmith@hess.com PHONE: (432) 758-6726

**For State Use Only**

APPROVED BY: Ed Martin TITLE **DISTRICT SUPERVISOR** DATE 2/9/09  
Conditions of Approval (if any):